APPARELBASE SHOE CAD 사용설명서

(주)유스하이텍

Homepage : http://www.apparelbase.com E-mail : support@apparelbase.com Tel : 070-4000-9700

* 제품의 성능을 위해 사전 고지 없이 제품 내용이 변경될 수 있습니다.

APPARELBASE

유스하이텍



Mind**CAD** 2D Design & Engineering for Luggage User Manual





MindCAD 2D Design & Engineering

© 2016 Mind - Software Multimedia e Industrial, SA

All rights reserved. No parts of this work may be reproduced in any form or by any means - graphic, electronic, or mechanical, including photocopying, recording, taping, or information storage and retrieval systems - without the written permission of the publisher.

Products that are referred to in this document may be either trademarks and/or registered trademarks of the respective owners. The publisher and the author make no claim to these trademarks.

While every precaution has been taken in the preparation of this document, the publisher and the author assume no responsibility for errors or omissions, or for damages resulting from the use of information contained in this document or from the use of programs and source code that may accompany it. In no event shall the publisher and the author be liable for any loss of profit or any other commercial damage caused or alleged to have been caused directly or indirectly by this document.

Printed: 29-04-2016 in Lisbon, Portugal

Publisher

Mind - Software Multimedia e Industrial SA

Managing Editor Bruno Mendes

Technical Editors Telma Caiadas, José Pereira

Cover Designer Olga Bernardino

Team Coordinator Bruno Mendes

Production Bruno Mendes

Special thanks to:

All the people who contributed to this document, customers and partners that provided valuable feedback on this ever ongoing product.

Table of Contents

Part I	Getting Started	12
1	Before you begin	
2	How do I start MindCAD Bags Design & Engineering?	
	How do I use the menus?	
	MindCAD Bags Design & Engineering Layout	
5	How do I manipulate the view contents?	
	Scaling Moving (Panning)	
6		
Ũ	Tool tips	
	Status Bar Help	
	Standard online Help	
Part II	File Overview	20
1	File - New	
	File - Open	
	Re-open	
3	File - Close	
	File - Save	
	File - Save As	
	File - Export	
Ū	File - Export - Image	
	File - Export - DGT	
	File - Export - DXF	
	File - Export - HPGL	
	File - Export - IGES	27
	File - Export - Image	27
	File - Export - PDF	27
	File - Export - Printer	
7	File - Import	
	File - Import - MindCAD Bag Design & Engineering document	28
	File - Import - CNC	30
	File - Import - DGT	30
	File - Import - DXF	30
	File - Import - HPGL	
	File - Import - IBA/VET	
	File - Import - Image	
	File - Import - ISO	
	File - Import - MDB	32

	File - Import - PDF	32
	File - Import - Manage Importers	33
8	File - Cut	
	File - Cut - Cut	35
	File - Cut - Manage Cutters	
	File - Cut - Properties	
	File - Cut - Using Property Rules	
	File - Cut - Model(1)	
	File - Cut - Model(2)	
	File - Cut - Cutting Area	
	File - Cut - Zund \ Other Cutters	
	File - Cut - Destination	
9	File - Digitize	59
	File - Digitize - Scanner	59
	File - Digitize - Scanner - Shell	
	File - Digitize - Scanner - Parts	
	File - Digitize - Scanner - Select Source	
	File - Digitize - Image	
	File - Digitize - Image - Shell	
	File - Digitize - Image - Parts	
	File - Digitize - Options	
10	File - Project Properties	
10		
	Project Properties - Summary	
	Project Properties - Material Options	
	Project Properties - Variants	
	Project Properties - Costing results	
	Project Properties - Parts	
11	File - Preferences	
	File - Preferences - Locations	86
	File - Preferences - Options	87
	File - Preferences - Digitizer	89
	File - Preferences - Language	90
	File - Preferences - Default Labels	91
	Adding a new text string	
	File - Preferences - Parts 1	92
	File - Preferences - Parts - Groups	
	File - Preferences - Parts - Names	
	File - Preferences - Parts 2	94
	File - Preferences - Rotation	
	File - Preferences - Reference points	
	File - Preferences - Post-processing part filtering	
	File - Preferences - Default stencils margin	
	File - Preferences - Name template	
	File - Preferences - Part assessment	
	File - Preferences - Printer	
	File - Preferences - Default Properties/Layers	
	File - Preferences - Customize	

	Contents	5
	Editing Theme	100
	Popup menus	
12	File - Printing	109
	File - Page Setup	109
	File - Print	
	File - Print Parts	
	File - Print Preview File - Printer Setup	
13	File - Exit	
Part III	Edit Overview	114
1	Edit - Undo	114
	Edit - Redo	
	Edit - Cut	
	Edit - Copy	
	Edit - Paste	
	Edit - Fixed Paste	
	Edit - Delete	
	Edit - Select All	
	Edit - Reverse Selection	
	Edit - Group	
	Edit - Ungroup	
	Edit - Freezings	
	Edit - Constrain Edit	
	Edit - Constrain Edit - Nearest Line	
	Edit - Constrain Edit - Nearest Intersection	
	Edit - Constrain Edit - Nearest End	
	Edit - Constrain Edit - Nearest Point	
	Edit - Constrain Edit - Grid Edit - Constrain Edit - Orthogonal Restriction	
14	Edit - Drag Constrain	
	Edit - Pre-copy	
	Edit - Digitize	
	Edit - Alignment Points	
	Edit - Properties	
Part IV	View Overview	126
1	View - Zoom to Fit	126
	View - Zoom to Fit to selected elements	
	View - Zoom 1:1	
3	View - Toolbars	129
	View - Toolbars - Main	129

	View - Toolbars - Constrain	129
	View - Toolbars - Layers	129
	View - Toolbars - Tools	130
	View - Toolbars - Parts	130
	View - Toolbars - Browser	130
	View - Toolbars - Parts/Library Bar	131
	View - Toolbars - Customize	
	View - Toolbars - Customize - Commands	133
	View - Toolbars - Customize - Toolbars	134
	View - Toolbars - Customize - Keyboard	
	View - Toolbars - Customize - Menu	138
	View - Toolbars - Customize - Options	140
4	View - Layers	
	View - Layers - Lines	141
	View - Layers - Parts	
	View - Layers - Punches	
	View - Layers - Markers	
	View - Layers - Notches	
	View - Layers - Images	
	View - Layers - Alignment Points	
5	View - Filters	
	View - Grid	
	View - Grid - Lines	143
	View - Grid - Points	
	View - Grid - None	
	View - Grid - Spacing	
7	View - Full Screen	
	Tools Overview	146
I	Tools - Selection	
2	Tools - Selection - Point selection	
Z	Tools - Drawing	
	Tools - Drawing - Line	
	Creating a curved line	
	Creating a curved line with corner	
	Creating a closed curve	
	Line editing	
	Line editing - Move point	
	Line editing - Select points	
	Line editing - Add/Delete point	
	Line editing - Changing a Corner/Curve point Line editing - Dragging/Scaling/Rotating lines/Mirror	
	Line editing - Virtual Mirror	
	Line editing - Arrow Movement Step	150
	Tools - Drawing - Bezier	
	Bezier Line Editing	
	······································	
	Tools - Drawing - Circle	

Drawing - Circle - Free	
Drawing - Circle - By radius	
Circle Properties	
Tools - Drawing - Rectangle	
Rectangle Properties	
Tools - Drawing - Arc	
Tools - Drawing - Text	
Tools - Drawing - Text (True Type)	
Text (True Type) Edition	
Tools - Drawing - Sawtooth	
Tools - Drawing - Sawtooth - Edit	
Tools - Drawing - Sawtooth over Line	
Tools - Drawing - Axis	178
Tools - Drawing - Marks	179
Tools - Drawing - Punches	180
Tools - Drawing - Symmetric Shapes	
Tools - Drawing - Symmetric Shape - Ellipse	
Tools - Drawing - Symmetric Shape - Circle	
Tools - Drawing - Symmetric Shape - Polygon	
Tools - Drawing - Grid	183
Tools - Drawing - Continue line	186
Tools - Change	
Tools - Change - Rotate	187
Tools - Change - Scale	
Tools - Change - Move	
Tools - Change - Cut Line	
Tools - Change - Break Line By Angle	
Tools - Change - Trim	194
Tools - Change - Trim (Hide)	196
Tools - Change - Hide Part of a Line	197
Tools - Change - Reverse	199
Tools - Change - Extend/Shorten Line	199
Tools - Change - Explode	201
Tools - Change - Smooth	202
Tools - Change - Filter	203
Tools - Change - Join Lines	203
Tools - Change - Join Lines by Distance	204
Tools - Change - Swap Lines	205
Tools - Change - Bounding Box	206
Tools - Change - Center point	207
Tools - Change - Wrap Lines	207
Tools - Change - Average lines	211
Tools - Change - Spring Adjustment	
Spring Adjustment - Complete process	
Tools - Change - Convert	
Tools - Change - Convert - to Sawtooth	
Tools - Change - Convert - to Axis	
Tools - Change - Convert - to Curve	


	Tools - Change - Convert - to Bezier	
	Tools - Change - Convert - From Axis to Line	
4	Tools - Measurements	225
	Free measurements	
	Measurement along lines	
	Using markers when measuring Measure fixed length	
5	Tools - Copy Properties	
6	Repeat last operation	
Part VI	Operations Overview	232
1	Operations - Links On/Off	232
2	Operations - Offset	
	Creating an offset to a line	234
	Changing the values of the offset	
2	Offset - Grading	
	Multiple Offset	
4	Operations - Perpendicular	
	Operations - Perpendicular - Line	
	Operations - Perpendicular - Axis Operations - Perpendicular - Circle	
5	Operations - Mirror	
	Operations - Mirror - Activate Axis	
	Operations - Mirror - About axis	
6	Operations - Markers	
7	Operations - Punches	
	Punch Generator	
	Add/Delete Punch Shapes from the library	
	Punches dependent on other punches	
	Multiple Punch Lines Punches over sawtooth	
	Editing Punches Distribution	
8	Operations - Notches	
9	Operations - Corner	
10	Operations - Distance Dependence	
11	Operations - Stitch line	
12	Operations - Bisection	
13	Operations - Anchor	
14	Operations - Release	
15	Operations - Release All	
Part VII	Parts Overview	286
1	Parts - Create Part	

Contents

	9
	J

	Parts - Create Part - By Contour	287
	Creating a part with no treatments or folds	
	Creating an unfolded mirrored part (1 axis)	
	Creating an unfolded mirrored part (2 axis)	
	Creating an unfolded non-mirrored part	
	Creating parts with treatments	
	Creating parts with two axes (enabling one at a time)	
	Creating parts with two axes (enabling the two axes at once)	
	Tips and tricks	
	Parts - Create Part - By One Click	
	Editing Parts	
	Editing Parts - Corners	
	Editing Parts - Treatments	
	Editing Parts - Radius	
	Editing Parts - Notches	
	Editing Parts - Text	
	Editing Parts - Configuring Treatments	
	Editing Parts - Stretch	
	Treatments - Line Offset	
	Treatments - Corners-Side	
	Treatments - Sawtooth offset	
	Editing Parts - Names, Cut Groups, Cost Groups and Colours	
	Editing Parts - Points	
	Editing Parts - Breaking the part boundary.	
	Editing Parts - Edit lines	
	Editing Parts - Copy and paste	
	Editing Parts - Return to Shell	
	Editing Parts - Simulate Cut	
	Editing Parts - Costing	
	Editing Parts - Properties	
	Parts Properties - Properties	
	Parts Properties - Assessment	
	Method - Convex Hull	
	Method - Parallelogram	
	Method - Inverse Parallelogram	
	Method - Bounding box	
	Method - Linear	
	Method - Circle	
	Method - Grid	
	Method - Synthetic	
2	Editing Parts - Parts Bar	
2	Parts - Create Hole	
	Parts - Create Hole - By Contour	
_	Parts - Create Hole - By One Click	
3	Parts - Create Quality Area	370
4	Parts - Add Lines	371
	Parts - Add Lines - Add Lines	
	Parts - Add Lines - Add Lines to One Side	373

	Parts - Add Lines - Add Lines only to Reflection	
5	Parts - Add Lines - Add Lines on both Sides	
5	Parts - Add Cut	
	Parts - Add Cut - Add Cut Parts - Add Cut - Add Cut to One Side	
	Parts - Add Cut - Add Cut only to Reflection	
	Parts - Add Cut - Add Cut on both Sides	
6	Parts - Add Stencil	
	Parts - Add Stencil - Add Stencil	385
	Parts - Add Stencil - To One Side	
	Parts - Add Stencil - Only to Reflection	
7	Parts - Add Stencil - On both Sides Parts - Add Modifier	
1		
	Parts - Add Modifier - To one side Parts - Add Modifier - Only to reflection	
	Parts - Add Modifier - On both Sides	
8	Parts - Remove - Lines	
9	Parts - Insert Lines on Border	
10	Parts - Replace Lines	401
	Parts - Replace Lines - Replace Lines	402
	Parts - Replace Lines - Replace Lines on Reflection	403
	Parts - Replace Lines - Replace Lines/Reflection	
	Parts - Delete Part	
	Parts - Delete All Parts	
13	Parts - Auto Add Lines on Creation	406
14	Parts - Costing	
	Parts - Costing - Options	409
Part VIII	Window Overview	412
1	Window - Cascade	
	Window - Side by Side	
	Window - List	
		416
Partix	Help Overview	410
1	Help - Help Topics	416
2	Help - Mind on the Web	
3	Help - About MindCAD 2D Modelling for Luggage	
	Index	419



1 Getting Started


1.1 Before you begin

IMPORTANTE NOTE: A valid product authorization file must be installed before MindCAD can be used.

If you'd like some sample data to use in MindCAD Bag Design&Engineering:

- 1. From the File menu, select Open to load example projects.
- 2. Select a file and press "Open" (or double click the file).
- All instructions in this manual are correct at the time of printing. Some sections may not be up to date due to subsequent updates to MindCAD Bag Design&Engineering.

1.2 How do I start MindCAD Bags Design & Engineering?



Double click the MindCAD Bags Design & Engineering's icon MindCAD Bags Design & Engineering will start shortly after.

1.3 How do luse the menus?


💩 Mi	ndCAD B	lag Desig	jn & Eng	ineering 2011.	V2 - [Mi	ndBags1]		đ		×
🗟 File	e Edit	View	Tools	Operations	Parts	Window	Help	-	8	×

Almost everything in **MindCAD Bag Design & Engineering** can be accessed through the main menu. This is shown in the picture above and is displayed at the top of the **MindCAD Bag Design & Engineering** screen.

1. Select an item from the main menu. A drop down list is displayed, showing a list of sub-items, each corresponding to specific program action. Greyed out sub-items mean that a specific program action is not available (e.g. a paste action will not be available is no copy action was previously executed).

	Zoom to fit	Ctrl+D
æ,	Zoom 1:1	Ctrl+Shift+D
	Toolbars	×
	Layers	۲
	Filters	•
	Grid	•
	Full Screen	F3

2. If you move your mouse to an item that has an arrow alongside, as highlighted above, an additional list of sub-items will appear.




3. If the item is followed by just ... (for example, **Save as...** below), selecting the item will display a dialog box so that you can enter data and make selections.

14	MindCAD 2D Design & Engineering				
				1	
		New	Ctrl+N		
	õ	Open	Ctrl+0		
		Close			
	H	Save	Ctrl+S		
		Save As			
		Export	+		
		Import	•		
		Cut	•		
		Digitize	•		
ľ		Project prop	erties		
		Preferences			
		Printing	•		
		Recent File			
		Exit			
L					

1.4 MindCAD Bags Design & Engineering Layout

The image below show the MindCAD Bags Design & Engineering interface.



- 1. Menu Bar Most of MindCAD Bags Design & Engineering's functionality may be accessed through this menu.
- 2. **Main Bar** This toolbar allows a user to open a new project or an existing one, save a project, print, cut, copy, paste, undo, redo, zoom to fit, go to help topics and open Mind's web site.
- Constrain Bar This toolbar have the options to let you 'snap' editing or drawing operations to specific points.
- 4. Layers Bar This toolbar have the options to let you turn on/off the layers of the project.
- 5. **Tools Bar** This toolbar allows a user to select the draw lines tool, on/off the links, create offsets, mirror selected lines, cut lines and copy objects properties.
- 6. **Parts Bar** This toolbar have the options to let you create parts, holes, add lines and remove lines.
- 7. **Draw area** Is in this area that the 2D part creation, grading and specification are made and seen.
- 8. **Tool Options** This window shows the options available for the tool that are selected in the moment, i.e., if you select the option draw lines the tool option will show the type off lines available but if you select for example the tool create parts the tool option will show the treatments that are available among other things.
- 9. **Object Browser Bar** This toolbar shows the elements' hierarchy, through this toolbar it's possible to freeze/unfreeze and show/hid elements, layers among other things.
- 10. Change Page In MindCAD Bags Design & Engineering it's possible to have more that one

MindCAD 2D Design & Engineering

page, its possible to Create, Duplicate, Import and Delete.

11.**Parts/Library Bar** - This toolbar have two tabs, the Parts where you can see the created parts, access their proprieties among other things and the Punches tab where you can see the existing punches, you can remove or add punches from the toolbar.

1.5 How do I manipulate the view contents?

There are two main interaction classes for direct manipulation of the 2D environment:

- Scaling
- Moving (Panning)

1.5.1 Scaling

16

To scale the view, in both 3D and 2D windows,

- 1. Press the **Ctrl** key and hold down the middle mouse button. View contents will scale up/down as the mouse is moved up/down.
- 2. Releasing the middle mouse button will end the scaling process.

If you have a wheel mouse, you can also use the wheel to change the scale.

1.5.2 Moving (Panning)

To move the view contents, in 2D windows,

- 1. Hold down the middle mouse button. As the cursor is moved, view contents will move with it.
- 2. Releasing the middle button will end the process.

1.6 Getting Help with MindCAD Bags Design & Engineering

Help in MindCAD Bags Design & Engineering is available in the following ways:

- Tool Tips
- Status Bar Help
- Standard online Help

1.6.1 Tool tips

Placing the cursor over a button will display a brief description of the function of the button.

1.6.2 Status Bar Help

Placing the cursor over a button will display information about the button in the status bar.

1.6.3 Standard online Help

- 1. Select Help from the MindCAD Bags Design & Engineering toolbar.
- 2. Select **Contents and Index** and then the item you require. There is a separate section in the help for each option on the main toolbar.



2 File Overview

20

This menu lets you create new files, open existing files, close and save files. It also lets you import and export data, set your preferences, print and cut files.

Use this option to open a recently used project. The names of the last five files are displayed at the bottom of the menu for quick selection.

	New	Ctrl+N
2	Open	Ctrl+0
	Close	
	Save	Ctrl+S
	Save As	
	Export	+
	Import	+
	Cut	•
	Digitize	•
	Project prope	erties
	Preferences	
	Printing	•
	Recent File	
	Exit	

2.1 File - New

Use this option to create a new file.

This is the same as clicking the **Create new file** button in the **Main** toolbar or pressing **Ctrl+N**



2.2 File - Open

Use this option to open any of your files.

This is the same as clicking the Open File	button in the Main toolbar or pressing Ctrl+O
🗋 🧀 🖪 🖨 🕺	🔊 🖎 🚫 🚱

Use this option to open any of your projects from a central database.

Insert the server, user and password and press Ok.

Connect to Server	
	Levella est
Server:	localhost 🔹
User name:	admin 🔹
Password:	••••
Remember the passw	vord
	Connect Cancel

The follow window will appear.

ocalhost	-						
	Ø	~ / *	1. 1	🤉 📄 📰	XML 	Columns	
ilters:							
Search	Q	Name	Created by	Created on	Changed by	Changed on	11
All Control of the second s		TestPerformance-DUP-51	admin	18/01/2010 17:11:41	admin	18/01/2010 17:11:41	
Changed in the last day		Yamamoto-kaban 0325-4	admin	21/04/2011 15:56:45	admin	21/04/2011 16:02:05	
hanged in the last 8 days		Yamamoto-kaban 0325-4	admin	21/04/2011 15:56:45	admin	21/04/2011 18:54:59	
Changed in the last 30 days Changed more than 30 days ago		teste.s3d	admin	05/01/2012 12:28:57	admin	16/01/2012 17:07:18	
hanged by me			admin	06/01/2012 12:28:57	admin	03/04/2012 15:48:15	
lot changed by me		camp camp-mod	admin	06/01/2012 16:31:30	admin	06/01/2012 17:22:55	
reated by me lot created by me		Eicheiro 1	admin		admin		
lot created by me				13/01/2012 13:12:08		13/01/2012 13:12:08	
		layer_counter_test.S3D	admin	18/01/2012 12:11:44	admin	26/01/2012 14:07:43	
		teste shoe laces	admin	18/01/2012 12:22:16	admin	30/01/2012 11:15:39	
		classic.L3D	admin	18/01/2012 15:13:13	admin	27/01/2012 13:20:08	1
		classic.s3d	admin	18/01/2012 15:46:03	admin	18/01/2012 15:46:03	
		kids.s3d	admin	18/01/2012 16:06:56	admin	18/01/2012 16:06:56	
aved by 🔻 Changed on 👻	-	Luisteste	admin	18/01/2012 16:20:57	admin	18/01/2012 16:22:04	1
▷ / [169]		gold.s3d	admin	18/01/2012 16:26:02	admin	18/01/2012 16:26:02	
		edit_last_test	admin	19/01/2012 09:39:14	admin	19/01/2012 09:41:59	-
		oulha	admin	19/01/2012 09:50:25	admin	19/01/2012 09:50:25	
		camp.L3D	admin	27/01/2012 12:21:24	admin	27/01/2012 12:21:24	
		classic_test	admin	27/01/2012 15:39:34	admin	27/01/2012 15:39:34	
		camp to gold	admin	07/02/2012 17:18:59	admin	08/02/2012 10:11:35	1
		classic	admin	10/02/2012 15:34:35	admin	24/02/2012 15:50:20	
		3D-change	admin	17/02/2012 17:30:13	admin	06/03/2012 09:45:11	
		lifters-negative	admin	20/02/2012 03:13:13	admin	20/02/2012 18:32:58	
		teste camp	admin	20/02/2012 03:28:11	admin	20/02/2012 03:29:34	
		camp-all	admin	23/02/2012 12:15:10	admin	05/03/2012 16:35:56	
		<					
		· [P

To open a file from pdm, select the desired one and select **Open**.

ocalhost	-					
	A - 7 - 2		n 🖪 = 🛛 -		Columns	_
ilters:	🐺 🧀 🖊		7 📄 📰	×MI 	Columns	•
Search	Q					
	Name	Created by	Created on	Changed by	Changed on	
All Changed in the last day	TestPerformance-		18/01/2010 17:11:41	admin	18/01/2010 17:11:41	
Changed in the last 8 days	Yamamoto-kaban	_0325-4 admin	21/04/2011 15:56:45	admin	21/04/2011 16:02:05	
Changed in the last 30 days	Yamamoto-kaban	0325-4 admin	21/04/2011 15:56:45	admin	21/04/2011 18:54:59	
Changed more than 30 days ago	teste.s3d	admin	05/01/2012 12:28:57	admin	16/01/2012 17:07:18	
Changed by me Not changed by me	camp	admin	06/01/2012 16:11:07	admin	03/04/2012 15:48:15	
Created by me	camp-mod	admin	06/01/2012 16:31:30	admin	06/01/2012 17:22:55	
Not created by me	Ficheiro 1	admin	13/01/2012 13:12:08	admin	13/01/2012 13:12:08	
	layer_counter_tes	st.S3D admin	18/01/2012 12:11:44	admin	26/01/2012 14:07:43	
	teste shoe laces	admin	18/01/2012 12:22:16	admin	30/01/2012 11:15:39	
	classic.L3D	admin	18/01/2012 15:13:13	admin	27/01/2012 13:20:08	
	classic.s3d	admin	18/01/2012 15:46:03	admin	18/01/2012 15:46:03	
	kids.s3d	admin	18/01/2012 16:06:56	admin	18/01/2012 16:06:56	
Saved by 👻 Changed on 👻	▼ Luisteste	admin	18/01/2012 16:20:57	admin	18/01/2012 16:22:04	=
▷ 🦢 / [169]	gold.s3d	admin	18/01/2012 16:26:02	admin	18/01/2012 16:26:02	
/[109]	edit_last_test	admin	19/01/2012 09:39:14	admin	19/01/2012 09:41:59	
	oulha	admin	19/01/2012 09:50:25	admin	19/01/2012 09:50:25	
	camp.L3D	admin	27/01/2012 12:21:24	admin	27/01/2012 12:21:24	
	classic_test	admin	27/01/2012 15:39:34	admin	27/01/2012 15:39:34	
	camp_to_gold	admin	07/02/2012 17:18:59	admin	08/02/2012 10:11:35	
	classic	admin	10/02/2012 15:34:35	admin	24/02/2012 15:50:20	
	3D-change	admin	17/02/2012 17:30:13	admin	06/03/2012 09:45:11	
	lifters-negative	admin	20/02/2012 03:13:13	admin	20/02/2012 18:32:58	
	teste_camp	admin	20/02/2012 03:28:11	admin	20/02/2012 03:29:34	
	camp-all	admin	23/02/2012 12:15:10	admin	05/03/2012 16:35:56	-
				1		

To open a stand alone file, select the **Open from** file button and select the file to open.

ocalhost	-					_	
ilters:	\$	<i>ĕ</i> 🖉 📑		? 📄 📰 🗄	2</th <th>Columns</th> <th>-</th>	Columns	-
Search	٩	Name	Created by	Created on	Changed by	Changed on	*
All		TestPerformance-DUP-51	admin	18/01/2010 17:11:41	admin	18/01/2010 17:11:41	
Changed in the last day Changed in the last 8 days	Open					4/2011 16:02:05	
Changed in the last 30 days	Open					4/2011 18:54:59	
Changed more than 30 days ago	Look in:	🚹 Shells		🚽 🎯 🏚 📂 🖪	•	1/2012 17:07:18	
Changed by me Not changed by me		[]				4/2012 15:48:15	
Created by me	<u> (3)</u>	Name				1/2012 17:22:55	
Not created by me		bottom.scd				1/2012 13:12:08	
	History	Court.scd				1/2012 14:07:43	
	<u> </u>	> courtni.scd		<u>⊢_</u> ∠∕	- 11	1/2012 11:15:39	
		kidstwotone.scd			~~~~	1/2012 13:20:08	
		> mega.scd			Main	1/2012 15:46:03	
		MindCAD2D1_test.b2	d	ack	- {//	1/2012 16:06:56	
Saved by 🔻 Changed on 🔻		MindCAD2D2.b2d			Le la compañía de la	1/2012 16:22:04	≡
Þ 🍅 / [169]		moc.scd				1/2012 16:26:02	
	~ ~~	> sprung.scd				1/2012 09:41:59	
	(*)	> trainer.scd				1/2012 09:50:25 1/2012 12:21:24	
	Favorites				Preview	1/2012 12:21:24	
		< III		4		2/2012 10:11:35	
	()	File name: court.scd			🗃 Open	2/2012 10:11:35	
	Web Pages	Files of type: MindCAD 2D	Design & Engine	ering Files (*.b2d; 🔻	Cancel	3/2012 09:45:11	
1		riles of type. [WindCAD 2D	Design a Engine	anng riles (1.020; 🔻	Cancel	2/2012 18:32:58	
_		teste camp	admin	20/02/2012 03:28:11	admin	20/02/2012 03:29:34	
		camp-all	admin	23/02/2012 12:15:10		05/03/2012 16:35:56	-
		<				•	

Note: If the project is opened by other user, it will open in ready only mode.

2.2.1 Re-open

æ

This is one of the options that can be added to the customised toolbar.

Re-open File - Use this option to re-open the current shell. The shell will be opened as it was when last saved.

2.3 File - Close

Use this option to close the current file.

This is the same as clicking the ${\bf X}$ button in the corner of any window.

Close

2.4 File - Save

Use this option to save the current file with the current name.

This is the same as clicking the Save 📕 button in the Main toolbar or pressing Ctrl+S



Use this option to save the current project with the current name to a central database.

2.5 File - Save As

This option allows you to save the current project in a different store and with a different name.

Save project	
Store:	localhost 👻
Name:	Mind-Project
Comments:	
Options:	Publish
	Save Cancel

Enable the **publish** option to export the created parts to the PDM.

2.6 File - Export

Use these options to export the current file to other software packages.

Image BGD DGT DXF IGES PDF Printer

2.6.1 File - Export - Image

This option allows to export the current project as an image. It's possible to configure the image resolution and quality.

The image can be output in the following formats:

- PNG
- JPG
- BMP

After selecting the image name and location, the Export image window will appear:

Export image ×			
Resolution Low (250x250) Average (500x500) High (1000x1000) Very high (2000x2000)	Quality Low Average High		
Checker background Lines width: 3 OK Cancel			

Select the image resolution and quality.

Check if a checker background is required.

And insert the lines width for the lines that are being exported to the image.

2.6.2 File - Export - DGT

Use this option to export the current project in **DGT** format.

© 2016 Mind - Software Multimedia e Industrial, SA

2.6.3 File - Export - DXF

Use this option to export the current project in DXF format.

2.6.4 File - Export - HPGL

Use this option to export the current project in HPGL format.

2.6.5 File - Export - IGES

Use this option to export the current project in IGES format.

2.6.6 File - Export - Image

This option allows to export the current project as an simplified image. The image can be output in the following formats:

Bitmap Files(*.bmp) JPEG Files(*.jpg;*.jpeg;*.jpe) Ico Files(*.ico) Tif Files(*.tif) Gif Files(*.gif) Png Files(*.png) Pcx Files(*.pcx) Tga Files(*.tga)

2.6.7 File - Export - PDF

Use this option to export the current project in PDF format.

2.6.8 File - Export - Printer

Use this option to export the current project to Printer.

2.7 File - Import

Use these options to import data from other software packages.

MindCAD Bag Design & Engineering document
BGD
CNC
DGT
DXF
HPGL
Image
ISO
MDB
PDF
Manage Importers

After selecting the file to import, the imported geometry will appear attached to the cursor allowing the operator to choose the appropriate position. When done, just do a left click and the content will be pasted.

2.7.1 File - Import - MindCAD Bag Design & Engineering document

This option lets you import data in **MindCAD Bags Design & Engineering document** format with multiple pages.

- 1. Select MindCAD Bags Design & Engineering document form the Import options on File menu.
- 2. Select the file to be imported and press **Open**.

Look in:	🕌 Shells		-	G 🦻 📂	 •	
<u></u>	Name	*		(<u>_</u>)	r	_
	BagX.b2	?d				1
History	MindBa	gs1.b2d		I WE	741	
<u> </u>	MindCA	AD-Bags.b2d			_ //セ	
	> Novo-6	41-07334-02.b2d			E fésie	in I
My documents					(~~	¬ nn
				<u> </u>	,	n
					U	0 1
Desktop						
				L		
Favorites	 III 		Þ		Preview	«
	File name:	MindCAD-Bags.b2d			a 0	pen
Web Pages	Files of type:	MindCAD Bag Design	& Engineering F	iles (*.b2c 🔻	Cano	;el

3. Select the components you which to import.

Import docum	ent 🗾
Page:	MindCAD 👻
🔲 Import all lin	
Import part	s
M0 M1 M2 M3	
	OK Cancel

4. If the imported document has multiple pages and .

30	MindCAD 2D Design & Engineering

Import document
Page: MindCAD MindCAD Import all line MindCAD-1 Import parts
M0 M1 M2 M3
OK Cancel

2.7.2 File - Import - CNC

Use this option to import data in *CNC* format.

2.7.3 File - Import - DGT

Use this option to import data in **DGT** format.

2.7.4 File - Import - DXF

Use this option to import data in **DXF** format.

2.7.5 File - Import - HPGL

Use this option to import data in *HPGL* format.


2.7.6 File - Import - IBA/VET

Use this option to import data in *IBA/VET* format.


2.7.7 File - Import - Image

Use this option to import images. The image can be input in the following formats:

All Graphics Files (*.bmp;*.jpg;*.jpeg;*.jpe;*.ico;*.tif;*.gif;*.png;*.pcx;*.tga) Bitmap Files(*.bmp) JPEG Files(*.jpg;*.jpeg;*.jpe) Ico Files(*.ico) Tif Files(*.tif) Gif Files(*.gif) Png Files(*.gng) Pcx Files(*.png) Pcx Files(*.pcx) Tga Files(*.tga) All Files (*.*)



- 1. Select Image from the Import options of the File menu.
- 2. Select the image to import and click Open.



3. Insert the DPI value.

32 MindCAD 2D Design & Engineering

Import	_	×
DPI:		96
	OK	Cancel
L		

4. The imported image will appear attached to the cursor allowing the operator to choose the appropriate position. When done, just do a left click and the content will be pasted.

This image could then be used as a tracing image for manual digitizing of lines and parts.

2.7.8 File - Import - ISO

Use this option to import data in *ISO* format.

2.7.9 File - Import - MDB

Use this option to import data in **MDB** format.

2.7.10 File - Import - PDF

Use this option to import data in **PDF** format.

2.7.11 File - Import - Manage Importers

1. Select Manage Importers from the Import options of the File menu.

MindCAD 2D Modelling document
BGD
CNC
DGT
DXF
HPGL
IBA/VET
Image
ISO
MDB
PDF
Manage Importers

2. We could now either select the button New or Import.

	Exporters	×
Name	Machine	New 👻 Import
		Clone Export
		Properties Rename Delete
		OK Cancel

3. Select **New**, and then the required import type from the menu.

34 MindCAD 2D Design & Engineering

Importers
DXF
DXF (Teseo)
Generic
LectralBA
MDB
NibbleComelz
INESCOP SIPECO

4. That option will now be available in the import menu.

MindCAD 2D Modelling document
BGD
CNC
DGT
DXF
HPGL
IBA/VET
Image
ISO
MDB
PDF
New Generic importer
Manage Importers

2.8 File - Cut

This option allows to export parts for cut and to manage the cutters.



2.8.1 File - Cut - Cut


This is the same as pressing F8.

		Parts selection		×
Models	Parts			Sizes
✓court				✓ 3 ✓ 3 1/2
	Name	Model	Group	✓ 4 ✓ 4 1/2
	☑ \$> мо	court		▼5 ▼5 1/2
	☑ 🎝 м1	court		▼6 ▼6 ▼6 1/2
	🗹 义 м2	court		₹7
	🗹 📣 мз	court		▼7 1/2 ▼8
Groups	✓ ✓ M4	court		
				OK Cancel
4. 1. 1	🛋 📲 📲 .		ll alla familia	
1. Use these buttons	to	change the visua	alization format.	
		=		==
a. Choose between	ı Icons View 💻, Til	es View 🗵 📃	or Details View 🧯	8

2. Select/deselect the required **parts** and **sizes** by clicking in the check boxes. To **select/deselect all option**, do a right click over it, to access the options from the contextual menu.

Models Court	Parts			Sizes
	Name	Model	Group	<u>4</u> ■ 4 1/2
		court		▼ 1 1/2 □ 5 ▼ 5 1/2
	№ ≫ M1	court		▼6 ▼6 ▼6 1/2
	🗹 义 м2	court		7


3. Do a right click to access the contextual menu:



• Override Selection - Allows to change the selected sizes for the selected part.

The Override Size Selected Part window will open, select/deselect the desired sizes and press Ok confirm.

Note: When the override selection is used in a part, the part info will change for red.



- Clear Override Delete the override changes.
- Copy Override Copy the override changes.
- Paste Override Paste the override changes, previous copied.
- Select All Select all parts.
- Deselect All Deselect all parts.
- 4. Press **Ok** when finished, now its possible to select the exporter.

Select exporters ×	
New Comelz exporter New Mutoh exporter New Zund exporter New DXF exporter	
OK Cancel	

5. It's possible to select several exporters at once. Do a left click over the required exporters.

Select exporters	×
New Comelz exporter	
New Mutoh exporter	
New Zund exporter New DXF exporter	
New DXP exporter	
OK Cancel	

MindCAD 2D Design & Engineering

6. Press OK and will be asked to save each one of the exported file formats separately.

2.8.2 File - Cut - Manage Cutters

38

Use this option to create a cutter manager for your cutting table

1. From the Cut option of the File menu, select Manage Cutters

Cut	F8
Manage Cutters	

A dialogue box is displayed. At this stage the list of options is empty.

2. You to buttons available **New** or **Import**. As we are showing the full process, we select New. In other scenarios, the user can import the predefined settings of an exporter previously saved to a mcf file. This option is useful to share exporter definitions within or between organizations.

	Exporters	×
Name	Machine	New 🗸 Import
		Clone Export
		Properties
		Rename Delete
		OK Cancel

3. Select the required cutter from the menu.

File Overview	39
l	

	Comelz
	OnePunchComelz
	LeatherComelz
	MicroDynamics
	Graphtec
	Mutoh
	CutterJet
	Elitron
	Teseo
	TA10
	OvicLince
	T5420Super
	ElitronK1
	Zund
	Atom
	TecmacalJet
	MDB
	IbertecXMakerSPF
	DimensionsPRO
	MDB_OldFormat
	GCode
	TeseoSnap
	LectraCAD
	HPGL
	PDF
	DXF
	Printer
	Ruizhou_RZ-2410
	Emma
The e	whether you have abagan is

The exporter you have chosen is displayed in the dialogue box.

	Exporters	×
Name	Machine	New 👻 Import
New Zund exporter	Zund	Clone Export
		Properties Rename Delete OK Cancel

4. Click OK

40

• The next time the Cut menu is selected the exporter you selected will be displayed as an option on the menu.



2.8.2.1 File - Cut - Properties

Use this option to adjust the setup cutters.

Select the exporter and press the button Properties.

	Exporters	×
Name	Machine	New 👻 Import
New Zund exporter	Zund	Clone Export
		Properties
		OK Cancel

A short reference about the available options:

- Clone Creates a copy of the selected exporter.
- Export... Save the parameters of this exporter to a file in mcd format.

41

- **Delete** Delete the selected exporter.
- Rename Rename the selected exporter.
- Properties Inspect and change parameters of the selected exporter.

Select Properties and a configuration dialog appears:

New Zund exporter	×
Model (1) Model (2) Cut	ting Setup Zund Destination
Configuration template	
Default	• + -
Stencils	
Use model width	
Width (mm):	0
No side indicator	
Use model side indication	
Custom side indicator	(mm) 1
Rounded	Complete stencil
Draw Twice	Apply tool compensation
Tool: D	efault 🔹 🔛
Text	
Activate	
	efault 👻 >>
On all sizes	
Only on smaller size	
Only on larger size	
Punches	
Convert to circle	
Radius: 0	Passes: 1
Convert to point	T 46665.
	efault 🔻 >>
ОК	Cancel Apply Help

Several properties under the tabs could be adjusted to control the cutting.

MindCAD 2D Design & Engineering

• Model(1)

42

- Model(2)
- Cutting Area
- ZUND
- Destination

Please refer to the corresponding sections for details on those tabs.

2.8.2.1.1 File - Cut - Using Property Rules

On some parameters tabs, a **Property Rules** button allows the creation of rules that override the default configuration.

For example, if you have stencils using the Knife tool by default but you want, for some of the lines,

to use the **Pen** tool, you need to create a rule. Activate **Property Rules** button; a dialog appears.

Property	Width	Tool	Rounded	Complete	Twice	Compensation	Side indicator
+ -						ОК	Cancel

Press + to add or - to remove rules. Press +. A dialog appears.

Property:	pen	
Vse model thic	kness	
Markers thickn	iess (mm):	0
No side indicat	tor	
O Use model side	e indicator	
Custom side in	dicator (mm)	1
Rounded		
Complete sten	cil	
Draw Twice		
Apply tool com	pensation	
Tool:	Pen	•
	ОК	Cancel

Now we create a rule with targeting a property named pen.

This property should previously exist and be used on some lines of the model to be visible. Properties are managed using File - Preferences - Default Properties menu option and the user should apply the properties to the lines.

All the options should be selected as needed to change the behaviour.

Property	Width	Tool	Rounded	Complete	Twice	Compensation	Side indicator
pen	Auto	Pen	Yes	No	No	Yes	None
•						OK	Cance

In this sample setup, sending stencils with the property pen will use the pen tool instead of the default knife.

2.8.2.1.2 File - Cut - Model(1)

Use this Model(1) tab to adjust the first subset of Model parameters

New Zund exporter	x
Model (1) Model (2) Cutting Setup Zund Destination	
Configuration template	
Default -	
Stencils	
☑ Use model width	
Width (mm):	
No side indicator	
Output Use model side indicator	
Custom side indicator (mm)	
Rounded Complete stencil	
Draw Twice Apply tool compensation	
Tool: Default >>	
Text	
Activate	
Tool: Default	
 On all sizes Only on smaller size 	
 Only on larger size 	
Punches	
Ose model geometry	
Convert to circle	
Radius: 0 Passes: 1	
Convert to point	
Tool: Default >>	
OK Cancel Apply Help	

Stencils

- Apply model width - Enable or disable usage of model width for stencils. If unchecked, the width

1.2

45

of the stencil is defined on the stencil Width (mm) field Width (mm):

- Rounded - Enable or disable rounded stencils.

- **Complete Stencil** - Enable or disable complete stencils. If checked all the sections of a stencil will be connected resulting in a single one.

- **Draw twice** - Enable or disable draw twice. If checked, a double pass with the tool will be done. Typically used for hard to draw materials.

- Apply tool compensation - Enable or disable tool compensation.

- Tool - Select default tool.

Default	~
None	
Default	
Knife1	
Knife1 Half Cut	
Knife 1 Perfect Cut	
Knife2	
Knife2 Half Cut	
Knife2 Perfect Cut	
Pen	
Drill 1	
Drill2	
Drill3	
Mill	

Text

- Activate Enable or disable text.
- Tool Select default tool.
- On all sizes Enable text on all sizes.
- Only one smaller size Enable text only one smaller size.
- Only one larger size Enable text only one larger size.

Punches

- Use model geometry Enable model geometry.
- Convert to circle Enable convert to circle
 - Radius define circle radius
 - Passes define passes number
- Convert to point Enable convert to point
- Tool Select default tool.

In case the exporter is for a Laser machine, an option to control if the Stencils are printed or not is also available.

Stencils

 Image: Activate

2.8.2.1.3 File - Cut - Model(2)

Use this Model(2) tab to adjust the second subset of Model parameters

Model (1) Model (2)	Cutting Setup	Zund	Destinat	ion
Configuration tem	olate			
Default	Jan	¥ .	+ Ed	it -
Lines				
Tool:	Default		~	>>
Break angle:	0			
Borders				
Tool:	Default		~	>>
Ignore size cod Notches:	e geometry			
Cut with the	border			
O Don't cut				
O Use specified	tool None			\sim
Allow inside ext	ensions			
Holes				
Tool:	Default		~	>>
Allow inside ext	ensions			
Line Filtering				
Activate	Amount:	0		
Corner Filtering				
Activate	Cu	irvature:		2
Max Angle:	180 Sn	nooth Fac	tor:	0.5
Other				
Cardboard				

Lines (inside parts)

- Tool - Select default tool.

Borders (perimeter of parts)

- Tool - Select default tool.

- Ignore size code geometry - Enable or disable size code geometry.

Notches

48

- Cut with the border Enable cut with border.
- Don't cut If checked notches will not be cut.
- Use specified tool Enable specified tool

Holes (inside parts)

- Tool - select default tool.

Line filtering

- Activate - enable or disable line filtering. Control the number of points on the filtered lines using the Amount field.

Corner filtering

- Activate - enable or disable corner filtering. Control the curvature using the **Curvature** field, the angle using the **Max Angle** field and the smoothness using the **Smooth factor**.

Other

- Cardboard - Enable or disable cardboard cutting mode. Group grading is applied to parts.

2.8.2.1.4 File - Cut - Cutting Area

Use this is the option to adjust the **cutting area**.

Model (1) Model (2	2) Cutting Se	tup	Zund	Destination		
Machine Configu	ration					
Dimensions Width(x):	2400 mm		Cutting ar Vidth(x):	rea 240	0	mm
Length(y):	1000 mm	c)ffset(x):		0	mm
Nesting Area		P	ickup Are	ea		
Width(x):	2400 mm	V	Vidth(x):		0	mm
Offset(x):	0 mm	C	ffset(x)	:	0	mm
y x						
Cutting offset X Cutting offset Y			mm mm			

Machine Configuration:

- Dimensions

Width (X) - Machine working area width (in mm);

Length (Y) - Machine work area length (in mm);

- Cutting Area

Width (X)- Width of the cutting area (in mm);

Offset (Y) - Offset of the cutting area, relative to the defined origin (in mm);

- Nesting Area

Width (X)- Width of the nesting area (in mm);

Offset (Y) - Offset of the nesting area, relative to the defined origin (in mm);

- Pickup Area

50

Width (X)- Width of the pickup area (in mm);

Offset (Y) - Offset of the pickup area, relative to the defined origin (in mm);

- Cutting offset X Apply an horizontal (X) offset to the cutting plane (in mm);
- Cutting offset Y Apply an vertical (Y) offset to the cutting plane (in mm);

2.8.2.1.5 File - Cut - Zund \ Other Cutters

Use this is the option to adjust the setup for the specific machine. This tab is different for each machine type, in this case we are displaying it for a **Zund** machine. Proper setup of the parameters on this tab is only needed if the machine is connected to the local computer.

Zund

For a Zund machine, the available parameters are:

Model (1) Model (2)		tup Z	und Dest	tination	
Default	piarce	~	+	Edit	-
General Wait before Start	Cutting 2	y s			
Plotter Curve Qua On End Cut:	lity: No d	hange			~
None N	Up: 20.0	00 mm	Down:	0.00	mm
Generate delay		default	value	50	ms
Turn Off Cells Turn On Vacu Turn Off Vacu Turn Off Vacu	um Before Sta ium After End	Cutting	3	0	ms s
Enable G3 va	cuum support		s adl:		
Conveyor Has Conveyor	Settings		Milling Mill Radius	1	mm
Tool Assignment			Machine Pa	ark	
Pen1 Knife	1 🗸	>>	Top Left		~
Pen2 Pen	×	>>	🖌 Auto Pa	rk	
Pen3 Drill1	×	>>	Part Sortin	g Order	
Pen4 Drill2	×	>>	Standard		~
Pen5 Pricke	er V	>>	Halfpar	ts first	
Sequencial Sequencial Cut Group Dynamic tool sv Config	-	Too dril dril dril dril	1 2 3	^	Up Dn
OK	Cance		Apply		Help

General

- Wait before start cutting - Select the value in seconds.

- **Plotter curve Quality** - Select the plotter quality, take in consideration that a lower velocity gives a better quality.

- On End Cut Select the tool and if available the up position and down position in mm.
- General delay instruction Enable/disable the delay before cut instruction.
- General tool waiting times default value Enable/disable the waiting times before and after the

MindCAD 2D Design & Engineering

tool moves.

52

Vaccum

- Vacuum Off to move cells - Turn off the pump to mode the cells configuration.

- Use Vacuum Curtain - Active this option for machines with vacuum curtain.

- **Turn off Cells along cut** - Check this option to close vacuum cells outside cutting area to improve material hold.

- Turn On Vacuum Before Start Cutting - Turn on the pump before start cutting.

- Turn Off Vacuum After End Cutting - Turn off the vacuum after end cutting. Define the time in milliseconds.

- **Turn Off Vacuum when idling more than** - Turn off the vacuum when the machine is park more than, define the value in seconds.

- **Enable G3 vacuum support** - Enable this option when using the vacuum system specific of a G3 machine.

Conveyor

- Has Conveyor - Check this box if the machine has a conveyor and you intend to use it.

Milling

- Mill Radius - Define the radius of the mill (in mm).

Tool Assignment - Select the tool for each slot.

Machine Park - Select from Top Left, Top Right, Bottom Left or Bottom Right.

- Auto Park - Enable or disable the machine Auto Park.

Part Sorting Order - This parameter allows the operator to choose the sequence the parts will be cut on the table.

- **Half parts first** - Checking this option allows that parts divided by a conveyor advance – parts that don't fit on the cutting window – to be cut first.

Sequencial

- **Sequencial Cut** - Check this option to active the sequential cut order mode. Select the number of parts to be cut in each group and the tool order.

- Group - The parts will be cutted in groups of X parts.

- Dynamic tool switching - Checking this option, makes the machine stop to allow a tool change.

Tool Order - Tooling order defines the order of operation of each tool during the cutting job. Click on the **Up** and **Dn** buttons to change the order. To enable this option check Sequencial Cut option.

Comelz

On a Comelz machine, the available parameters are:

Model (1)	Model (2)	Comelz	Destination			
Configu Defaul	ration temp t	late	~	+	Edit	-
Punc! Micro	h Punch		1 0.35			

Punch - Radius of the punch tool.

Micro Punch - Radius of the micro punch tool.

Cutter Jet

For a cutter jet machine, the available parameters are:

Model (1)	Model (2)	CutterJet	Destination	۱
Config	uration temp	late		
Defau	lt		~	+ Edit -
Assign	Qualities to	Materials		
Leath	er Red	1	×	New
Mate	rial			Quality
Leath	ner Red			1
Linnin	ng			6
Use f	oats			

Assign Qualities to Materials - Allow to setup different qualities for template materials.

Use floats - Disable - The exported coordinates can only be integers.

- Enable - Allow the use of non-integer values.

PDF

For the PDF exporter, the available parameters are:

Model (1) Model (2) PDF	Destination	
Virtual sheet dimensions		
Length (mm)	277	
Width (mm)	380	
Real sheet dimensions		
Length (mm)	287	
Width (mm)	200	
✓ Draw alignment circles		
Radius:	2	
Thickness:	0.1	
✓ Draw alignment lines		
Thickness:	0.25	
Page overlap (mm)	5	
Default line thickness (mm):	0.2	

Virtual sheet dimensions:

- Length (mm) - Enter the virtual sheet length in mm.

- Width (mm) - Enter the virtual sheet width in mm.

Real sheet dimensions:

- Length (mm) Enter the real sheet length in mm.
- Width (mm) Enter the real sheet width in mm.

Draw alignment circles: Enable or disable draw alignment circles.

- Radius - Enter the circles radius.

- Thickness - Enter the circles thickness.

Draw alignment lines: Enable or disable draw alignment lines.

- Thickness - Enter the alignment lines thickness.

Page Overlap (mm) - Enter the page overlap in mm.

Default Line Thickness (mm) - Enter the default line thickness in mm.

Printer

For the Printer exporter, the available parameters are:

Model (1) Model (2)	Printer		
Virtual sheet dimens	sions		
Length (mm)		277	
Width (mm)		380	
✓ Draw alignment o	irdes		
Radius:		2	
Thickness:		0.1	
Draw alignment li	ines		
Thickness:		0.25	
Page overlap (mm)		5	
Default line thicknes	s (mm):	0.5	

Virtual sheet dimensions:

- Length (mm) Enter the virtual sheet length in mm.
- Width (mm) Enter the virtual sheet width in mm.

Draw alignment circles: Enable or disable draw alignment circles.

- Radius Enter the circles radius.
- Thickness Enter the circles thickness.

Draw alignment lines: Enable or disable draw alignment lines.

- Thickness - Enter the alignment lines thickness.

Page Overlap (mm) - Enter the page overlap in mm.

Default Line Thickness (mm) - Enter the default line thickness in mm.

HPGL

For the HPGL exporter, the available parameters are:

56 MindCAD 2D Design & Engineering

Tool Assignr	nent Speed	Machine Pa	
Pen1	500	O Top Ri	
Pen2	500	OBottor	
Pen3	500	OBotton	-
Pen4	500	🖌 Auto F	Park
Pen5	500	Units:	100
Pen6	500	Pen down co	mmand:
Pen7	500	PR;PD0.0;	
Pen8	500	Pen up com	nand:
		PU;	
re-cut custor	n HPGL:		

Tool assignment:

- Speed - Enter the tools speed (pen1, pen2,...).

Machine Park: Select from Top Left, Top Right, Bottom Left or Bottom Right.

- Auto Park - Enable or disable the machine Auto Park.

Units - Enter the units.

Pen down command - Insert the HPGL command or sequence of HPGL commands used to lower the tool.

Pen up command - Insert the HPGL command or sequence of HPGL commands used to raise the tool

Pre-cut custom HPGL - HPGL instructions to be sent to the machine before parts.

Post-cut custom HPGL- HPGL instructions to be sent to the machine after parts.

Graphtec

For the graphtec exporter, the available parameters are:

Model (1) Model (2) C	Cutting Area	Graphtec	Destination	
Configuration template	e		Edit	
Default		× +	Edit	-
Cut/Draw separ		đ		
Park Machine				
🖌 Auto Park				
Top Left				
O Top Right				
O Bottom Lef				
O Bottom Rig	ht			

Cut/Draw separately - Enable or disable cut/draw separately .

Send HPGL escape command - Enable or disable send HPGL escape command.

Machine Park: Select from Top Left, Top Right, Bottom Left or Bottom Right.

- Auto Park - Enable or disable the machine Auto Park.

2.8.2.1.6 File - Cut - Destination

Use this is the option to adjust the destination of the generated data for cutting/plotting.

Model (1)	Model (2)	Cutting	Setup	Zund	Destination	
To File	-	61	(d):			
	ays use the	same nie	e/airecta	bry		D
						U
O To Co	mm Port					
CO	MM 1	~		Baud	9600 V	1
Pa	rity None	\sim	5	Stop Bits	1	£
Data	Bits 8	~	Flow	Control	Hardware 🔻	¢
	T Port					
	LPT 1					
To Pri	nter Port (a	s raw)				
						~
	mote Servi	e				
Server						
Config	uration:					
configu						
	P/IP port					
Address	s: 0.0.0	0.0		Port:	50000	

To File:

- Always use the same file/directory - Enable or disable always use the same file/ directory.

To Comm Port:

- COMM Enter the comm.
- Parity Enter the parity.
- Data Bits Enter the data bits.
- Baud Enter the baud.
- Stop Bits Enter the stop bits.
- Flow Control Enter the flow control.

To LPT Port: Enter the LPT port.

To Printer Port: Enter the printer port.

To Remote Service:

- Server - URL of the server with the remote service

- Configuration - Insert the configuration name that was defined in CuttingServices.

To TCP/IP port - Insert the Address and Port.

2.9 File - Digitize

Use these options to import from:

- Scanner
- Image

Scanner	•
Image	•
Options	

2.9.1 File - Digitize - Scanner

This menu allows to choose if you digitizing a Shell or Parts and to select the source.

Shell
Parts
Select Source

2.9.1.1 File - Digitize - Scanner - Shell

This is the option to scan a shell into the software.

1. Select **Options** from **Digitize** option of the **File** menu to adjust the properties, before you start digitizing the shell; however, it's recommended to use the **default values**.

MindCAD 2D Design & Engineering

60

	Scanner Options	×
Filter Before	0	0.30
Filter After	0	0.30
Stuff Dist	Π	= 1.00
Break Angle	Π	30.00
✓ Import image	Scale X: 0 in 100 Y: 0 in 100 OK	Cancel

2. Open Select Source from Digitize option of the File menu to select the right scanner.

Select Source	×
Sources: HP Officejet Pro X476dw TWAIN 1.0 (32-3; TW-Brother MFC-8890DW LAN 3.9 (32-32) WIA-Brother MFC-8890DW LAN 1.0 (32-32) WIA-HP Officejet Pro X476dw MFP (1.0 (3) WIA-HPF7C997 (HP Officejet Pro X4 1.0 (3)	Select Cancel

3. Select **Shell** from the **Digitize** option of the **File** menu. Your scanner software will be launched.

	File Overview 61
Scan :	
Photo	PreScan
web 🔿 🖉	
© Text	Width: 210,0 mm 2480 pixels
	Height: 291,0 mm
Resolution	3437 pixels
300 x 300 dpi 👻	Data Size: 24,3 MB
Scan Type	Image:
24bit Colour 🔻	🔘 inch
Reduce Noise	
Brightness	
· · · · · · · 0	Start
Contrast -	Start
· · · · · · · O	
Document Size	Help
A4 210 x 297 mm (8.3 x 11. ▼	
Duplex(two-sided) Scanning	Default
Congreated scanning Congreated scanning	Cancel
Short-edge binding	

4. Adjust the scan properties and select **PreScan**.

Photo	h	++		PreScan
🛛 🖉 🛇 Web				Width: 210,0 mm
Text				2480 pixels
Resolution				Height: 291,0 mm
300 x 300 dpi				3437 pixels Data Size: 24,3 M
			i	-
Scan Type) mm
24bit Colour 🔻) inch
Reduce Noise				
Brightness				
	H-L	#		Start
Contrast	Ļ	L		
0		<u>с</u> т		
Document Size			Ì	Help
A4 210 x 297 mm (8.3 x 11. 🔻				Default
Duplex(two-sided) Scanning	1		Ì	Default
Charles (chro sidea) searning	~ 	H-1		Cancel

5. To finish the shell scanning press Start.

MindCAD 2D Design & Engineering


62

6. A dialog box will appear, insert the DPI value and click **OK**.

Image DPI	x
DPI:	300.00
ОК	Cancel


7. The load bar will appear during the scanning process.

8. After the loading is finish the lines will be displayed on the screen.




9. Select all the image.

64



10.Now it's possible to see the lines.



2.9.1.2 File - Digitize - Scanner - Parts


This option lets you scan one or more parts into the software.

1. Select **Options** from **Digitize** option of the **File** menu to adjust the properties, before you start digitizing the part; however, it's recommended to use the **default values**.

	Scanner Options	×
Filter Before	0	0.30
Filter After	Π	0.30
Stuff Dist	Π	1.00
Break Angle	0	30.00
✓ Import image	Scale X: 0 in 100 Y: 0 in 100 OK	Cancel

1

2. Open Select Source from Digitize option of the File menu to select the right scanner.



3. Select Parts from the Digitize option of the File menu. Your scanner software will be launched.

Scan : Photo Web Text	PreScan Width: 210,0 mm 2480 pixels Height: 291,0 mm
Resolution	3437 pixels
300 x 300 dpi 🗸 🗸	Data Size: 24,3 MB
Scan Type	mm
24bit Colour 🗸	🔘 inch
Reduce Noise	
Brightness	Start
Document Size	Help
A4 210 x 297 mm (8.3 x 11. ▼	Default
Duplex(two-sided) Scanning Cong-edge binding	Cancel
Short-edge binding	


4. Adjust the scan properties and select **PreScan**.

🕞 💿 Long-edge binding 📜 Cancel	Scan : Photo P		File Overview 67 PreScan Width: 210,0 mm 2480 pixels Height: 291,0 mm 3437 pixels Data Size: 24,3 MB © mm © inch © inch Start Help Default
--------------------------------	--	--	--


- 5. To finish the shell scanning press Start.
- 6. A dialog box will appear, insert the DPI value and click **OK**.

	Image DPI		
	DPI:	300.00	
	ОК	Cancel	
•	7. The load bar will appe	ear during the scan	, ning process.


8. Select if the part is or isn't face down.




9. After the loading is finish the part will be displayed on the screen.




10.Select all the image.




11.Now it's possible to see the line that composes the part.



12. Select Create Part from the Parts menu, select the line, do a right click and select Finish.



13. The part will be added to the Parts/Library Bar. Double click the part you just created to see it now standalone.



72

2.9.1.3 File - Digitize - Scanner - Select Source

This option lets you select the scanner to use.

- 1. Select the Select Source from the Digitize option of the File menu.
- 2. Select if you what to use the Windows Image Acquisition or the normal interface.

MindCAD2D	×
Use WIA digitizing interface?	
Yes No	

3. Using the WIA to select the source

Select the device to use and press Ok.

<i>3</i>		Select D)evice			×
Which de	evice do g	you want	to use?			
HPF7C997 (HP Officejet Pro X476dw	HP Officejet Pro X476	Brother MFC-8890D				
MFP) Manufacturer: Description:	Microsoft WSD Scan	Device			Properties	
				OK	Cance	1

4. Using the normal interface to select the source, a list of available scanners will be displayed. Select the required scanner and press **Select**.

Select Source	×
Sources: HP Officejet Pro X476dw TWAIN 1.0 (32-3; TW-Brother MFC-8890DW LAN 3.9 (32-32) WIA-Brother MFC-8890DW LAN 1.0 (32-32) WIA-HP Officejet Pro X476dw MFP (1.0 (3) WIA-HPF7C997 (HP Officejet Pro X4 1.0 (3)	Select Cancel

2.9.2 File - Digitize - Image

This menu allows to choose if you selecting an image of a Shell or a Parts.

Shell Parts


2.9.2.1 File - Digitize - Image - Shell

- 1. Select Digitize Image Shell options of the File menu.
- 2. Select the file.


🔾 🗢 📕 « Mind	🚱 🕞 🗢 📕 « Mind 🕨 Data 🕨 Pictures 🔹 🗣 🚱 Search Pictures 🔎									
Organize 👻 New f	folde	er		!≡ ▼ 🗍	0					
Documents	*	Name	Date	Туре	*					
J Music		驞 copy_area_f1.png	14-06-2011 16:00	PNG image						
Pictures		驞 digitize-2-bg.png	23-09-2011 11:32	PNG image						
🛃 Videos		🔄 digitize-214.jpg	13-11-2006 12:29	JPEG image						
		📔 leather.jpg	14-06-2011 15:44	JPEG image						
P Computer			📔 MindCAD.jpg	02-06-2011 14:48	JPEG image	E				
Local Disk (C:)		👫 part.png	04-07-2011 15:42	PNG image						
Local Disk (E:)	Ε	Ш	Ш	Ш	н	Ш	📭 part_tt.png	06-07-2011 16:40	PNG image	
👝 Local Disk (F:)								📡 scan-120.jpg	01-06-2011 15:25	JPEG image
📬 Network		📭 shell.png	04-07-2011 15:39	PNG image						
Network		📔 test.jpg	08-04-2011 16:39	JPEG image	Ψ.					
	Ŧ	•			•					
Fi	le na	ame:	✓ All Grap	hics Files (*.bmp;*.jpg;*	-					
			Ope	n 🖵 Cancel						

3. Insert the DPI.


74 MindCAD 2D Design & Engineering




4. After the loading is finish the image will be displayed on the screen.



5. Select show/hide Images from the Layers options on the View menu.




6. Behind the image are the lines, which are editable.



2.9.2.2 File - Digitize - Image - Parts

- 1. Select Digitize Image Parts options of the File menu.
- 2. Select the file.

C v Mind	Correction of the second secon																																								
Organize 👻 New																																									
Documents	*	Name	Date	Туре	*																																				
J Music		copy_area_f1.png	14-06-2011 16:00	- PNG image																																					
Pictures		驞 digitize-2-bg.png	23-09-2011 11:32	PNG image																																					
H Videos		📔 digitize-214.jpg	13-11-2006 12:29	JPEG image																																					
Computer		📔 leather.jpg	14-06-2011 15:44	JPEG image	E																																				
🖳 Computer 👝 Local Disk (C:)		📔 MindCAD.jpg	02-06-2011 14:48	JPEG image	=																																				
Local Disk (E:)		📭 part.png	04-07-2011 15:42	PNG image																																					
Local Disk (F:)	Ξ	Ε	Ξ	Ξ	Ξ	Ξ	=	=	Ξ	Ξ	E	=	Ξ	Ξ	E	=	Ξ	Ξ	E	=	=	=	E	Ξ	=	Ξ	Ξ	Ξ	Ξ	Ξ	=	=	=	=	Ξ	E	E	😼 part_tt.png	06-07-2011 16:40	PNG image	
		🔄 scan-120.jpg	01-06-2011 15:25	JPEG image																																					
👊 Network					📭 shell.png	04-07-2011 15:39	PNG image																																		
•	+	E test.jpg	08-04-2011 16:39	JPEG image																																					
F	ile n	ame:	← All Graph	ics Files (*.bmp;*.jpg;*	•																																				
			Open	Cancel																																					




Import		×
DPI:		55
	OK	Cancel


4. Select if the part is or isn't face down.

?	Is your part	facing down?
	Yes	No


5. After the loading is finish the image will be displayed on the screen.



6. Select show/hide Images from the Layers options on the View menu.



7. Behind the image are the lines, which are editable.



© 2016 Mind - Software Multimedia e Industrial, SA

2.9.3 File - Digitize - Options

Use this is the option to adjust the properties of the scanning software.

	Scanner Options							
Filter Before		0.30						
Filter After		0.30						
Stuff Dist	<u>_</u>	1.00						
Break Angle	0							
✓ Import image	Scale X: 0 in 100 Y: 0 in 100 OK	Cancel						

Filter Before	Filter the points to a maximum of this value, before a spline is created
Filter After	Filter the points to a maximum of this value, after a spline is created
Stuff Dist	Distance between points between filter operations
Break Angle	The angle between points above which a corner will be inserted in the line
ХҮ	Define the X and Y scale when using the scanner
Import Image	Enable or disable import image

2.10 File - Project Properties

78

Select **Project Properties** from **File** menu, this lets you keep a record of any information regarding your project.

			Project	-	×
Summary Material Op	otions Variants Costing results	Parts			
Name:	30.191 (A)			Images	
Description:	This model was created for 2010 v	rersion			
Created by:	ngoncalves	Created on:	18/01/2010 13:33:00	+	
Changed by:	admin	Changed on:	30/04/2011 05:08:01	-	
Revision:	2	4	L		
Custom attributes:					
Name	Value				^
TIPO					
Client					
CLIENT					
LAST					
SOLE					
YEAR					
Distributor	Mind	-			
特記事項					
その他備考					
メーカー名					
SalesRegion	PT	•			~

2.10.1 Project Properties - Summary

This tab allows to consult the project data, to add personal comments, change the project image or any other information in this area.

			Project	_ 🗆 🗙
Summary Material O	ptions Variants Costing results	Parts		
Name:	30.191 (A)		Images	
Description:	This model was created for 2010 v	ersionproject		>>
Created by:	ngoncalves	Created on:	18/01/2010 12:33:00	+
Changed by:	admin	Changed on:	05/08/2015 10:54:38	-
Revision:	3			
Custom attributes:				
Name	Value			^
TIPO				
Client				
CLIENT				
LAST	camp 03			
SOLE	Camp 03			
YEAR	Child_14			
Distributor	Court			
特記事項				
その他備考				
型紙名				
メーカー名				
SalesRegion	PT	-		
Crimo				~
·				OK Cancel

2.10.2 Project Properties - Material Options

Shows the material groups associated to this project and the material details.

Summary Material Options V	ariants Costing results	Parts			
+ - Groups	+ - Catalogue	Options			
Pele	Name	Material	Description	Unit	Price
Só para aparar Velcro	Option 1	A3	Ocean Leather	ft²	2,50€
Forro	Option 2	A5	Camoflado Leather	ft²	1,00€
Espumas					
Tela Contraforte e Testeira					
Controlo					

- 1. To create a new Material Group, press the button **Groups**; The window new material group will appear;
- 2. Insert the new material group name and press OK.

	New material group	×
Name		
	OK Cancel	

- 3. The group will be created, now to add material to the group, press the button **Catalogue options**; A window with all available material will open.
- 4. Select the required material, press Ok and the material will be added to the group. Its possible to add several material to the same group, to do that repeat the same process.

Note: Use CTRL to select more than one material at the same time.

81

)			Open				- □	
Filters:	4	📑 📄 📑	1	? 🖻 📰 🖽 🖦		Co	lumns	-
Search	٩	Name	ID	Description	Family	Unit	Price	^
All		A2	3492	Brown Flowers	PL	ft ²	1,50€	
New Filter 456		A3	3491	Ocean Leather	PL	ft ²	2,50€	
100		A4	3490	Jeans Leather	PL	ft ²	2,20€	
		A5	3489	Camoflado Leather	PL	ft ²	1,00 €	
		A6	3488	Grey Leather	PL	ft ²	3,00 €	
		A7	3487	Syntetic Grey	PL	ft ²	1,00 €	
		A8	3486	Syntetic Kaki	PL	ft ²	1,00 €	
		AA1	3485	Flowers Leather lady yellow	PL	ft²	3,00€	
		AA2	3484	Flowers Leather lady Blue	PL	ft ²	3,00 €	
		AG.119.OV	764	AGRAFES 119 OURO VELHO	AG		19,45 €	
		AG.119.OX	765	AGRAFES 119 OXIDADOS	AG		19,45 €	
Family 🗸 Unit 🗸 Cu	irrency V	AG.134.DR	766	AGRAFES 134 LATONADOS	AG		22,59€	
> 🍅 / [2730]		AG.134.NI	767	AGRAFES 134 NIQUEL	AG		18,15 €	
		AG.134.OX	768	AGRAFES 134 OXIDADOS	AG		17,19€	
		AP.000049.NI	769	APLICACAO 49 NIQUEL	AP	pair	0,04 €	
		AP.000086.NI	770	APLICACAO 86 NIQUEL	AP		61,79€	
		AP.000225.NI	771	APLICACAO 225 NIQUEL	AP	pair	0,22 €	
		AP.000225.PV	772	APLICACAO 225 PRATA VELHA	AP	pair	0,22 €	
		AP.000239.PR	773	APLICACAO 239 PRETA	AP	un	0,04 €	
		AP.000380.PR	774	APLICACAO 380 PRETA	AP	pair	0,99€	
		AP.000380.TA	775	APLICACAO 380 TARTARUGA	AP	pair	0,99 €	
		AP.000H16.PR	776	APLICACAO H16 PRETO	AP	un	0,00€	
		AP.003353.NI	777	APLICACAO 3353 NIOUEL	AP	pair	0.74 €	~

5. It's possible to edit the name and material group of the material added to the group, just do a double click over the field to edit.

2.10.3 Project Properties - Variants

In this tab you can find the projects variants available in the selected project.

Summary	Material	Options	Variants	Costing results	Parts				
/ariant:		S2	×				Size:	24	¥
Info	Material C	Option Cos	st Assignme	ent Operations	Compo	nents			
Notes:									L
Materials			12,05€						
Compone			374,46						
Operation	ns cost		11,13€						
Total cost	+		397,64	F					

Variants Types:

Material Options Cost Assignment

riant:	S2			 Size: 	24	~						
info Ma	terial Optio	n Cost Assignme	nt	Operations Components								
Gro	oup	Option		Source Material	Unit	Price	Costing group		Area	Section		Total price
Pele		Option 1	•	Ocean Leather	ft²	2,50 €	{Pele}	-	2.0783 ft ²	Costura	-	5,19€
Só para	aparar	Option 1	•	Brown Flowers	ft²	1,50 €	{2D\timbre gola}	-	0.0487 ft ²	Pré-Costura	-	0,07€
		Option 1	•	Flowers Leather lady Blue	ft²	3,00€	{Pele}	-	2.0783 ft ²	Pré-Corte	•	6,23€
Forro		Option 1	•	Brown Lines	ft²	2,00€	{2D\Tira de forro}	-	0.0121 ft ²	Pré-Costura	•	0,02€
Espuma	IS	Option 1	•	AQUILINE S/ COLA 04 (DARK BROWN)	m²	2,56€	{2D\Biqueira}	•	0.0044 m²	Pré-Costura	•	0,01€
Tela		Option 1	•	Brown Lines	ft²	2,00€	{2D\Cano}	-	0.1916 ft ²	Montagem	•	0,38€
Contrafo	rte e Tes	Option 1	•	Camoflado Leather	ft²	1,00€	{2D\Taloeira}	•	0.0509 ft²	Pré-Corte	•	0,05€
Controlo		Option 1	•	Brown Lines	ft²	2,00€	{2D\Taloeira}	•	0.0509 ft²		•	0,10€
Total												12,05€

• Operations

Summary Materia	al Option	s Variants Co	sting results	Parts									
/ariant:	ant: S2 Size: 24												
Info Material Option Cost Assignment Operations Components Add Operation Remove Operation Copy from variant Copy from variant													
Operatio	on		Descrip	tion		Unit	Price	Quantity	Overhead	Section	Size		Total price
Embalament	o -	Embalamen	to		•	min	0,31€	10.000000	1.0 %	Corte	▼ [19.5; 20]	-	3,13€
OP03	•	 Operação 03 	3 (III)		-	min	4,00€	2.000000	0.0 %	Pré-Corte	•	-	8,00€
Total 11,13 €													

• Components

riant: S2	ions	✓ Size:		24	~			
nant; 52		♥ 512€;		24	*			
info Material Optio	n Co	ost Assignment Operations Components						
Add Components		Remove Component Copy from variant						
Component		Description	Unit	Price	Quantity	Section	Size	Total price
AG.119.OV	-	AGRAFES 119 OURO VELHO	•	19,45€	1.000000	•	-	19,45€
AG.119.OX	-	AGRAFES 119 OXIDADOS	•	19,45 €	2.000000	•	-	38,90€
AG.134.DR	-	AGRAFES 134 LATONADOS	•	22,59 €	3.000000	•	•	67,77€
AG.134.NI	-	AGRAFES 134 NIQUEL	•	18,15€	8.000000	•	•	145,20€
AG.134.OX	•	AGRAFES 134 OXIDADOS	•	17,19€	6.000000	•	-	103,14€
Total								374,46€

2.10.4 Project Properties - Costing results

In this area you have two automatic values, the Netresult and Fullresult of each image.

Netresult - Value obtained by the consuming calculation.


Fullresult - Is the Netresult with the factors defined by the user.

You can order by Variant or Group.

Summary Material	Options	Variants	Costing re	sults Parts						
Variant:	2D		~	Gr	oup:	Taloe	ira	*		
Image	Si	ze Me	ethod	Efficiency	Parts	Overhead1	Overhead2	PartsArea	NetResult	FullResult
	. 24	4 Co	nvexHull	94.1%	1			0.00 m² / 0.05 ft²	0.00 m² / 0.05 ft²	0.00 m² / 0.05 ft²

2.10.5 Project Properties - Parts

Allows to consult all the parts in the project.




Right click over a part to access the contextual menu:

Сору
Open part
Open project
Search similar parts

• Copy - Allow to copy the selected part and past directly into MindCAD 2D Design & Engineering.

MindCAD 2D Design & Engineering

- Open project Opens the part project.
- Search similar parts It will use a search engine to search for parts similar to the selected one, and show then in a new tab, Similar parts.



2.11 File - Preferences

Use this option to define the default settings of things like:

- file locations
- colors
- language

84

85

eferences				<u> </u>
Parts	Printer	Default Pr	operties/Layers	Customize
Locations	Options	Digitizer	Language	Default Labels
Font path:		@KaiTi		🏝
Shells path:		E:\Program	Data\Mind\Data\She	ells
Cut path:				
Library Location:		F·\Program	Files\MindCad 2011	V1\Bin\MindC
Location:		E. (Flogram	Files (Millidead 2011	
			Add	
Themes path:				

86

2.11.1 File - Preferences - Locations

Use these options to set your default file locations.

Preferences					×
Printer		Default	Properties	Custor	nize
Locations (Options	Digitizer	Language	Default Labels	Parts
Font path: Shells path: Cut path:			ISimSun ProgramData∖Mind`	\Data\Shells	T
Library Location:		E:\			
Themes path:			Add	a	
		ОК	Cancel	Apply	Help

Font Path - The directory where you keep the font that is loaded by the software on startup; it is recommended that this option is not changed.

Shells Path - The directory where you keep your shells. Select the directory by clicking under to display the Browse for folder dialogue box

Cut Path - The directory where you keep your files for cutting. Select the directory by clicking is to display the **Browse for folder** dialogue box

Library Location - The directory where your punch library is kept. Select the directory by clicking

to display the **Browse for folder** dialogue box

Add - Use this option to create a new library. A lines library could be added to hold standard lines such as heel curves. The library will be displayed in the Parts toolbar. Use the added tab in the same way as the punch library

Remove - Use this option to remove any libraries that you have added.

Themes Path - The directory where your themes are kept. Select the directory by clicking use to display the **Browse for folder** dialogue box

2.11.2 File - Preferences - Options

Use these options to set personal preferences for:

- autosave
- line deletion
- drawing margins
- export
- line widths of model when drawing
- default document size
- keep multiple versions of documents

MindCAD 2D Design & Engineering

eferences					- ×			
Printer		Default F	roperties	Custon	nize			
Locations	Options	Digitizer	Language	Default Labels	Parts			
Auto-save Image: Confirm deletion of dependent lines Continuous Drawing Margin: 0.5 Image: Use line widths of model when drawing Image: Pick multiple parts New document properties Width (mm): 2000 Height (mm): 2000								
Number of ve	✓ Keep multiple versions of documents Number of versions to keep:							
 Draw mode Fast Quality Auto-degrad 	de quality	Monitor	de (mm): 593					
		ОК	Cancel	Apply	Help			

A comprehensive description on available options follows:

Autosave	If ON, your work is automatically save at the specified time interval
Confirm deletion of dependent lines	If ON, you will be warned if the line you are trying to delete has other lines dependant on it
Continuous Drawing Margin	Parts can be digitized from a tablet using a mouse with a small 'follower'. The special cursor is tracked around the outline of the part and this option is used to give the offset required to offset the input points back to the original part boundary
Use line widths of model when drawing	If ON, line drawing is done with the thickness specified by the user. If OFF the thickness is equivalent to zero, the thinnest possible line is displayed

88

Pick multiple parts	If ON, activates pick multiple parts
New Document Properties	set the default document size in millimetres
Keep multiple versions of documents	If ON, activates versioning which allows for retrieval of old versions
Number versions to keep	number of versions to be kept in the history of a document
Draw Mode	Select Fast or Quality mode. Enable or disable Auto- degrade quality.
Monitor	If the Override option are ON the user as tospecify the dimensions of is monitor in mm.

2.11.3 File - Preferences - Digitizer

Use these options to set the cursor keys actions when digitising with a tablet.

	Digitizer]
Digitizer: Digitizer not fo	ound	
Dimensions:		
Key Setup:		
canvas/screen mode:		Change Erase
Select:		Change Erase
Finish:		Change Erase
Next tool:		Change Erase
Previous tool:		Change Erase

2.11.4 File - Preferences - Language

Use this option to select your preferred language.

91

2.11.5 File - Preferences - Default Labels

Use these options to create default text on your parts.

Auto add on part creation: Border V Size (mm): 3				Default Labels	
Auto add on part creation: Border Size (mm): Properties:	Default labels				
Size (mm): 3 Properties:	Text:	%Part%		~	
Properties:	Auto add on part	creation:	Border	*	
	Size (mm):	3			
Create Delete	Properties:				
		Create Delete	е		

Text - The drop down list contains the following standard text components.

%Part % %Number % %Model % %Area %m2 %Length %mm %File Date % %File Name % %Component % %Dimension %mm

%Part% - Part name

%Model% - Shell name

%Area%m2 - Part area in square meters.

%Length%mm - Part boundary length in millimeters.

%FileName% - The name of the scd file.

92 MindCAD 2D Design & Engineering

%FileDate% - Date of last modification of the file.

%Component% - Material name.

%Dimension%mm - Provide parts dimensions.

Auto add on part creation - If ON, the text components you have selected will be automatically added when the part is created, in the **border** or in the **inside**, depending of witch option is chosen.

Size (mm) - Height of the text in millimetres

Properties - Set a property for your text. The property will be sent to the cutter and can be used to define the tool that is used to produce the text.

Create - Use this to add a text string to the drop down list. For further details see Adding a new text string.

Delete - Remove unwanted strings by selecting the text and clicking this option.

2.11.5.1 Adding a new text string

New text strings can be added to the default labels dropdown

- 1. Select Create on the Default Labels tab.
- 2. Type in the required text in the dialogue box

	×
Type the new part label name	
OK Cancel	

3. Click OK

The text is added to the dropdown list and can be applied to parts.

2.11.6 File - Preferences - Parts 1

Use these options to set the default settings for:

- Groups
- Names

File Overview	93
---------------	----

Groups V V + - Names Name: V	Groups	àroups	Parts (2)	Printe	er	Default Properties	/Layers	Customize
Vames Name: Group: Vame:	Names Name: Color:	V V + -	Locations	Options	Digitizer	Language	Default Labe	ls Parts (1
Vames Name: Group: Vame:	Names Name: Color:	V V + -	Crowne					
Names Name: Group: Color:	Names Name: Vame: V Group: V Color: V	Names ame: V roup: V olor: V	Groups					
Name: Group: Color:	Name: Group: Color:	ame: roup: lolor: l		×	*			
Group:	Group:	roup:	Names					
Color:	Color:	olor:	Name:			~		
			Group:			~		
			Color:	.				
Create Delete	Create Delete	Create Delete						
			Ci	reate I	Delete			

2.11.6.1 File - Preferences - Parts - Groups

Use this option to create materials. These materials can be applied as a section of the text on your finished parts.

Groups			_	_
leather	¥	 -	+	-

Groups - Select the required group from group from the drop down list.

Color - Select this option if you want parts with the same group to be the same color.

• Click "+" to open a dialogue box that allows you to create a new group name that will be added to the **Groups** drop down list. Enter the name in the dialogue box and click **OK**.

94

2.11.6.2 File - Preferences - Parts - Names

Use this option to select the names and materials to be applied as a section of the text on your finished parts.

Names			
Name:	toecap		~
Group:	leather		~
Color:	AUTO	•	
	Create	Delete	

Name - Select the required name from the drop down list.

Material - Select the required material from the drop down list. The parts with the Name you have selected will use the material you select in this option.

Color - Select this option if you want parts with the same material to be the same color.

Create - Click **Create** to open a dialogue box that allows you to create a new name that will be added to the **Name** drop down list. Enter the new material name in the dialogue box and click **OK**

2.11.7 File - Preferences - Parts 2

Use these options to set the default settings for:

- Rotation
- Reference points
- Post-processing part filtering
- Default stencils margin
- Name template
- Part assessment

owed rotation: 180 degree step Tolerance: 0 Use %S for slot number Use %P for part index Use %C for number of parts Use %M for model name Part assessment Method Convex Hull Parts margin 0 mm Size: 30 Size: 30 Size: Nargin: 10 Sost-processing part filtering	Ilowed rotation: 180 degree step ∨ Tolerance: 0 0 ▼ Use %S for slot number Use %P for part index Use %C for number of parts Use %M for model name eference points Part assessment reate: On vertical axis ∨ Shape: Round chess ∨ Size: 30 Margin: 10 Post-processing part filtering	otation		Name template
Tolerance: Image: Convextical axis Use %P for part index deference points Use %M for model name eate: On vertical axis Part assessment Shape: Round chess Method Convex Hull Size: 30 Image: Convex Hull Image: Convex Hull Parts margin 0 mm Image: Convex Hull Image: Convex Hull Post-processing part filtering Image: Convex Hull Image: Convex Hull Image: Convex Hull	Tolerance: 0 Image: Use % P for part index eference points Use % M for model name reate: On vertical axis Part assessment Shape: Round chess Method Convex Hull Size: 30 Image: Use % M for model name 0 mm Post-processing part filtering Post-processing part filtering Image: Use % M for model name	ase angle:	90	M%S
Tolerance: U U U Use %C for number of parts deference points Use %M for model name Part assessment eate: On vertical axis V Method Convex Hull Shape: Round chess Method 0 mm Size: 30 Image: 10 Image: 10 Image: 10 Post-processing part filtering Image: 10 Image: 10 Image: 10	Tolerance: 0 Image: Use %C for number of parts Use %M for model name eference points reate: On vertical axis Part assessment Shape: Round chess Method Convex Hull Size: 30 Image: Use %C for number of parts 0 mm Post-processing part filtering Post-processing part filtering 0 0	lowed rotation:	180 degree step 🛛 🗸	
Use %M for model name ference points eate: On vertical axis Shape: Round chess Size: 30 Margin: 10 Post-processing part filtering	Use %M for model name eference points reate: On vertical axis Shape: Round chess Size: 30 Margin: 10 Post-processing part filtering	Tolerance:	0	-
eate: On vertical axis V Shape: Round chess V Size: 30 1 Margin: 10 1 Parts margin 0 mm	reate: On vertical axis ∨ Shape: Round chess ∨ Size: 30 ↓ Margin: 10 ↓ Post-processing part filtering			
Shape: Round chess Size: 30 Margin: 10 Post-processing part filtering	Shape: Round chess Size: 30 Margin: 10	eference points -		Part assessment
Size: 30 Margin: 10 Post-processing part filtering	Size: 30 Margin: 10 Post-processing part filtering	reate:	On vertical axis 🛛 🗸	Method Convex Hull
Margin: 10 Post-processing part filtering	Margin: 10 -	Shape:	Round chess 🗸 🗸	Parts margin 0 mm
Margin: 10 Post-processing part filtering	Margin: 10 -	Size:	30	
Post-processing part filtering	Post-processing part filtering	Marrin		
		Margin.	•	
			_	

2.11.7.1 File - Preferences - Rotation

Allows to define the rotation angles for auto nesting.

After inserting the Angle and Range, click "+" button, to add the new angle range. To delete an angle range, select it and press "-" button.

All the parts created after this change will be by default with this rotation angles. This can be also configured individually in the parts properties.

96

2.11.7.2 File - Preferences - Reference points

This option allows to add predefined reference points automatically when creating parts.

Reference points		
Create:	On vertical axis	~
Shape:	Round chess	~
Size:	30	
Margin:	10	

Create: Select where to create the points, On Center (one point in the part center), On Vertical Axis (two points in the part vertical axis), On Horizontal Axis (two points in the part horizontal axis), by Bounding (four points, one in each corner of parts the bounding box).

Shape: Select the points shape from, Circle, Square, Cross, Square chess or Round chess.

Size: Select the points size.

Margin: Select the points margin (from the part) in mm.

2.11.7.3 File - Preferences - Post-processing part filtering

Enable or disable the post-processing part filtering option for the. This is effective for new parts (created after handling this settings).

The post-processing is defined in the parts properties tab.

2.11.7.4 File - Preferences - Default stencils margin

Allows to control the stencils margins, when cutting the part.

This can be also configured individually in the parts properties.

Default stencils margin:

•

2.11.7.5 File - Preferences - Name template


This option allows to assign automatically names to parts.

Name template	
M%S	
Use %S for slot number Use %P for part index Use %C for number of parts Use %M for model name	

The default value is M%S in this case the parts name will appear, like M1, M2 depending in which slot they are assigned.




If the part changes to other slot, the name will change, in this example from M4 to M5.



2.11.7.6 File - Preferences - Part assessment

Use this option to define a preferred part assessment method and part margin.



• Method: Several interlock costing techniques can be used;

There are several methods:


~	Convex Hull
	Parallelogram
	Inverse parallelogram
	Bounding box
	Linear
	Circle
	Grid
	Synthetic

• Parts Margin: Adds a margin in mm between parts;

2.11.8 File - Preferences - Printer

Use these options to set some printer control:

- Control colour
- Control scale
- Enable or disable use lines widths of model when printing
- Pen width
- Enable or disable print file data
- Enable or disable print file name



2.11.9 File - Preferences - Default Properties/Layers

Use these options to create and set default properties and Layers for lines, parts, punches.

Properties Layers Layers Properties Layers Layers Reforce
Halfout Pen Eforce
Add Remove Add Remove
Reset Reset

100

2.11.10 File - Preferences - Customize

Use these options to choose or configure the application theme, and the popup menus.

			Customize
Theme			
		Duplicate	
White	~	Delete	
		Customize	
Popup menus			
Customize			

2.11.10.1 Editing Theme

Use these options to edit a theme.

1. To duplicate a theme, select one of the existing one and press $\ensuremath{\text{Duplicate}}$.

Theme		Duplicate	2
White	Υ.	Delete	
		Customize	

2. To customize a theme, select Customize.

Theme		Duplicate
White(2)	~	Delete
		Customize

Note: If the <u>buttons</u> of the theme option <u>aren't available</u>, it's because the themes path is not defined yet. So please go to File - Preferences - Location and select the themes path.

3. All the visual environment parameters can be changed for this new theme.

Theme customization	×
Name	White(2)
BACKGROUND	255,255,255
PARTWND 🖃	
SELECTED	255,196,0
UNSELECTED	0,0,0
HIGHLIGHTED	255,0,0
PARTNAME_SHADOW	0,0,0
PARTNAME_SELECTED	255,0,0
PARTNAME_UNSELECTED	128,128,128
PLACE_PART	
GRID 🖃	
POINTS	0,0,0
LINES	128,160,128
PALETTE 🔳	
GRADING CENTERS	
SEGMENT HIGHLIGHTING	
	▼
	OK Cancel

2.11.10.2 Popup menus

Use these options to customize popup menus .

1. Select customize (popup menus) and open the **Menu** drop down list.

102 MindCAD 2D Design & Engineering

Customize menus			
Menu:	<ali></ali>		-
		Clear menu Add	
		Separator	Top level menu
		Add	File
		Menu item	
		File/New	✓ Add
		Рорир	
			Add
		Predefined menu	group
		General settings	▼ Add
			OK Cancel

In this list, the available tools in which the popup menu could be configured.

<All> Selection tool Create lines tool Create markers tool Create punches tool Create parts tool Measurement tool Create circles tool Create rectangles tool Rotate lines tool Scale lines tools Modify parts tool Create symmetric shapes tool


2. Using the Clear Menu button will in fact, remove all the default items of the menu.

3. Using the Add Separator button will add a separator for better organization of the menu

4. On the **Top Level Menu** section a drop down list is available with the default top level menus. After selection, use the **Add** button for insertion of the entire top level menu and its children. To remove the item, just select it on the tree view on the left and press the **Del** key.

Customize menus				×
Menu:	<all></all>		•	
····· [Parts]		Clear menu Add		
		Separator	Top level menu	
		Add	Parts 🔻	Add
		Menu item	File Edit	
		File/New	View Tools	Add
		Popup	Operations Parts	
			Grading Window	Add
		Predefined menu	Applications gr(Help	
		General settings	; •	Add
			ОК	Cancel

Follows a sample of an insertion of the top level menu **Parts** on a popup menu.



104 MindCAD 2D Design & Engineering

5. On the **Menu item** section a drop down list is available with all the menu entries. After selection, use the **Add** button for insertion. To remove the item, just select it on the tree view on the left and press the **Del** key.

Customize menus		
Menu:	<all></all>	▼
[Parts]		Clear menu Add
		Separator Top level menu Add File Add
		Menu item
		File/New Add
		File/Photograph/Generate calibration grid File/Preferences File/Page Setup File/Print Add
		File/Print Parts File/Print Preview File/Print Setup File/Recent File File/Exit
		Edit/Undo Edit/Redo Edit/Cut Edit/Copy

Follows a sample of an insertion of the **Print Parts** menu entry on a popup menu.

2	Undo	Ctrl+Z
X	Delete	Del
ø	Cut	Ctrl+X
Ð	Сору	Ctrl+C
ē	Paste	Ctrl+V
	Mirror	
	Arrow Moven	nent Step
	Change	F12
f	Properties	Alt+Enter
	Parts	+
	Print Parts	

6. On the **Popup** section it is possible to create a new sub menu by simply writing its name and pressing the **Add** button. To remove the item, just select it on the tree view on the left and press the **Del** key.

Popup	
Sub-menu	Add

It's possible to add child items using the previously described options, by selecting the created sub menu on the tree view on the left.

Customize menus		3
Menu:	•	
… [Parts] … File/Print Parts ⊡ Sub-menu … File/Cut/Manage Cutters	Clear menu Add Separator Add File	
	Menu item File/Cut/Manage Cutters Add	
	File/Cut/ <export_mend> File/Cut/Manage Cutters File/Digitize/Scanner/Shell File/Digitize/Scanner/Parts File/Digitize/Scanner/Select Source File/Digitize/Image/Shell</export_mend>	
	File/Digitize/Image/Parts File/Digitize/Options File/Photograph/Shell File/Photograph/Parts File/Photograph/Calibrate Camera	
	File/Photograph/Generate calibration grid Cancel	J

Follows a sample of an insertion of the **Manage Cutters** menu entry on the sub menu called **Sub Menu** on a popup menu.

106	Mino	dCAD 2D Des	sign & Engin	eering		
	2	Undo	Ctrl+Z			
	X	Delete	Del			
	ø	Cut	Ctrl+X			
	Ð	Сору	Ctrl+C			
	Ē	Paste	Ctrl+V			
		Mirror				
		Arrow Mover	ment Step			
		Change	F12			
	f	Properties	Alt+Enter			
		Parts	+			
		Print Parts				
		Sub-menu	•	Manage Cutters		

7. On the **Predefined menu group** section a drop down list is available with the available settings groups. After selection, use the **Add** button for insertion. To remove the item, just select it on the tree view on the left and press the **Del** key


File	Overview	

ustomize menus	
/enu:	▼
[Parts] File/Print Parts ⊡ Sub-menu File/Cut/Manage Cutters	Clear menu Add Separator Add File Add
[Treatment settings]	Menu item
	File/New Add
	Popup
	Predefined menu group
	Treatment settings
	General settings Offset settings Marker settings Cancel
	Corner settings Notch settings Punch settings
	Treatment settings Export shell Import shell Cut model

Follows a sample of an insertion of the **Treatment settings** group, just after the sub menu called **Sub Menu,** on a popup menu.

8 Min	dCAD 2D De	sign & Engir
	Undo	Ctrl+Z
	Delete	Del
st and a start sta	Cut	Ctrl+X
	Сору	Ctrl+C
	Paste	Ctrl+V
	Mirror	
		the second s
	Arrow Mover	
	Change	F12
Ê	Properties	Alt+Enter
	Parts	•
	Print Parts	
	Sub-menu	+
	Sub-menu None	•
		•
	None) O F
	None Overlap	
	None Overlap Fold	F

8. It's possible to change the order of the inserted items by simply selecting and drag-and-dropping it in the new position.



2.12 File - Printing


This menu allows to control the printing options.

Page Setup			
Print	Ctrl+P		
Print Parts			
Print Preview	/		
Print Setup			

2.12.1 File - Page Setup


Use this option to control the printing of the current shell.

1. with the mouse we can control the pages locations related to the model, click over the page and drag it.



2. with Shift and mouse left click the operator can enable or disable the pages to be printed.

110 MindCAD 2D Design & Engineering



2.12.2 File - Print

Use this option to print the current shell.

This is the	e same as clic	king the Prir	nt 📄 but	tton in the Ma	in toolbar	r or pressing	Ctrl+P
🗋 🧀	• 🖪 🖨	X 🗈	<u></u>	🛯 🔍		👽 🗸	

2.12.3 File - Print Parts

Use this option to print your parts.

Select Models, Groups, Parts to print.

111

		Parts selection		×
Models Default	Parts			Sizes
	Name ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓	Model Default Default	Group Leather	
Groups	 ✓ [] M3 ✓ () M4 	Default Default	Leather	
				OK Cancel

2.12.4 File - Print Preview


Use this option to preview a print out.

2.12.5 File - Printer Setup

Use this option to set up your printer.


2.13 File - Exit

Use this option to exit the program.



3 Edit Overview

This menu lets you carry out some of the editing commands, it also allows you to undo edits that have been made, and restrict editing of items that are correct.



3.1 Edit - Undo

This option undoes the last editing command.



114

3.2 Edit - Redo

This option redoes the last undo command.



3.3 Edit - Cut

This option cuts the currently selected items. Cut copies the selected items to the clipboard, then deletes the selected items.

This is	the s	same	as clicki	ng the	e Cut	x	butto	on in tl	ne Mai i	n toolb	ar or pr	ressing Ctrl	+X
	õ			X		â	5			\bigcirc		-	

6.0

3.4 Edit - Copy

This option copies the currently selected items into the clipboard.

This is the same as clicking the Copy	button in the Main toolbar or pressing Ctrl+C
	👔 🖍 ঝ 🕄 🚱 🏟 🚬

3.5 Edit - Paste

This option pastes the contents of the clipboard (filled by **Cut** or **Copy**) into the current window and leaves it active so it can be moved to a new position. Drag the contents of the clipboard and place using the left mouse button.

This is the same	as clicking th	e Paste	button i	n the Main	toolbar or	pressing Ctrl+V
🗋 📂 🖪			50	🔍 🔮)	-

3.6 Edit - Fixed Paste

This option pastes the contents of the clipboard (filled by **Cut** or **Copy**) into the current window in its original position

3.7 Edit - Delete

This option deletes the currently selected items. This is the same as pressing the **Delete** key on your keyboard.

3.8 Edit - Select All

This option selects all items. This is the same as pressing Ctrl+A

3.9 Edit - Reverse Selection

This option reverses the current selected items. If you want to select all items except a number of lines, select the lines you do not want to select and use this option. This is the same as pressing **Ctrl+Shift+W**

3.10 Edit - Group

This option lets you treat a number of lines as a single object. If any line within a group is selected all the other lines in the group will be selected as well.

1. Select the lines that you wish to make into a group.



2. Select Group from the Edit Menu

3.11 Edit - Ungroup

This option lets you return lines within a group to individual lines.

1. Select any line in a group.



2. Select Ungroup from the Edit Menu

3.12 Edit - Freezings

This option lets you **Freeze** and **Unfreeze** lines. If lines are frozen, they cannot be edited, use Unfreeze to make them available for editing.

Freeze all			
Freeze selection	Ctrl+F		
Freeze all but selection			
Unfreeze all	Ctrl+Shift+F		

Freeze all - Freeze all lines.

Freeze selection - Freeze the selected lines or pressing Ctrl+F.

Freeze all but selection - Freeze all lines except the selected lines.

Unfreeze all - Unfreeze all lines or pressing Ctrl+Shift+F.

3.13 Edit - Constrain Edit

Set of options that enable you 'snap' editing or drawing operations to specific points. You can use any combination of the **Nearest** options together. This lets you select all options if you want the snap options to work to their full capabilities.

Ş	Nearest line	н
X	Nearest intersection	к
ſ	Nearest end	L
\$	Nearest point	J
扭	Nearest grid	G

3.13.1 Edit - Constrain Edit - Nearest Line


Use this option to make all editing and drawing operations snap to the nearest line, when the cursor is close to it.



This is the same as clicking the **Constrain Edit Nearest Line** button ir toolbar or pressing **H**

button in the Constrain

Snap to the Nearest Line:



3.13.2 Edit - Constrain Edit - Nearest Intersection


Use this option to make all editing and drawing operations snap to the nearest intersection between lines, when the cursor is close to it.



This is the same as clicking the **Constrain Edit Nearest Intersection**

button in the

Snap to the Nearest Intersection:



3.13.3 Edit - Constrain Edit - Nearest End


Use this option to make all editing and drawing operations snap to the nearest line end, when the cursor is close to it.



This is the same as clicking the Constrain Edit Nearest End toolbar or pressing ${\ensuremath{\mathsf{L}}}$

button in the **Constrain**

Snap to the Nearest End:




3.13.4 Edit - Constrain Edit - Nearest Point

Use this option to make all editing and drawing operations snap to the nearest point on a line and to the geometric centre on symmetry shapes when the cursor is close to it.



This is the same as clicking the **Constrain Edit Nearest Point** button in the **Constrain** toolbar or pressing **J**

Snap to the Nearest Point:



Snap to the geometric centre on symmetry shapes:



120

3.13.5 Edit - Constrain Edit - Grid


Use this option to make all editing and drawing operations snap to the grid when the cursor is close to it. In addition,

- When the cursor is on a grid line, the *grid* is displayed in blue.
- When the cursor is on a grid intersection, grid intersection is displayed in red.



This is the same as clicking the **Constrain Edit Nearest Grid** toolbar or pressing **G**

Snap to the Nearest Grid:




3.13.6 Edit - Constrain Edit - Orthogonal Restriction

1. Select the desired constrain editions.




2. Start drawing a line, after doing the first point if you move the mouse courser the line will move freely, but if you press **SHIFT** key the orthogonal restriction is activated.





3.14 Edit - Drag Constrain

This lets you control whether a line(s) can be dragged (moved), rotated or scaled.



If Drag Constrain is ON,

- Lines cannot be dragged, rotated or scaled.
- It is only possible to move points in a line. This means whole lines do not accidentally get dragged to a new position.

122

3.15 Edit - Pre-copy

Use this option to copy a line or lines before editing them.

- 1. Select the lines.
- 2. Select **Pre-copy** from the **Edit** menu **I** or pressing **Ctrl+Shift+C**.
- 3. Edit the lines as required. The original lines are left untouched and the new lines are modified.

3.16 Edit - Digitize

This lets you digitize lines from a tablet . To return to using the cursor, select the option again.

3.17 Edit - Alignment Points

Use this option to align the reference points of the current shell and the physical reference points on the digitizer.

Remark on Screen Remark on Tablet Clear

A sample sequence follows:

- 1. define two reference points on the working shell.
- 2. define the same two points now on the digitizer for the alignment.
- 3. clear the alignment points.

3.18 Edit - Properties

This displays the current document size in mm and side. To change the document size, type in the new values required and side.

It's possible to display notes in the project load, in order to do that:

- 1. Write the notes for the project in the text box.
- 2. Select the option display notes box on load.

	Docum	ent properties ×
Notes project notes d	lisplayed on load!	
Display note Selected page pr Width (mm): Height (mm): Side:		Part name template %M%P Use %S for slot number Use %P for part index Use %C for number of parts Use %M for model name
		OK Cancel

3. Press **Ok** and save the document changes.

4. When someone opens the project the message will be displayed.

MindBags	
i	project notes displayed on load!
	ОК



4 View Overview

126

This menu lets you control what is displayed on the screen

	Zoom to fit	Ctrl+D
1:1	Zoom 1:1	Ctrl+Shift+D
	Toolbars	•
	Layers	•
	Filters	•
	Grid	•
	Full Screen	F3

You can use it to turn on or off the following

- toolbars
- layers
- filters
- grid

(2)

(+4)

4.1 View - Zoom to Fit

This option lets you scale any graphics, so that it fits onto the screen. This is the same as clicking



In addition to Zoom to fit, you can add the following buttons to your customised toolbar

Zoom in x 2 - A rectangle is displayed with a magnifying glass at the centre, place the magnifying glass at the point you want to centre, and press the left mouse button. The scale will be increased by 2.


Zoom in x 4 - A rectangle is displayed with a magnifying glass at the centre, place the magnifying glass at the point you want to centre, and press the left mouse button. The scale will be

increased by 4.
Zoom out x 2 - select this option to reduce the scale by a factor of 2.
Zoom out x 4 - select this option to reduce the scale by a factor of 4.

4.1.1 View - Zoom to Fit to selected elements


To zoom to fit to selected elements:

1. Select the desired elements.



2. Click the **Zoom to fit** button in the **Main** toolbar or pressing **Ctrl+D**

128 MindCAD 2D Design & Engineering



4.2 View - Zoom 1:1

When this option is used, the graphics are scaled to the correct physical dimensions. This is the



If Zoom 1:1 doesn't work correctly please go to the File-Preferences-Options and specify the correct value (in mm) of your monitor.

4.3 View - Toolbars

Use this option to select the toolbars that are displayed.

•	Main
~	Constrain
~	Layers
•	Tools
~	Parts
~	Browser
•	Parts/Library
	Customize

4.3.1 View - Toolbars - Main

Use this option to turn on/off the main toolbar. It is recommended that this menu is displayed at all times.



4.3.2 View - Toolbars - Constrain

Use this option to turn on/off the constrain toolbar. It is recommended that this menu is displayed at all times.



4.3.3 View - Toolbars - Layers

Use this option to turn on/off the layers toolbar. It is recommended that this menu is displayed at all times.



Where there is more than one project open, there will be one layer toolbar for each project.

4.3.4 View - Toolbars - Tools

Use this option to turn on/off the tools toolbar. It is recommended that this menu is displayed at all times.



4.3.5 View - Toolbars - Parts

Use this option to turn on/off the parts toolbar. It is recommended that this menu is displayed at all times.



4.3.6 View - Toolbars - Browser

Use this option to hide/display the browser bar.

M1 M2 M3 M4 Properties Connections Markers Markers Markers Punches Punches Connections Markers Mar	x
M1 M2 M3 M4 Properties Connections Markers Markers Notches Offsets Punches 	
- Design 🧧	

Click in ^S to see the **normal line coloring**

Click in ⁵⁵ to see the **line coloring by layer** (to add more layers go to File - Preferences - Default Properties/Layers)

Click in to see the **line coloring by properties** (to add more properties go to File - Preferences - Default Properties/Layers)

Click in ³⁵⁵ to see the **line coloring by dependencies**

Use this option to turn On
 Off
 the parts layer.
 Parts
 m

➡ Parts M1 M2 M3 M4

Use this option to turn On @/Off the parts properties layer.

Properties	
Connections	🔒 👁
Markers	🔒 👁
- Notches	逼 👁
··· Offsets	🔒 👁
Punches	🔒 👁


Use this option to turn On @/Off / layer by layers, those are:

- image layer (0), construction lines (Construction), style lines (Design) and lining lines (Lining).

Layers		
··· 0	2	œ۵
- Construction	2	œ۵
- Design	2	œ۵
Lining	2	œ,

4.3.7 View - Toolbars - Parts/Library Bar

Use this option to turn on/off the Parts/Library toolbar. It is recommended that this menu is displayed at all times.



4.3.8 View - Toolbars - Customize

This allows advanced interface customization.

Customize			
Edit View Tools Operations Parts Grading Window Applications Help New Menu User defined			
	C	lose	

4.3.8.1 View - Toolbars - Customize - Commands

In the commands tab are available all the program commands, arranged by Categories.

Customize				
Commands Categories File Edit View Tools Operations Parts Grading Window Application Help New Menu	s ns J		Customize	
User defin All Comma Description	inde	~	MindCAD 2D Design Engineering ¥	

The user can drag any command to the toolbars.

134

4.3.8.2 View - Toolbars - Customize - Toolbars

Use these options to create your own toolbars and to reset the existing ones.

Customize					
Commands Toolbars Keyboard Menu Opt	tions				
Toolbars:					
 ✓ Constrain ✓ Grading 	Reset				
✓ Layers ✓ Main	Reset All				
Menu Bar	New				
✓ Parts ✓ Tools	Rename				
	Delete				
	Show text labels				
	Close				

To add a customized toolbar please follow this sequence:

1. On the Toolbars tab, click New

Toolbar Name	×
Toolbar Name:	ОК
	Cancel

 $\ensuremath{\text{2.}}$ Insert the name and press OK, the new bar will appear.



3. In the commands tab are available all the program commands, arranged by Categories

4. Select the required command button and Drag and drop to the toolbar. To drag the command, click over it with the left mouse button and keep it pressed

Customize				
Commands Toolbars Keyboard Menu Options Categories: Commands: File Image: Commands: Edit View New Tools Open Image: Commands:				
Parts Close Grading Window Applications Help New Menu User defined All Commands MindCAD 2D Design Engineering				
Description: Open an existing document Close				

5. When the mouse button is over the toolbar, you can let go of the left mouse button



6. The button will be added to the toolbar



7. To remove a button from the **current toolbar**, select the button and drag and drop it to the commands list.

4.3.8.3 View - Toolbars - Customize - Keyboard

This option allows you to create your one keyboard shortcuts.

Customize					
Commands Toolbars	Keyboa	ard Menu Options			
Category: File	~	Set Accelerator for: Default V	<u>@</u>		
Commands: Current Keys: Exit Assign FileDigitizeImageParts Remove FileDigitizeScannerShet Press New Shortcut Key: Image: Command of the active document Reset All					
			Close		

1. Select the Category and the Command to add the shortcut.

Customize	×
Commands Toolbars Keyboard Menu Op Category: Set Accelerator fr Tools Default Commands: Current Keys: Arc Arc Average lines Axis Bezier Bounding Box Continue Line Press New Short Copy Properties Description:	Assign Remove
	Close

2. Select the text box **Press New Shortcut Key** and press keys to assign to add the shortcut.

	Customize	X
Commands Toolbars Keyb	ooard Menu Options	
Category:	Set Accelerator for:	
Tools 🗸	Default 🗸 😪	
Commands:	Current Keys:	
Arc Average lines	Assign	
Axis Bezier	Remove	
Bounding Box Continue Line Copy Properties	Press New Shortcut Key: Reset All	
< >	Shift+A	
Description:	Assigned to:	
	[Unassigned]	
L		
	Close	

3. To remove the shortcut, select it and press **Remove**.

138	MindCAD 2D Design & Engineering

	Customize	×
Commands Toolbars Ke	yboard Menu Options	
Category: Tools	Set Accelerator for:	
Commands:	Current Keys:	-
Arc Average lines Axis Bezier Bounding Box Continue Line Copy Properties Copy Properties Description:	Press New Shortcut Key	Assign Remove Reset All
		Close


4. The button $\ensuremath{\text{Reset All}}$ allows to set the original shortcut and delete the custom ones.

4.3.8.4 View - Toolbars - Customize - Menu

Custo	mize 🛛 🗙
Commands Toolbars Keyboard Menu	Options
Application Frame Menus:	Context Menus:
Show Menus for:	Select context menu:
MindCad2D 🗸	V
Reset	Reset
MindCad2D Document	Hint: select the context menu, change the page to 'Commands' and drag the toolbar buttons into the menu window.
Menu animations: None V Menu shadows	
	Close

Application Frame Menus

Select the desired menu to reset from the "Show menus for:"



After selecting the menu, press the **Reset** button, when you do that the menus will return to the original state.


Menu Animations

It's possible to select animations for the menus.

Menu animations:	None 🗸
 Menu shadows 	None Unfold Slide
	Fade [Default]

140

4.3.8.5 View - Toolbars - Customize - Options



Toolbar

Show Screen Tips on toolbars - Enable/ Disable the tooltips

- Show shortcut keys in Screen Tips - This option is available only when the Show Screen Tips on toolbars is enable.

Large icons - Select this option to see the icons larger.


Normal icons

Large icons



4.4 View - Layers

Use this to show the options for displaying layers



The available layers are:

- Lines
- Parts
- Punches
- Notches
- Markers
- Images
- Grading Centres
- Grading Points
- Alignment Points

4.4.1 View - Layers - Lines

Use this option to turn on/off all lines. This is the same as clicking the **All Lines** button in the **Layers** toolbar.



4.4.2 View - Layers - Parts

Use this option to turn on/off the parts layer.

This is the same as clicking the **Parts** without the **Layers** toolbar



4.4.3 View - Layers - Punches

Use this option to turn on/off the punches layer.

This is the same as clicking the **Punches** button in the Layers toolbar



4.4.4 View - Layers - Markers

Use this option to turn on/off the markers layer.

This is the same as clicking the **Markers** button in the **Layers** toolbar.



4.4.5 View - Layers - Notches

Use this option to turn on/off the notches layer.

This is the same as clicking the **Notches** button in the **Layers** toolbar



4.4.6 View - Layers - Images

Use this option to turn on/off the images layer.

This is the same as clicking the **Images** button in the **Layers** toolbar



4.4.7 View - Layers - Alignment Points

Use this option to turn on/off the reference points.

4.5 View - Filters

Use this to hide or show lines.

Hide all	
Hide selection	Ctrl+U
Hide all but selection	Ctrl+R
Show all	Ctrl+W
Reverse	Ctrl+Shift+U

Hide all - Hide all lines.

Hide selection - Hide the selected lines, or press Ctrl+U

Hide all aut selection - Hide all lines except the selected lines. Alternatively, press Ctrl+R Show all - Show all lines. Alternatively, press Ctrl+W

Reverse - Reverse the show/hide selection. Alternatively, press Ctrl+Shift+W

4.6 View - Grid

Use this option to control how the grid is displayed and the spacing of the lines within the grid.

•	Lines
	Points
	None
	Spacing

4.6.1 View - Grid - Lines

Use this option to display the grid as a series of dashed lines.

L
i i i i
i i i i
i i i i
i i i i
i i i i
i i i i
i i i i
i i i i
i i i i
i i i i
i i i i
i i i i
i i i i
i i i i

144

.

4.6.2 View - Grid - Points

.

Use this option to display the grid with points at the grid intersections only.

```
· · · · ·
```

.

4.6.3 View - Grid - None

Use this option to turn off the grid.

4.6.4 View - Grid - Spacing

Use this option change the spacing of the lines within the grid.


Grid spacing	—
Spacing	50.00
ОК	Cancel

Spacing - Enter the in the value required.

4.7 View - Full Screen

Use this option to view only graphics, so that it fits onto the screen.

This is the same as pressing F3, repeat the operation to return to normal viewing mode.



5 Tools Overview

146

This menu lets you carry out all selection operations, draw lines, edit lines, make measurements and copying properties between objects.

	Selection	
	Drawing	+
	Change	+
k	Measurements	Ctrl+K
2	Copy Properties	
	Repeat last operation	F2

The available options are:

- Make selections
- Draw lines
- Edit lines
- Measure on screen
- Copy Properties

5.1 Tools - Selection

Use this option to select any object (for example, line, part, punch).


This is the sa	me as clicking	the Selection	buti	ton in the Tools toolbar
$\triangleright \ \ \subset$	95 <mark>U</mark>	ŷ 🖞 🔨	2.	

- 1. select Selection from the **Tools** menu. The cursor will be displayed k
- 2. select the object using the left mouse button. The selected object will highlight.


5.1.1 Tools - Selection - Point selection

It is possible to select an individual point or points on a line. This is required in some operations.

- 1. Select **Selection** from the **Tools** menu. The cursor will be displayed
- 2. Select the line with the point(s) to be selected.



3. Hold down the **Shift** key and click the left mouse button to make a polygon around the required points. As the points are selected they highlight.



4. Releasing the **Shift** key will finish the polygon creation; these points can now be edited.

5.2 Tools - Drawing

This menu contains all the options for drawing lines.

Ç	Line	Ctrl+L
G	Bezier	
\odot	Circle	
	Rectangle	
С	Arc	
ا ل	Text	
Ţ	Text (True Type)	
<i>∧</i> ∿°	Sawtooth	
+42	Axis	
\oplus	Marks	
	Punches	
	Symmetric Shape	es 🕨 🕨
	Grid	
6	Continue Line	

To quickly visualize some information about any object, simply press the I key and hover on the object (to deactivate this query mode just press the I again).

Line 34 [card_spline_c2 (3 Pts)] Length: 74.84 mm Width: 67.85 mm Height: 20.94 mm Offset (33) Distance to master: 8.00 mm

For detailed information do a right click over the object and select Properties.

In the properties window there are two tabs:

• Properties:

Properties Dependences		
ID	22	
Name	_inside topline	
Color	АЛТО	
Style		
Width	0 mm	
Layer	Design	
Side	Inside	
Linked to 3D		
Properties	Offsets	

ID: Number representing the object identity.

Name: Is possible to assign a name to the object.

Color: Select the line color, from the available options.

Style: Choose the style for the line.

Width: Allows to change the line width in mm.

Layer: Select the object layer, press button [...] to see the available layers.

Side: Allows to define in what side the object should be. Press button [...] to choose the side.

Linked to 3D: Check to link with 3D.

Properties: Allows to add properties to the object.

• Dependencies:

150 MindCAD 2D Design & Engineering

Properties	Dependences	
Parts:		
M0 M1		
Dependen		
Paralell (1	Master): Partner	: 49686

In this tab is visible if the object as dependencies, this is, if is used in parts, if as parallels associated, etc.

Is also possible to quick select the dependent parts. The matching part will be visible on the model.

Back Pt Cente Mein Front/P back Ginth Pt	Properties Dependences Parts: M0 M1 C Dependences: Paralell (Master): Partner: 49686
	OK Cancel Apply Help

x

5.2.1 Tools - Drawing - Line

Use this option to draw lines. By default the lines will be curved, but corners can be added at any time, using the **Tool Options** menu.

This is the same as clicking the **Create Line** G button in the **Tools** toolbar or pressing **Ctrl+L**.




5.2.1.1 Creating a curved line


1. Select Line from the Drawing options of the Tools Menu. The cursor will be displayed as a




2. Insert points using the left mouse button.




- 3. It's possible to insert the line points in a specific places, based in X,Y coordinates. To do that, press the key **A** or do a right click and select **Add point** from the contextual menu.
 - a. Insert the ${\bf X}$ coordinates and press ${\bf Enter}.$



b. Insert the Y coordinates, press Enter.



c. The point will be placed.



4. To finish the line, do double click with the left mouse button, or press **Enter**, or do a right click and select **Finish** from the contextual menu.


Finish	Enter
Cancel	
Add Corner	
Remove Last F	Point
Add point	А

5.2.1.2 Creating a curved line with corner

1. Select Line from the Drawing options of the Tools menu. The cursor will be displayed as a




2. Insert points using the left mouse button.



- 3. To add a corner,
 - § Press Ctrl as you add the point
 - § With the cursor in the correct position for the point, press the right mouse button and select **Add Corner** from the menu

Finish	Enter
Cancel	
Add Corner	
Remove Last Poi	nt
Add point	А

4. Continue drawing the line. The corner option can be used repeatedly in any line to create a zigzag effect.




5. To finish the line either double click the left mouse button or press the right mouse button and select **Finish** from the menu

5.2.1.3 Creating a closed curve

- 1. Select Line from the Drawing options of the Tools menu. The cursor will be displayed as a
 - _____ cross
- 2. Select Closed Curve from the Tool Options toolbar.

Tool Options			
Create Line			
Line type			
Curve 🔘			
Closed curv	e		
ine 🔘 🔘	© Line		
Closed line			
Continuous	drawing		
Restrict leng	gth 0		
Side:	Not defined		

3. Insert points using the left mouse button.



4. To finish the line either double click the left mouse button or press the right mouse button and select **Finish** from the menu

Finish	Enter
Cancel	
Add Corner	
Remove Last Poi	int
Add point	А

• Tips

1. Use as few points as you can to create your desired curve.

2. Avoid drawing across the centre line if possible, as these lines will not be give the desired result when 'mirrored'

3. Use the snap functions in the Constrain menu to keep lines (points) accurate.

5.2.1.4 Line editing

You can edit a line in the following ways:

- Move a point
- Add/Delete a point
- Changing a Corner/Curve point
- Dragging/Scaling/Rotating lines/Mirror


5.2.1.4.1 Line editing - Move point

k

1. Select Object selection from the Selection options on the Tools menu. The cursor will be


displayed

2. Select the line to be edited. As you approach a point on the selected line the cursor will change to a pen.




- 3. Press and hold down the left mouse button, as you move the mouse the point will move.
- 4. To finish the edit release the left mouse button.
- 5. Repeat on any point on the selected line.


5.2.1.4.2 Line editing - Select points



- 2. Hold down the CTRL button, approach the point to be selected the cursor will change to a pen ($\sqrt{2}$).
- 3. Select the desired point.



- 4. The selected points are shown in blue.
- 5. It's possible to edit just the selected points. For example rotate just the select points.



5.2.1.4.3 Line editing - Add/Delete point

To add a point to a line

1. Select Object Selection from the Selection options on the Tools menu. The cursor will be k

displayed

- 2. Select the line to be edited.
- 3. Hold down the Shift key, approach the selected line between original points, the cursor will change to a pen with a plus sign.
- 4. Press the left mouse button to add a point at this position.

To delete a point from a line

1. Select **Object Selection** from the **Selection** options on the **Tools** menu. The cursor will be

displayed

- 2. Select the line to be edited.
- 3. Hold down the **Shift** key, approach the point to be deleted, the cursor will change to a pen with a minus sign.
- 4. Press the left mouse button to delete the point.

5.2.1.4.4 Line editing - Changing a Corner/Curve point

1. Select Object Selection from the Selection options on the Tools menu. The cursor will be

displayed

- 2. Select the line to be edited.
- 3. Move the cursor towards the point to be edited and get the pen cursor displayed.
- 4. Press the right mouse button and select the Change corner/curve option from the menu.

5	Undo	Ctrl+Z
	Delete	Del
X	Cut	Ctrl+X
	Сору	Ctrl+C
Ê	Paste	Ctrl+V
	Mirror	
	Arrow Mover	nent Step
	Change	F12
	Properties	Alt+Enter

5.2.1.4.5 Line editing - Dragging/Scaling/Rotating lines/Mirror

Full information on **Drag Constrain** is in the **Edit** chapter.

Click here for information on **Drag Constrain**.

1. Select Object Selection from the Selection options of the Tools Menu. The cursor will be

displayed

2. Select the line(s) to be edited.

158 MindCAD 2D Design & Engineering

- 3. With the pointed cursor displayed ^k, click the left mouse button and hold it down to drag the lines.
- 4. Hold down the Ctrl button and click the right mouse button to select the rotation point.
- 5. Click the left mouse button to start rotation. Move the cursor to rotate the line(s)
- 6. Click the left mouse button to finish.

For further information, see Edit - Drag Constrain.

5.2.1.4.6 Line editing - Virtual Mirror

It is possible to do a mirror of selected geometry without having to select an axis. This is provided for a quicker interaction. To do this, the operator should:

- 1. select line(s) to mirror.
- 2. press the right mouse button and select the Mirror option from the menu.

The lines are mirrored around a virtual axis, automatically defined, based on the selected geometry.


5.2.1.4.7 Line editing - Arrow Movement Step

This tool allows the user to configure the value in mm that the line will be moved, each time, when moving the line with the keyboard arrows.

- 1. Select a line.
- 2. Do a right click and select Arrow Movement step.


5	Undo	Ctrl+Z
	Delete	Del
X	Cut	Ctrl+X
	Сору	Ctrl+C
Ê	Paste	Ctrl+V
	Mirror	
	Arrow Mov	ement Step 🔓
	Change	F12
	Properties	Alt+Enter

3. Insert the step value.



4. Now when the keyboard arrows are pressed the line will move 1 mm in the direction of the arrow pressed.

5.2.2 Tools - Drawing - Bezier




With this type of line it's possible to have better control the direction of tangents to each of the control points of the line.


1. Select **Bezier Line** from the **Tools - Drawing** Menu. The cursor will be displayed as a cross.



2. Insert points using the left mouse button, by default the simple point will be corner points.



3. To control the point tangent during the line creation, press down the left mouse button and move de mouse until have the desired curvature.




4. To finish the line either double click the left mouse button or press the right mouse button and select finish from the menu


Finish	Enter
Cancel	
Remove Last Po	oint

5.2.2.1 Bezier Line Editing


- 1. Select the button **Select** from the **Tools** toolbar. The cursor will be displayed
- 2. Select the line to be edited. As you approach a point on the selected line the cursor will change to a pen.




3. Select the point to edit. Doing a left click over it. Now the tangent is visible.




4. Press and hold down the left mouse button, as you move the mouse the point tangent will move.



5. Hold down the **Shift** key and hold down the left mouse button, as you move the mouse the direction of tangents will match.



Hold down the Shift+Ctrl key and hold down the left mouse button, as you move the mouse. You can see that now its possible to change one side length without interfering with the length of the other side.



7. Repeat on any point on the selected line.

5.2.3 Tools - Drawing - Circle

Use this option to draw circles freehand or by a given radius

5.2.3.1 Drawing - Circle - Free

1. Select Circle from the Drawing options of the Tools menu. The cursor will be displayed as a

	_
cross	

2. Select Free from the Circle options

Circle			
Free	•		
🔘 By ra	adius		
Radius (mm):		12	· · · · · · · · · · · · · · · · · · ·

3. Insert a point using the left mouse button. This point will be the centre of the circle. As you move

the mouse the size of the circle will change.

4. Press the left mouse button again to complete the operation.

5.2.3.2 Drawing - Circle - By radius

1. Select Circle from the Drawing options of the Tools menu. The cursor will be displayed as a

cross I

2. Select By radius from the Circle options


Circle			
Free			
By ratio	adius		
Radiu	us (mm):	12	· · · · · · · · · · · · · · · · · · ·

- 3. Select the radius required using the up/down arrows.
- 4. Insert a point(s) using the left mouse button. This point(s) will be the centre of the circle of your specified radius.

5.2.3.3 Circle Properties

To access the circle properties:

- Select the circle;
- Do a right click over it;
- And select Properties from the contextual menu.



The **Properties** window will be displayed.


	×		
Properties Dependen	ces		
ID	52		
Name			
Color	AUTO		
Style			
Width	0 mm		
Fill color 🛛 🖃			
Color	0,0,0		
Layer	Design		
Side	Not defined		
Linked to 3D			
Properties			
Center	795.00; 898.00		
Radius	25.12 mm		
OK Cancel Apply Help			

164 MindCAD 2D Design & Engineering


ID: Number representing the Circle identity.

Name: Is possible to assign a name to the circle.

Color: Select the circle line color, from the available options.




Style: Choose the style for the line.



Width: Allows to change the line width in mm.

Fill Color: Check to fill in the closed shape.



Color: Select the color to fill the shape.



Layer: Select the circle layer, press button [...] to see the available layers.

Layer	Design		
Side	Not defined	1	Lining
Linked to 3D			Construction
Properties		✓	Design

Side: Allows to define in what side the circle should be. Press button [...] to choose the side.

Side	Not defined		
Linked to 3D		~	Not defined
Properties			Inside
Center	859.00; 969.50		Outside

Linked to 3D: Check to link with 3D.

Properties: Allows to add properties to the circle.

Properties	Punches	N
Center	. 🗌 Text	45
Radius	_ Offsets	

Center: Allows to change the circle center to a different position. **Radius:** Allows to change the circle radius.

Dependencies Tab:

Properties	Dependences			
Parts:				
M1				
Dependen Paralell (M	ces: laster): Partner:	72		
	OK	Cancel	Apply	Help

In this tab is visible if the shape as dependencies, this is, if is used in parts, if as parallels associated, etc.

5.2.4 Tools - Drawing - Rectangle

Use this option to draw rectangles.

1. Select **Rectangle** from the **Drawing** options of the **Tools** menu . The cursor will be

displayed as a cross


2. Insert a point using the left mouse button. Move the mouse to give the diagonally opposite corner of rectangle and press the left mouse button again to complete the operation.

Rectangle			
 Free By dimm 	ensions		
		10	
Width (m	m):	10	-
Height (n	nm):	10	 T
A			

3. If By dimensions, enter the Width and Height in mm.


And select the rectangle alignment.

The corner or edge of the rectangle specified by the alignment option is placed at the position selected by the left mouse button click.









After its creation, the rectangle has 3 control points for enhanced shape control. The original corner control handle, given on creation, will control width and height of the rectangle, maintaining angle directions. The third control point will allow you to rotate and change the width and height, using the first given handle has the anchor handle.

5.2.4.1 Rectangle Properties

To access the rectangle properties:

- · Select the rectangle;
- Do a right click over it;
- And select Properties from the contextual menu.

	5	Undo	Alt+Backspace
5	ľ	Delete	Delete
	X	Cut	Shift+Delete
		Сору	Ctrl+C
	Ê	Paste	Ctrl+V
		Mirror	
		Arrow Mov	rement Step
		Change	F12
	Ĩ	Properties	ß


The Properties window will be displayed.

		×
Properties Dependen	ices	
ID	58	
Name		
Color	лито	
Style		
Width	0 mm	
Fill color 🛛 🖃		
Color	0,0,0	
Layer	Design	
Side	Not defined	
Linked to 3D		
Properties		
Center	1056.00; 885.25	
Width	39 mm	
Height	37.5 mm 🗸	•
ОК	Cancel Apply Help	

ID: Number representing the Rectangle identity.

Name: Is possible to assign a name to the rectangle.

Color: Select the rectangle line color, from the available options.



Style: Choose the style for the line.

Style		
Width		
Fill color	Đ	
Layer		Design

Width: Allows to change the line width in mm.

Fill Color: Check to fill in the closed shape.

Fill color	<u> </u>	
Color	⁵ 128,0,64	

Color: Select the color to fill the shape.



Layer: Select the rectangle layer, press button [...] to see the available layers.

Layer	Design		
Side	Not defined		Lining
Linked to 3D			Construction
Properties		~	Design

Side: Allows to define in what side the rectangle should be. Press button [...] to choose the side.

Side	Not defined		
Linked to 3D		~	Not defined
Properties			Inside
Center	859.00; 969.50		Outside

Linked to 3D: Check to link with 3D.

Properties: Allows to add properties to the rectangle.

Properties	_ Dunches	
Center	: Text	45
Radius	Offsets	_

Center: Allows to change the rectangle center to a different position.

Width: Allows to change the rectangle width.

Height: Allows to change the rectangle height.

Dependencies Tab:

170 MindCAD 2D Design & Engineering

Properties Dependences	
Parts:	
M1	
Dependences:	
Paralell (Master): Partner: 72	
OK Cancel Apply	Help

In this tab is visible if the shape as dependencies, this is, if is used in parts, if as parallels associated, etc.

5.2.5 Tools - Drawing - Arc

This option lets you arcs. An arc is the arc of a circle. If you draw three points using the normal line drawing it will not be an arc.

1. Select Arc from the Drawing options of the Tools menu Note. The cursor will be displayed as a

cross ^{____}

- 2. Insert three points to define the arc.
- 3. Repeat if required.

5.2.6 Tools - Drawing - Text

This option lets you add text to your shell (not parts).

1. Select **Text** from the **Drawing** options of the **Tools** menu **T**. The cursor will be displayed as

		_
а	cross	

2. Insert the start point for your text with the left mouse button. A dialogue box is displayed

Text:	MindCAD	
Height:	10	mm
ОК)	Cancel

- 3. Insert Text and size of text (Height)
- 4. Select OK

5.2.7 Tools - Drawing - Text (True Type)


This option lets you add text to your shell (not parts).

- 1. Select Text (True type) from the **Drawing** options of the **Tools** menu I. The cursor will be displayed as a cross
- 2. Insert the start point for your text with the left mouse button. A dialogue box is displayed

	Text
Text:	
Font:	Times New Roman 🗸 🖪 🗾
Size (mm): ScaleX: Orientation: Horizontal alignment:	10
Vertical alignment:	First line V OK Cancel

- 3. Insert Text, Font type, Size of text, scaleX, spacing between the letters, the orientation, the horizontal and vertical alignment, and the shear to be applied.
- 4. Select OK

In alternative it's possible to add text to a line.




- 2. Select Text (True type) from the **Drawing** options of the **Tools** menu
- 3. A dialogue box is displayed

	Text
Text:	
Font:	Times New Roman V B
Size (mm):	10
ScaleX:	1 Spacing: 1
Orientation:	0 ▲ Shear: 0 ▲
Horizontal alignment:	Left 🗸
Vertical alignment:	First line 🗸
	OK Cancel

5. Insert Text, Font type, Size of text and select OK.



6. Now the text will move when the line is moved.



5.2.7.1 Text (True Type) Edition

1. Select the text to edit.



2. In the Tool Options, select the **Text** tab.

То	ool Options
Properties Te	ext Grading
Text:	
Mind	
Font: Times New R	oman 🗸 B Z
Size (mm):	15 💂
ScaleX:	1
Orientation:	0
Spacing:	1
Shear:	0
Alignment	
Horizontal	Vertical
Left	✓ First line ✓

3. Any option you change will be automatically applied to the selected text.

	Tool Options		
	Properties Text Grading		

	Text:		
	Mind		
Mind	Font:		
	Vivaldi v BZ		
	Size (mm):		
	ScaleX: 1		
	Orientation: 0		
	Spacing: 1		
	Shear: 0		
	- Alignment Horizontal Vertical		
	Left Vertical		


5.2.8 Tools - Drawing - Sawtooth

Use this option to draw sawtooth lines (zigzag lines).

1. Select **Sawtooth Line** from the **Drawing** options of the **Tools** menu . The cursor will be

displayed as a cross

2. Insert points using the left mouse button.



While drawing the line you can press the right mouse button and use the options to change the sawtooth line width and depth

Finish	Enter
Remove Last Pt	
Sawtooth line wid	th
Sawtooth line dep	th

3. To finish the line either double click the left mouse button or press the right mouse button and select **Finish** from the menu

5.2.8.1 Tools - Drawing - Sawtooth - Edit


Use this option to edit sawtooth lines (zigzag lines).

Select Sawtooth line, using the right mouse button and select change or pressing F12.

Sawtooth		
Туре]
Triangular		
Rectangular		
 Ellipse Arc 		
O User defined		
Balance:		
Roundness:		
By width	10	
Start width (mm):	10	- - 0
End width (mm):	10	÷
O By number		
Number:	10	*
Start depth (mm):	10	
End depth (mm):	10	• ©
Centered		•
Start distance (mm):	0	*
	-	ම
End distance (mm):	0	* *
Reverse		
Rounded		
 Morph geometry 		
On Section	-	
Initial margin (mm):	0	÷
Final margin (mm):	0	▲ ⁽⁶⁹⁾
		_


- 1. Select Sawtooth Type (Triangular, Rectangular, Elipse, Arc or User defined).
- 2. Define the **Balance** and **Roundness** by moving the slide in the bar.
- 3. By Width (enter the start and end width), or By Number (enter the number).
- 4. Enter the Start and End Depth.
- 5. Centered Enable or disable centered sawtooth.
- 6. Start and End Distance Insert the original start and end line distance.
- 7. Reverse Enable or disable reverse sawtooth.
- 8. Rounded Enable or disable rounded sawtooth.
- 9. Morph geometry Enable or disable the morph geometry.

Morph option Off: Morph option On:




10.On Section - Enable or disable sawtooth on section.11.Initial and Final Margin - Insert the initial and final margin value for on section sawtooths.


5.2.8.2 Tools - Drawing - Sawtooth over Line



2. Select Sawtooth Line from the Drawing options of the Tools menu




3. Now the sawtooth will move when the line is moved.




When a sawtooth is drawn over a line it's possible to set a section.


- 1. Draw 3 lines, one for apply the sawtooth and two to define the section.
- 2. Select the line to apply the sawtooth and apply it.



3. Go to the sawtooth tool options, select the option **On Section** and select the lines that will compose the section.



4. When one of the lines is moved the section is automatically updated.




Note: Now that the sawtooth is created over a line, its possible to add punches, those will be synchronized with the sawtooth. For further information go to Punches over Sawtooth.

5.2.9 Tools - Drawing - Axis

This option lets you to draw axis lines. An axis is used to mirror lines across, or for grading. There is always an axis down the centre of the shoe. If you do not have at least one axis, you will not be able to grade your shell.

1. Select **Axis** from the **Drawing** options of the **Tools** menu

2. Insert two points to define the axis.




5.2.10 Tools - Drawing - Marks

This option lets you to draw marks.

- 1. Select **Marks** from the **Drawing** options of the **Tools** menu . The cursor will be displayed as a cross
- 2. Insert a points(s) using the left mouse button.

Marks (small crosses) are added to each point input. Marks can be used as reference points to either check or construct other lines.






5.2.11 Tools - Drawing - Punches

This option lets you to draw punches.

1. Select **Punches** from the **Drawing** options of the **Tools** menu . The cursor will be displayed

2. Select a punch shape in the punches tab of the **Parts/Library** bar using the left mouse button.



3. Insert one or more points using the left mouse button, a punch shape will be added for each point.

5.2.12 Tools - Drawing - Symmetric Shapes

This option enables the creation of symmetric shapes. Several base geometry types are available:




as a cross

- Circle
- Polygon

5.2.12.1 Tools - Drawing - Symmetric Shape - Ellipse

This option allows to draw punches with the help of a symmetry base.

1. Select symmetric shape Polygon.




- 2. Select free or by radius.
- 3. If select By Radius, enter radius value.

Tool Options	
Shape	
 Free By radius 	
Radius (mm):	20 💌 10 💌

5.2.12.2 Tools - Drawing - Symmetric Shape - Circle


This option allows to draw punches with the help of a symmetry base.

1. Select symmetric shape circle.




- 2. Enable or disable Mirror
- 3. Enter axis number.






4. Draw the punch



5.2.12.3 Tools - Drawing - Symmetric Shape - Polygon

This option allows to draw punches with the help of a symmetry base.

1. Select symmetric shape Polygon.



- 2. Select free or by radius.
- 3. If select By Radius, enter radius value and sides number.

Tool Options				
Shape				
 Free By ratio 				
	us (mm):		23	
	().			_
Sides				
Sides			7	×


5.2.13 Tools - Drawing - Grid

This option allow to create a grid and apply punches and markers to it, that can be subsequently added to a part. This function allows the user to quickly create patterns on parts.

1. Select the Grid option from tools - drawing menu.

2. Select the points to create the grid. The grid can be created based in three or four point.

Draw the first point: Second point: And third point:



- 3. It's possible to click and drag any point to a different location.
- 4. In the Tool Option there are available several parameters:

Tool Options		
Grid		
Line count:	5 🔺 5 🔺	
Add punches		
Properties:	Properties -	
Add markers		
Width (mm):	1	
Margin (mm):	2	
Properties:	Properties -	

Line count - Insert the grid, number of rows and columns.

Add punches - Enable/disable to add punches automatically at the intersection of the grid.


Add markers- Enable/disable to add markers automatically at the intersection of the grid. It's possible to define the markers Width (mm) and Margin (mm).

In the image bellow is an example:

	Tool Options
	Grid
	Line count: 7 🔺 6 🔺
	✓ Add punches
2 NON 22 32 NON -	Properties:
	✓ Add markers
	Width (mm):
N. 66 28 2.0	Margin (mm):
N. 0 N. 0	Properties: Properties -
	

5. Do a right click and the contextual menu will appear:

186 MindCAD 2D Design & Engineering



Finish - Select to finish the grid edition.

Cancel - Select to delete the grind and leave the tool.

Reset - Select to delete the actual grid, and draw other.

Set count - Allow to define the grid number of rows and columns, also available in the tool option panel.

Create Markers - Enable/disable to add markers automatically at the intersection of the grid. Also available in the tool option panel.

Markers width - Allows to define the markers width, also available in the tool option panel.

Markers margin - Allows to define the markers margins, also available in the tool option panel.

Create punches - Enable/disable to add punches automatically at the intersection of the grid. Also available in the tool option panel.

5.2.14 Tools - Drawing - Continue line

This option lets you add points to the ends of lines.

- 1. Select the line to be continued.
- 2. Select **Continue Line** from the **Drawing** options of the **Tools** menu

displayed as a cross

- 3. Add points to the end of the line using the left mouse button.
- 4. If you want to add points to the other end of the line, use **Tools Change Reverse** to reverse the direction of the line.

5.3 Tools - Change

These options let you manipulate the lines that have been drawn.

5	Rotate	Ctrl+1	
ج ر – ا	Scale	Ctrl+2	
d,	Move	Ctrl+3	
Ļ	Cut Line		
	Break Line by Angle		
$\frac{ }{ }$	Trim		
	Trim (Hide)		
	Hide Part of a Line	End	
	Reverse		
~	Extend/Shorten Line		
60	Explode		
\$ →]	Explode Smooth		
{ خ	Filter		
} →}	Join Lines	Ctrl+J	
	Join Lines by Distance		
Ĵ.	Swap Lines	Ctrl+I	
	Bounding Box		
	Center point		
] 3(Wrap Lines		
	Average lines		
	Spring adjustment		
	Convert	•	

5.3.1 Tools - Change - Rotate

Use this option to rotate lines.

1. Select the line(s) to be rotated.

2. Select Rotate from the Change options of the Tools menu

or pressing CTRL+1.


3. Enter the rotation point using the left mouse button.

Tool Options	
Rotate	
 Free By angle 	
Angle (deg):	133.07
Space to rotate:	Ali

Use the Space to rotate option to determine which points of the selected lines will be affected

All space (right and left)	All the handles will be affected
Right space	Only handles to the right of the rotation point will be affected
Left space	Only handles to the left of the rotation point will be affected

4. Enter another point near the rotation point using the left mouse button, and then move the mouse.



As the mouse is moved, the lines are rotated and the angle of rotation is displayed.

5. Click the left mouse button to finish.

5.3.2 Tools - Change - Scale

Use this option to scale lines.


- 1. Select the line(s) to be scaled.
- 2. Select Scale from the Change options of the Tools menu unit or pressing CTRL+2.
- 3. In the tool option it's possible to choose between **Scale Free** or **By bounding box**.

Scale				
• Free				
O By bounding box				
Lengtł	n <mark>(</mark> mm):	0	*	
Width	(mm):	0	*	
Lengtł	ר (%):	0	×	
Width	(%):	0	*	

Scale Free

1. Using the left mouse button select a region to scale by clicking on two diagonally opposite corners.

When you select the second point a number of values will be displayed.



2. Move the mouse to change the scale;



The values change as follows:

H:1.3313x 10.6329mm - This is the new scale horizontally in this case 33.13% bigger and 10.6329mm longer

V:1.1138x 3.7022mm - This is the new scale vertically in this case 11.38% bigger and 3.7022mm longer


3. Click the left mouse button to finish.

Finish	Ente
Cancel	

By bounding box

Scale			
⊖ Free			
🖲 By b	ounding box		
Len	gth (mm):	0	▲ ▼
Wid	th (mm):	0	•
Len	gth (%):	100	•
Wid	th (%):	100	•

1. Selecting the option **By bounding box**, an bounding box is automatically created around the selected area.



- 2. To edit the scale, you can either change the values displayed in the tool options, length and width in mm or in percentage Or use the mouse cursor to change the bounding box dimensions by click and drag in one of the points.
- 3. Click the left mouse button to finish.


Finish	Enter
Cancel	

5.3.3 Tools - Change - Move

Use this option to move lines


Free

- 1. Select the line(s) to be moved.
- 2. Select **Move** from the **Change** options of the **Tools** menu **Lun** or pressing **CTRL+3**.
- 3. Using the left mouse button select the point from which the move operation starts.
- 4. Move the mouse from the original position to new position.



By Values

- 1. Select the line(s) to be moved.
- 2. Select **Move** from the **Change** options of the **Tools** menu.
- 3. Enter the values (XY, angle and distance).



5.3.4 Tools - Change - Cut Line

Use this option to cut lines.

This is the same as clicking the **Cut Line** button in the **Tools** toolbar or pressing the **Home** key.




To cut a line,

- 1. Select the line to be cut.
- 2. Select Cut Line from the Change options of the Tools menu. The cursor is displayed on the line.
- 3. Move the cursor to the required position.
- 4. Click the left mouse button to cut the line.


5.3.5 Tools - Change - Break Line By Angle

Use this tool to break the lines points that have an angle inferior to user-defined value.


1. Select the line to apply the break line by angle tool.



- 2. Select Break Line By Angle from the Change options of the Tools menu.
- 3. A text box will appear, insert the angle and press **ENTER** key to apply.




4. The line will break where the angle is equal or higher to the inserted one (in this examples 90°).




5.3.6 Tools - Change - Trim

194

Use this option to **Trim** lines.




a. To trim **several lines** at the same time, click and drag to define the trim area and select more then one line simultaneously.



b. Release the right mouse button and the trim will be applied.



5. To finish the trim press enter or do a right click and and select finish from the contextual menu.




Finish - Allows to leave the tool and apply the changes.

Cancel - Allows to close the tool and cancel the changes.

Mode - Allows to select the trim tool mode, between the normal behavior and the reversed.

Trim Normal - The selected side of
the line will the erased.Trim Reversed - The selected side of
the line will be the one to stay.




196

5.3.7 Tools - Change - Trim (Hide)

Use this option to Trim (Hide) lines.

This is the same as clicking the Trim (Hide) button in the Tools toolbar.

- 1. Select the main line.
- 2. Select the side of a line where the trim will be applied
- 3. The other side of the lines after the main line will be hidden.



4. To finish the trim press enter or do a right click and and select finish from the contextual menu.


Finish	Enter
Cancel	Esc
Mode	•

Finish - Allows to leave the tool and apply the changes.

Cancel - Allows to close the tool and cancel the changes.

Mode - Allows to select the trim tool mode, between the normal behavior and the reversed.

Trim Normal - The selected side of
the line will the hidden.Trim Reversed - The opposite side of
the line will be the one to be hidden.




5.3.8 Tools - Change - Hide Part of a Line

Use this option to hide part of a line. The line will still be held in its original state, but parts of the line can be removed from display.

This is the same as pressing the **END** key.


To hide part of a line,

- 1. Select the line to be partly hidden.
- 2. Select **Hide Part of a line** from the **Change** options of the **Tools** menu. The cursor is displayed on the line and both ends will be highlighted.



3. Move the cursor to either end and drag it along the line holding down the left mouse button.

The ends of the line will be hidden



198 MindCAD 2D Design & Engineering


4. In alternative, do a right click over either line ends and select one of the options, Set distance from source or Set distance from opposite.



Set distance from source - Insert the distance from the original line point.

	Set distance	×
Distance		µ0.00
	ОК	Cancel

Press ok, and the change will be applied.



If the distance value is 0, the point will return to is original place.

	Set distance	×
Distance		47.93
	ОК	Cancel

This value is the distance between the two line ends. Change the distance and press **Ok** to apply the changes.

Set distance from opposite - Insert the distance between the selected point and other line end.

5. To **Finish** press the middle mouse button, **Esc** or do a right click and select finish from the contextual menu.



When the line is selected, all the original line is highlighted. You can use the option again to restore hidden sections of lines.

5.3.9 Tools - Change - Reverse

Use this option to change the direction of a line.


- 1. Select the line to be reversed.
- 2. Select Reverse from the Change options of the Tools menu.

5.3.10 Tools - Change - Extend/Shorten Line

Use this option to extend or shorten a line.

There are two ways to use this tool:

- a) By selecting the Line first:
 - 1. Select the line to be extended/shortened.
 - 2. Select Extend/shorten Line from the Change options of the Tools menu



Extend Line	×
By distance	10.00
O By percentage	10.00
ОК	Cancel

To extend the line insert a positive value and click OK.

To shorten the line insert a negative value and click OK.

Both ends of the line will be extended/shortened by the given value.

----0

b) Selecting the tool first:

1. Select Extend/shorten Line from the Change options of the Tools menu



2. Do a right click and the contextual menu will appear.

	Finish	Enter
	Set Value	v
•	By Value	Q
	By Percentage	w
	By Point	E
	Next point	Barra de espaços

3. Its possible to extend/shorten the line By Value, By percentage or By point.

a. By Value (shortcut key Q):

- Select the option $\ensuremath{\text{Set Value}}$ from the contextual menu or press $\ensuremath{\text{V}}$, to define the value in mm.

A dialogue box is displayed. Insert the value in mm and press Ok.

	Extension percentage	×
Percentage	[15.00
	ок	Cancel

To extend the line insert a positive value and click OK.

To shorten the line insert a negative value and click OK.

- Place the mouse cursor over one of the line ends and do a left click over to apply the extension.




- The tool will remain active, doing more right clicks over the line ends the same change will be applied.



b. By Percentage (shortcut key W)

- Select the option ${\bf Set \ Value}$ from the contextual menu or press ${\bf V},$ to define the percentage value.

A dialogue box is displayed. Insert the percentage value and press Ok.



To extend the line insert a positive value and click OK.

To shorten the line insert a negative value and click OK.

- Place the mouse cursor over one of the line ends and do a left click over to apply the extension.



- This tool will increment x% based in the line length, this means that for every new click the length incremented will be higher than the previous.



c. By Point (shortcut key E):

- Place the mouse cursor over one of the line ends and do a left click over it to start.



- The distance is controlled by the mouse cursor. Do other right click to fix the fix extension position.



- The tool will remain active, its possible to repeat the process as many times as desired.




An example of using this option to short the line:



5.3.11 Tools - Change - Explode

Use this option to change a curved line into a polyline (several connected straight segments).

1. Select the line to be exploded.



starting over a point on the line, simply redraw the line to get the desired smooth aspect. This tool allow for line smoothing only on a specific section of the base line or at its full extent.
 to finalize just press ENTER or right-click and choose the intended action.

Finish ENTE	ER
Cancel E	sc
Smooth complete line	S

5.3.13 Tools - Change - Filter

Use this option to filter points lines. The number of points in a line can be dramatically reduced with this command.

1. Select the line to be smoothed.

|→|

The line will be highlighted and the **Tool Options** toolbar will look as follows:

2. Select Filter from the Change options of the Tools menu

Tool Options		
Smooth		
Amount		
		0.250
Results		
Points:	12/12 100.00%	
Max. error:	0.00 mm	
Total error:	0.00 mm	
L		

3. Move the slider with the left mouse button.

Clicking the left mouse button will update the menu and highlight the line in its current geometry.

As the slider is moved the number of points in the line, the **Max error** (maximum distance from the original line) and the **Total error** (total distance from the original line) are displayed.

4. Click the middle mouse button to complete the command.

5.3.14 Tools - Change - Join Lines

Use this option to join separate lines into one line.

1. Select **Join Lines** from the **Change** options of the **Tools** menu **D** or pressing **CTRL+J**. The menu will be displayed as a box on the lines



- 2. Select the end of the first line to be joined using the left mouse button
- 3. Select the start of the next line using the left mouse button




The lines will be joined




4. Continue to select other lines to be joined or press the Esc button to finish.

5.3.15 Tools - Change - Join Lines by Distance


Use this tool to join the all the lines that are an user-defined distance from each other. 1. Select the **lines** to apply the tool.



- 2. Select Join Lines by Distance tool from the Change options of the Tools menu.
- 3. A text box will appear, insert the distance and press ENTER key to apply.




4. All the lines that are an user-defined distance or less, from each other are joined.




5.3.16 Tools - Change - Swap Lines

Use this option to swap lines. If a line has several dependant lines (for example, mirrors or offsets) swap line can be used to replace the original line and keep all the dependencies.




- 1. In the diagram above the selected line has been used to create the other lines (offsets and mirrors)
- 2. Draw a new line to carry the dependencies (in black) and select the original line.



206 MindCAD 2D Design & Engineering

- 3. Select Swap Lines from the Change options of the Tools menu.
- 4. Select the new line (in black)




The dependencies are carried onto the new line.

5.3.17 Tools - Change - Bounding Box

Use this option to draw a bounding box around selected lines.


- 1. Select the line(s) to be used to define the bounding box.
- 2. Select Bounding Box from the Change options of the Tools menu.
 - A box will be drawn around the selected lines




5.3.18 Tools - Change - Center point

This tool allow to create a punch in the center of the selected group of lines.

1. Select a group of lines.




- 2. Select the Center point option (Tools Change Center point)
- 3. A punch will appear in the center of the selected lines.




5.3.19 Tools - Change - Wrap Lines

Use this option to wrap lines around another line. This option is usually used when constructing moccasin patterns.


1. Select the line(s) to be wrapped. Do a Pre-Copy to keep the original lines position.




- 2. Select Wrap Lines from the Change options of the Tools menu
- 3. Select the guide line, this line is used as the base line to wrap the other lines around




4. Select the line to wrap around the base line.




6. Use the Red pointer to scale the wrapped lines, just click and drag.



7. A scale length factor (% / mm) could be used to extend or decrease the wrapped lines lengths.



8. Do a right click and select Finish from the contextual menu to apply the changes.



Tip: Learn how to apply punches dependent on other punches.


Doing a right click several option are available in the contextual menu:

	Finish	Enter
	Cancel	
~	Both directions	
	Forward direction	n
	Backward directi	on


Finish - Select to apply the changes and close the tool.
Cancel - Select to cancel the changes e close the tool.
Both directions - The warp lines direction will be for both forward and backward.
Forward direction - The warp lines direction will be forward.
Backward direction - The warp lines direction will be backward.

5.3.20 Tools - Change - Average lines


This tool allow to do a quick modification of two lines to establish a mean plus blend region effect.




- 2. Go to Tool Change Average lines
- 3. It will appear two new lines between the two selected




4. It's possible to control the new lines approximation using the handles in it. Just click over it and drag.



5. When the lines are in the correct possition, do a rigth click and select finish.



6. The new lines will replace the old ones




Note: To keep the old lines to, you just need to do a **pre-copy** before start the Average lines process.


5.3.21 Tools - Change - Spring Adjustment

Semi-automatic springing process allowing for a coordinated rotation and offsetting of parts.


1. To start the springing process, select the part lines to apply the deformation.




- 2. Then active the option Spring Adjustment from the Tools Change menu.
- 3. Select the center line.




4. Do a right click to open the context menu.



- 5. Select the Add path option.
- 6. Select the line or lines to apply the path.




7. It's possible to select just a part of the line, just keep the left mouse button pressed over the line and drag, from the start point until the last point you want to select.



8. Now doing a right click, select the deformation to be applied, from the contextual menu.


Rotate:

Using the left mouse button, click to select the mouse, select the rotation axis, by doing a click with the left mouse button.




Then start moving the cursor and the lines will rotate, the angle of rotation is displayed.

Do left click with the mouse button to stop the rotation.




Move:

Using the left mouse button, click in the point from which the move operation starts. In the Tool Options that point is shown as point 0,0.




Move the mouse cursor and the lines will move.


In the Tool Options you can see the distances from Axis-aligned and Relative to center line.



In alternative it's possible to change the distance directly in the Tool Option.



9. Doing a right click and the contextual menu will open.



Finish - Allows to accept the changes and close the tool.

Cancel - Allows to close the tool and cancel the changes.

Undo - Allows to undo the last change.

Redo - Allows to redo the last change.

Reset position - Allows to reset the lines position.

Previous position - Allows to move the lines to the previous position.

Rotate - Allows to rotate the lines.


Move - Allows to move the lines.

Add path - Allows to add a path.


Restart - Allows to restart all the process. Will be asked to select central line.

5.3.21.1 Spring Adjustment - Complete process


1. To start the springing process, select the part lines to apply the deformation.




- 2. With the lines selected, go to Tools Change and select the option Spring Adjustment.
- 3. Select the center line (axis).




4. When selected will appear with a different color.



5. Do a right click and select the **Add path** from the context menu, or press **E** key. Now select the line(s) section to apply the path.




6. Do a right click and select the **Rotate** from the context menu or press **R** key. Apply the required rotation.




7. Do a right click and select the Add path from the context menu, or press E key. Now select the


lines sections to apply the path.




8. Do a right click and select the **Rotate** from the context menu or press **R** key. Apply the required rotation.




9. Do a right click and select the **Add path** from the context menu, or press **E** key. Now select the line section to apply the path.



10.Do a right click and select the **Move** from the context menu or press **T** key. Apply the required movement.




11. Do a right click and select the **Reset Position** from the context menu or press **0** key. The original lines will return to his original position. Do a right click and select the **Finish** from the context menu or press **ENTER** to exit the tool e apply the changes.



5.3.22 Tools - Change - Convert

These options allow you to convert lines to sawtooth lines, curves or to axis lines.



5.3.22.1 Tools - Change - Convert - to Sawtooth

Use this option to change the selected line to a sawtooth line

5.3.22.2 Tools - Change - Convert - to Axis

Use this option to change the selected line to an axis **I** or pressing **CTRL+G**.

5.3.22.3 Tools - Change - Convert - to Curve

Use this option to change the selected line to a curved line

5.3.22.4 Tools - Change - Convert - to Bezier

Use this option to change the selected line to a $\ensuremath{\text{Bezier}}$ line.

5.3.22.5 Tools - Change - Convert - From Axis to Line

Use this option to change the selected axis to a line or pressing CTRL+G.

5.4 Tools - Measurements

This option let you take measurements on the screen, either in a straight line or along lines, select

Measurements from the tools menu 2 or press CTRL+K.


5.4.1 Free measurements

1. Select **Measurements** from the **Tools** Menu ^{Mail} or pressing **CTRL+K**. The cursor will be displayed



- 2. Move the cursor to the position you want to measure from and press the left mouse button.
- 3. Move the cursor to the point you want to measure to.

226 MindCAD 2D Design & Engineering




The measurement is displayed in the menu


4. Click the left mouse button to take another measurement or the Esc button to finish the command.

5.4.2 Measurement along lines


1. Select **Measurements** from the **Tools** Menu Menu Menu Menu Topics or pressing **CTRL+K**. The cursor is displayed



2. Click the right mouse button to display the following menu




3. Select Mode and another menu is displayed



4. Select Along or press X. The cursor will be displayed




5. Move the cursor close to the line you want to measure. As you get close, the line will highlight.



6. Click the left mouse button at the point on the line you want to measure from.

7. Move the mouse to the position you want to measure to.



The measurement is displayed in the menu.

8. Click the left mouse button to take another measurement or the Esc button to finish.

5.4.3 Using markers when measuring


When measuring it is possible to leave markers on the points used for taking the measurements. The following example was also used in the Free measurements section.

To add markers when measuring,

- 1. enter the first point using the left mouse button, but do not enter the second point using the left hand mouse button
- 2. when in the correct position to measure to, click the right mouse button and select **Place Markers**

The start, end and mark now points will be left as markers on the shell.

228 MindCAD 2D Design & Engineering




5.4.4 Measure fixed length

Measuring over a line from a point plus a distance value is possible using the fixed length option.

1. select line to measure.

Finish	ENTER
Mode	•
Marks	+
Measure fix	ed length 🕨

2. right click and under Measure fixed length select Measure fixed length option.




3. on the Tool Options toolbar, under Mode select Along.

Tool Options	
Measure	
Mode	
Straight	
Along	
Fixed length	
Length (mm):	10 🊔
🔲 Add mark at start	
🔲 Add mark at end	
Length:	

- 4. Fixed Length enable or disable fixed length measuring.
- 5. enter the Length.
- 6. Add mark at start enable or disable the placement of a mark at start of the measured segment.

7. Add mark at end - enable or disable the placement of a mark at the end of the measured segment.



5.5 Tools - Copy Properties

Use this option to copy properties between objects.

- 1. select the object from which the properties are being copied.
- 2. Select **Copy Properties** from the **Tools** *loop* toolbar.

3. Press **Ctrl** and left mouse button to copy all the properties of the object. To select individual properties press the right mouse button and select the required properties from the menu using the left mouse button.

	Finish	ENTER
~	Line Colo	ur
•	Line Style	
•	Layer	
•	Properties	;
•	Grading C	enter
•	Group Gra	ading
•	Grading R	estriction
•	Subgradir	ng
•	Fittings	

The cursor will be displayed

* when the properties have been copied.


4. Move the cursor to the objects to have these properties applied to them and press the left mouse button.

5.6 Repeat last operation


230

This tool allows you to retrieval the last used tool. Select **Repeat last operation** from the **Tools** menu or press **F2**.


1. Draw a line and select it.



2. Go to Tools - Change - Cut Line and cut de line.



3. After that the cut tool is disable.



4. If you want to used the same tool again press **F2** and the tool is turn back on.



6 Operations Overview

This menu lets you

- Create new lines from existing geometry using, the offset, perpendicular and mirror options.
- Apply markers and punches to any line.

\bigcirc	Links On/Off	
Ĵ,	Offset	F5
	Multiple Offset	Ctrl+F5
	Perpendicular	+
	Mirror	+
\$	Markers	F6
S	Punches	F9
	Notches	
5	Corner	F7
	Distance dependence	
	Stitch line	
SSS	Bisection	
S	Anchor	
.	Release	
	Release All	

6.1 Operations - Links On/Off

This option lets you keep a reference to the original line if required.

This is the same as clicking the Links 🕛 button in the Tools toolbar



If **Links** is *ON* when a line is created by mirroring or offsetting, any future edits of the original line will also be reflected in the linked lines.

If Links is OFF when an operation is carried out, the newly created line is independent.

6.2 Operations - Offset

This option allows you to offset lines.

This is the same as clicking the **Offset** button in the **Tools** toolbar or pressing **F5**.

To set a shortcut for commonly used offsets, including distance and offset type,

1. Set the **Distance**, right click on a blank shortcut box at the top of the menu, enter the name for this kind of offset and select **OK**

Press right button to configure	this shortcut
Distance: 8 mm ↔ Offset type:]
Type name (×
8 OK Cancel	•

2. This shortcut is now available for future use.

Offset
*mm *
Distance: ◎ mm ↔ ○ Offset type:
 Approximated and Free
Correct and Frozen
Offset Original Line

3. More space is available for more quick access buttons by pressing the 4 triangle button.

234	MindCAD 2D Design & Engineering

Offset	

6.2.1 Creating an offset to a line

1. Select the line to be offset.

2. Select Offset from the Operations menu. The Tool Options toolbar displays appropriate options.

Offset
*mm *
Distance: Offset type: Approximated and Free Correct and Frozen Offset Original Line

- 3. Select the **Distance** for the offset using one of the following methods:
 - § by clicking in the up/down arrows;
 - § by typing in a value;
 - § dragging the point with the cursor using the left mouse button.

Distance: 8 🚔 mm

- It's also set the distance point by point, by selecting the point with the left mouse button, then doing a right click and selecting **Distance** from the contextual menu or press key **D**.

Offset distance	X
	30.0 🔺

Press Enter and the distance will be applied to the selected point.

- 4. Select the direction of the offset by using the **change side** button , or pressing **S** or doing a right click and select **Swap side** from the contextual menu.
- 5. Select the type of offset by selecting an Offset type.

Offset type: Approximated and Free Correct and Frozen Offset Original Line

Approximate and Free - The original points are offset

Correct and Frozen - Extra points are added to the offset to keep the line parallel to the original. **Offset Original Line** - Make change to original line instead of creating a new one.

- 6. If you want a constant offset click the middle mouse button to finish.
- 7. If you want to add different values at different points, select the points using the left mouse button

Enter a new value or position with the cursor.

- 8. Repeat for as many points as required
- 9. To finish click in the middle button or do a right click and select **Finish** from the context menu.

Finish	Enter
Distance	D
Swap side	S
Clear distance	С
Select next point	х
Select previous point	Z
Configuration	•

Finish - Apply the changes and close the tool.

Distance - Set a specific distance to the selected line points.


Swap side - Change the side of the offset

Clear distance - If the point as applied a manual distance, it release the point and the automatic distance will be applied.

If a point has applied a manual distance, it will be connected by a line to the main point:




To release this constrain, you can either do a right click and select Clear distance from the contextual menu, or approach the line with the mouse cursor and "Cut the line". When the mouse cursor is placed over the connector line, will change and appear like a scissors, just do a right click to release the point.




6.2.2 Changing the values of the offset


1. Select the offset line



2. Click the right mouse button and select Change or press F12



3. Select the point to edit



- 4. Change values, using one of the methods described in Creating an offset to a line
- 5. Click the middle mouse button to finish.


6.2.3 Offset - Grading

This option allows control offsets behavior while grading.

1. Select the offset and edit it, by doing a right click and select **Change** from the contextual menu or pressing **F12** key.

2. Select Grading tab from the tool option.

238 MindCAD 2D Design & Engineerin




- 3. To **Add** new grading groups press the button
- 4. Insert the minim and the maxim size, and press Ok.

New grading rule					
Min: Max:					
Size:	18	~	22	~	
Fitting: V V					
OK Cancel					

- 5. The new grading will be added to the list.
- 6. Now configure a new value for the offset, and it will be applied to the grading rule.

Tool Options
Offset Grading
Default 13 - 17 18 - 22




6.3 Multiple Offset


This option allows you to multiple offset lines in a single operation.

Create offset	×
Number of offsets	
Offset type: Approximated and Free Correct and Frozen	
Distance Fixed Variable Mouse defined	
OK Cancel	


Number of offsets - Enter the number of offsets.



• Correct and Frozen - Extra points are added to the offset to keep the line parallel to the original.



Distance - Chose between Fixed, Variable or Mouse Defined.



6.4 Operations - Perpendicular

This lets you draw a line or axis perpendicular (at 90 degrees) to another line or axis.



6.4.1 Operations - Perpendicular - Line

This lets you construct a line perpendicular to another line.


- 1. Select the line from which you want to construct the perpendicular line.
- 2. Select Line from the **Perpendicular** options of the **Operations** menu . The cursor will be displayed on the line



3. Move the cursor to a position which gives the correct start point for the line and the correct distance from the line.



4. Press the left mouse button to create the line. Its possible to create several lines.




5. Do a right click and several options are available in the contextual menu.

	Finish I	Enter
	Cancel	
	Both sides	
	Set distance	
~	Automatic distance	e


Finish - This option applies the changes and close the tool.

Cancel - This option cancel the changes and close the tool.

Both sides - If this option is active, the perpendicular will be applied in both sides of the line.



Set Distance - Insert the perpendicular line length.



Automatic distance - The distance is controlled by the mouse position.

Note: The perpendicular will be dependent from the master line. To break the dependency to the master line go to Operations - Release.

244

6.4.2 Operations - Perpendicular - Axis

This lets you construct perpendicular to another line.


- 1. Select the line from which you want to construct the perpendicular axis.
- 2. Select **Axis** from the **Perpendicular** options of the **Operations** Menu



3. Move the cursor to a position which gives the correct start point for the axis and the correct distance from the line.



4. Press the left mouse button to create the axis. Its possible to create several axis.




5. Do a right click and several options are available in the contextual menu.

	Finish	Enter
	Cancel	
	Both sides	
	Set distance	
~	Automatic distanc	e


Finish - This option applies the changes and close the tool.

Cancel - This option cancel the changes and close the tool.

Both sides - If this option is active, the perpendicular will be applied in both sides of the line.



Set Distance - Insert the perpendicular axis length.



Automatic distance - The distance is controlled by the mouse position.


Note: The perpendicular will be dependent from the master line. To break the dependency to the master line go to Operations - Release.

246


6.4.3 Operations - Perpendicular - Circle

This lets you construct perpendicular to another line.


- 1. Select the line from which you want to construct the perpendicular circle.
- 2. Select **Circle** from the **Perpendicular** options of the **Operations** Menu. The cursor will be displayed on the line



1. Move the cursor to a position which gives the correct start point for the circle and the correct distance from the line.




2. Press the left mouse button to create the circle. Its possible to create several circles.




5. Do a right click and several options are available in the contextual menu.

	Finish	Enter
	Cancel	
	Both sides	
	Set distance	
~	Automatic distar	ice

Finish - This option applies the changes and close the tool.Cancel - This option cancel the changes and close the tool.Set Distance - Insert the circle diameter.





Note: The perpendicular will be dependent from the master line. To break the dependency to the master line go to Operations - Release.

6.5 Operations - Mirror

This lets you mirror or reflect lines about an axis.

<u></u> .	Activate Axis	Ctrl+E
m	About axis	Ctrl+M

6.5.1 Operations - Mirror - Activate Axis

To mirror any lines you must have an active axis. This option activates an axis, making it the current axis.

1. Select an axis.

2. Select **Activate Axis** from the **Mirror** options of the **Operations** menu **D**. The axis will be highlighted and displayed as a dotted line.

This is the same as pressing Ctrl+E

6.5.2 Operations - Mirror - About axis

This mirrors any selected lines about the activated axis.

1. Select line(s) to be mirrored.

248

2. Select Mirror - To the other side from the Operations menu.

This is the same as clicking the **Mirror** button in the **Tools** toolbar or pressing **CTRL+M**.



6.6 Operations - Markers

This lets you draw markers over existing lines. Markers are small closed lines or bubbles that can be

added to parts later. Selecting this option \checkmark is the same as pressing F6.

- 1. Select the line to have markers applied.
- 2. Select Markers from the Operations menu.
- 3. Define the markers with pairs of clicks using the left mouse button.

The **Tool Options** toolbar displays appropriate options.

Tool Options				
Marker				
+ <u></u> + M2 M1 M0.6				

Width (mm):	2 🔺			
Distance to line (mm):	1 🔹 🔿			
Side:	$\bigcirc \bigcirc \bigcirc \bigcirc$			
Side indicator size:	-0.5			
✓ On Section Initial margin (mm):	0			
Final margin (mm):	0			
Automatic				
Max. Length (mm):	50 🌻			
Gap (mm):	10 🜩			

- 4. Use the options in the upper portion of the toolbar to adjust the size and position of your markers. Width
 - Distance to line
 - Side (or pressing S)
 - Side indicator size
 - On Section (initial margin and final margin)
 - Automatic (max. length and gap)
- 5. Press the middle mouse button to complete the command.
- To set a shortcut for commonly used Markers, including width, distance to line, side and others values,
- 1. Click on a blank shortcut box at the top of the menu

250 MindCAD 2D Design & Engineering

Press right button to cor	figure this shortcut			

Width (mm):	1.2			
Distance to line (mm):	0 🚔 🔿			
Side:	000			
Side indicator size:	0			
On Section Initial margin (mm):	0			
Final margin (mm):	0			
Automatic Max. Length (mm):	50			
Gap (mm):	10 📫			
Tool Optior	ns			
Marker				

Width (mm):	1.2			
Type name				
1.2	~			
1.2	✓ Cancel			
	Cancel			
ок				
OK				
OK Initial margin (mm): Final margin (mm):				

2. Type in a name and select OK. This shortcut is now available for future use.

- -

Tool Options				
Marker				
M 1.2				
TTTT				
Width (mm):	1.2 📮			
Distance to line (mm):	0 🔷 🗢			
Side:	$\odot \circ \circ$			
Side indicator size:	0			
On Section	0			
Initial margin (mm):				
Final margin (mm):	0			
Automatic				
Max. Length (mm):	50 🌲			
Gap (mm):	10 🔹			

3. more space is available for more quick access buttons by pressing the 4 triangles button.

Marker			
 M 1.2			

6.7 Operations - Punches

This lets you space punches on lines and offset from them. Selecting this option is the same as pressing F9.

1. Select the line to apply the punches.

2. Select **Punches** from the **Operations** menu . The **Tool Options** toolbar displays appropriate options.

Punches Grading	

Punches type	10 📥
By number	
 By distance 	
Start distance (mm)	20.3 🔹 🚱
End distance (mm)	20.3 🔹
O Dependent on other p	unches
Distance to master line	
Start margin	0
End margin	0
O Manual O Auto	matic
Align directions	0
On section	
On intersection	
Oblique	
Number of lines:	1
Line separation:	5 🔶 😝
Final line separation:	5 -
Start scale	1
End scale	1
Mirror distribution	
Shape	
• •	ත

Using the options on the toolbar, select the way the punches should be applied:

By number - Equally space the input number of punches along the line

By distance - Space punches at the specified distance along the line.

Start and End distance - Place a punch at an input distance from the start and end of the line. This options are available when the **By distance** option is used.

Dependent on other punches - Copy the number of punches from another punch line;

Distance to master line - Offsets the punches parallel to the line (use the arrows to swap the offset

to the other side or press S)

Start Margin - Distance from the start of the line to place the first punch.

End Margin - Distance from the end of the line to place the last punch.

Manual - If ON, the punches can be edited manually after they have been applied to the line

Automatic - If ON, the values defined in other options are used to space the punches

Align directions / Rotation - If *ON*, align the punches to the geometry of the line. If *OFF*, apply the punches in their original XY positions. Or enter rotation value.

On section - If *ON*, the punches are placed on a section of a line. The section is defined by selecting two lines that intersect the line.

On intersection - If *ON*, one punch is placed on an intersection. Use the cursor to select the intersecting line.

Oblique on intersection - If *ON*, one punch is placed oblique to an intersection. Use the cursor to select the intersecting line.

Number of lines - Enter the number of punch lines.

Line Separation - Distance between lines.

Final Line Separation - Distance between final lines.

Start Scale - Insert the first punch size. The punches in between will scale based in the start and end scale size.

End Scale - Insert the last punch size. The punches in between will scale based in the start and end scale size.

Mirror distribution -This option is available when the **Distance to master line** is being used. If this option is active the punches will be mirrored to the other side of the line.

Shape - The software is supplied with two standard punch shapes, a cross and a circle. By default the punched are drawn as crosses.





- Select to transform the punch shape into a cross.

- Select to transform the punch form into a circle, as you select this option, a text box will appear to insert the Circle Radius;



- Insert the Circle Radius and press Enter to

apply.

⁴ - Select to access the **Punch Generator Window**.

3. Click the middle mouse button to finish

To edit the spacing of the punches,

- 1. Select the punches
- 2. Click the right mouse button
- 3. Select Change or press F12
- To set a shortcut for commonly used Punches, including punches type (by number, by distance or dependent on other punches), distance to master line, start margin, end margin, on section, on intersection or oblique on intersection.
- 1. Right click on a blank shortcut box at the top of the toolbar.

Tool Options	
Press right button to configure this sh	ortcut
Punches type	
O By number 10 🚔	
O By distance 27.77 ▲	
Final distance 0	
Dependent on other punches	
Distance to master line 6	

2. The contextual menu will appear, select configure.

Apply	,
Confi	gure
Сору	
Paste	
Delete	e

3. Type in a name and select OK.

Tool Optic	ons
Punches	

Punches type	
O By number	10 💂
O By distance	27.77
Final distance	0
Type nam	ne 💌
Double	~
ОК	Cancel

4. Type shortcut key and select OK.

Tool Optic	ons
Punches	
TTT	
Punches type	
O By number	10 💂
O By distance	27.77
Final distance	0
Type shortcu	it key 🛛 🗙
D	
D	¥
ок	Cancel

5. This shortcut is now available for future use.

Double (D)	
Punch type: Depend	dent
Distance to master Initial margin: 12 r Final margin: 10 m Automatic Align directions	nm
Punches type	
O By number	10 🜲
O By distance	27.77
Final distance	0
Dependent on other president	unches
Distance to master line	8 🔹 🗢

6. More space is available for more quick access buttons by pressing the 4 triangles button.

Punches		
<u> </u>		

Operations Overview 257

6.7.1 Punch Generator

The punch generator is available in the Punches distribution Tool Options.

Punches Grading	
Punches type	
By number	10 🚔
O By distance	
Start distance (mm)	20.3
End distance (mm)	20.3 🜲
O Dependent on other p	unches
Distance to master line	0 -
Start margin	0
End margin	0
O Manual Auto	matic
✓ Align directions	0
On section On intersection Oblique	
Number of lines:	1
Line separation:	5
Final line separation:	5
Start scale	1
End scale	1
Mirror distribution	
Shape	
• 0	40

Select the Punch Generator button and the **Generate punch** window will appear.

250	
200	

					Gene	rate punch				
) *										
Туре	Distance	Angle	Size	Edges	Phase	Property	1		Î	
	•						 	 	 	
							- d	 	 	
									_	




- Press to start creating a new punch.



- Press to open a punch file.

H - Press to save the punch to file.


1. To start a new punch creation, select the punch Type:



2. As you select the Type, a preview will be visible

)))					Gene	rate punch				
Type Polygon -	Distance	Angle	Size	Edges	Phase	Property				
-										
							 	~		
								$ \mathbf{P} $		
							 			•
								(Ж	Cancel

3. Set the available parameters for the selected punch type.




4. Insert as many Types as required.

1,50 ÷	40 ÷	0,50 ÷	3 🔹	-20 🌲		
	0 🗘	0.60 *				
		0,50 +				
1,50 🌩	-270 🔶					
1,50 🌲	-40 🌲	0,50 🌲	3 📫	20 🔶		
0,00 🜲	-20 🔹		6 📫	0 📫		
				-40 🌲		
1,50 🌲			3 🛟	40 🌲		
1,50 🌲						
2,00 🔹	-180 🌲	0,50 🔶				
	0,00 ÷ 1,50 ÷	0,00 1,50 1,50 1,50 220 1,50 1,50 0,0	0,00 ▲ -20 ▲ 1,00 ▲ 1,50 ▲ 140 ▲ 0,50 ▲ 1,50 ▲ 220 ▲ 0,50 ▲ 1,50 ▲ 220 ▲ 0,50 ▲ 1,50 ▲ -90 ▲ ▲	$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	$\begin{array}{c ccccccccccccccccccccccccccccccccccc$

5. To easily identify witch type is shown in the preview, just move the mouse cursor over the preview and the Type and parameters will be highlighted.

Туре		Distance	Angle	Size	Edges	Phase	Property	1	1		Î	Ĩ
Polygon	-	1,50 🌲	40 🌲	0,50 🌲	3 🌲	-20 🌲		 			ļ	
Circle	-	2,00 🗘	0 🌲	0,50 🌻								
Point	-	1,50 🔶	-270 🛟									
Polygon	-	1,50 🗘	-40 🌲	0,50 🌲	3 🗘	20 🌲		 			······	
Polygon	-	0,00 🗘	-20 🌲	1,00 🌲	6 🛟	0 🌲		 	$\Delta -$	$\neg \Delta$		
Polygon	-	1,50 🌲	140 🌲	0,50 🌲	3 🌲	-40 🌲			7	- Tot		
Polygon	-	1,50 🌲	220 🌲	0,50 🌲	3 🛟	40 🌲		ΤΨ		A	2	
Point	-	1,50 🌲	-90 🌲					 	\vee	- V	••	
Circle	-	2,00 🗘	-180 🌲	0,50 🌲				 				
	-											

6. The opposite is also applied, clique over the Type and the preview will be highlighted.



7. When finished, press Ok and the punch will be applied.

6.7.2 Add/Delete Punch Shapes from the library

The software is supplied with two standard punch shapes:

- a cross
- a circle.

You can add any new shape of punch to the library.

1. Draw a new punch shape



2. Select the lines

- 3. Select the Punches tab of the Parts/Library toolbar.
- 4. Click Add.

Parts/Library		д	x
Parts Pun	ches		
⊕ Punch1	Circle 1mm	Add Remove	

A dialogue box is displayed

Obje	ect name
new punch	ОК
	Cancel

5. Type in the name for the new punch shape and click **OK**. The new punch will be displayed ready for selection

Parts/Library	д 🗙
Parts Punches	
	Add
new punche Punch1 Circle 1mm	Remove


To **delete** a punch shape from the library:

- 1. Select the punch shape from the **Punches** tab of the **Parts/Library** toolbar.
- 2. Click in the **Remove** button.
- 3. A confirmation message appear, select **Yes** to delete the punch or **No** to cancel.


6.7.3 Punches dependent on other punches

This allows to copy the number of punches from another punch line; use the cursor to select the line.

1. Select the line to apply the punches.



2. Select **Punches** from the Operation menu or press **F9**. The last punch configuration used will be automatically applied to the line.




3. From the option **Dependent on other punches** from the Tool Option.


Tool Options						
Punches Grading						

Punches type						
By number 68						
O By distance 5.36 ♣						
Final distance 0						
Dependent on other pu	unches					
Distance to master line	3 🔹 🔿					

4. Select the master punches.



5. The new punches will be automatically rearranged based on the masters.




If the masters change, the dependent will follow.

Note: Usually the punches applied to the tongue are set **by distance**, then the punches applied to the vamp are dependent to the tongue punches.


6.7.4 Multiple Punch Lines

This option allows creating many punch lines.

1. Draw the line, select the line and the desired type of punches.



2. Go to operation menu and select punches.




3. The next tool box will be displayed.


Punches Grading							
Punches type							
By number	10 🌲						
By distance	7.91						
Final distance	0						
O Dependent on other punches							
Distance to master line 0 🔹 🔿							
Start margin	0						
End margin	0						
O Manual O Auto	matic						
✓ Align directions	0						
On section							
On intersection							
Oblique							
Number of lines:	1 📥						
Line separation:	5						
Final line separation:	5						
Mirror distribution							
Start scale	1						
End scale	1						

4. Change the option **Number of lines** and use the option **Line separation** to adjust the lines distance.

Number of lines:	4
Line separation:	14
Final line separation:	14 🚔 🔤







6.7.5 Punches over sawtooth

When a sawtooth is created over a line, its possible to add punches, those will be synchronized with the sawtooth.

1. Create a sawtooth over line.

2. With the sawtooth selected, go to **Punches** from the **Operations** menu \checkmark or press F9.

L

3. It's possible to rearrange the Punches distribution, on the tool options.

Punches Grading						
Punches type By number	8					
By distance						
Start distance (mm)	10.33 🌲					
End distance (mm)	10.33 📤 😁					
O Dependent on other p	unches					
Distance to master line						
Start margin	0					
End margin	0					
Manual Automatic						
✓ Align directions	0					
On section						
Oblique						
Number of lines:	1					
Line separation:						
Final line separation:	C					
Start scale	1					
End scale	1					
Mirror distribution						
Shape						
	40					

4. Use the Sawtooth position slide bar to change the punches position, based on the sawtooth.



5. Its also possible to center the punches, increasing the distance from master line.





6. Now if you change the sawtooth properties, the punches will follow.



In the example was changes the option sawtooth by number property, from 8 to 3.

6.7.6 Editing Punches Distribution

1. Select the punch distribution



2. In the tool option is now visible the punches Properties.

Tool Options						
Properties						
Name:						
Color:	AUTO -					
Style:	—					
Layer:)esign 🔹					
Properties:	Properties -					
<u> </u>	Property-1					
	Punches					
	Punches-1					
	Punches-2					


3. It's possible to insert a name, change the colour, the style, the layer and assign one or more properties, to add new property go to **Preferences**, **Default Properties** tab.

6.8 Operations - Notches


This toll is used to create or change a notches line.

To create a new notches line:

1. Select the line that will be the master of the notches.



2. Select Notches from the Operations menu. The notches will be applied.




3. In the tool option are several options available.

Notches							
							
Width	Height						
5 📥	5 📮						
5	5						
J 🔻	J 🔻						
Curvature	Margins						
Shape							
Oblique							
Distribution	Distribution						
By number	10 🜩						
O By distance	10 🌲						
Final distance	10						
Delimiters							
None							
On intersection							
On section							
Dependencies							
Width	Height						
Curvature	Margins						
Shape							
Count Positioning	Spacing						
◇ R							

4. To finish, press **Enter** or do a right click and select Finish from the contextual menu.

Finish	Enter
Controlling Note	hes 🕨
Swap side	s
Reset	R
Configuration	•


To change notches position (one by one):




6.9 Operations - Corner

Use this option to create a corner. This is mainly to control the corners shape of parts.

1. Select the lines, when you select the last line, the corner will be created.



2. In the Tool Options there are available several parameters:




Type - Select the corner type between Arc, Bezier, Chamfer or Smooth Radius - Input radius for the first line in mm.

Radius 2 - Input radius for the second line in mm.

Smooth - If the selected type of corner is Smooth, select the smooth factor.

Trim masters - Enable\Disable the trim masters option.




3. To finish press Enter or right click and select finish from the contextual menu.



6.10 Operations - Distance Dependence


This tool control line position based on extracted length property from other elements.

1. Select Distance Dependence tool from the Operations menu.




Note: If the tool is not available please deselect the lines.


- 2. To create a distance line dependence based on a value inserted manually, select the first option (**Distance**) on the **Tool options** introduce the distance (mm) in the text box.
- 3. Select the master line (the created line will be equal to this one).



4. Select the base line. (the new line will appear X mm away from the master line, following the base line)




5. The new line (green line) it was created 50mm from the master line.



6. To create a distance line dependence based on the length of other line, select the option

Dependent from the Tool options.

7. Select the master line.




10. If we increment the "line to measure distance", the distance between the green line and the master line will be automatically readjusted.




11. To create a distance line dependence based on a section, select the option Dependent from the

Section.


12.Select the master line.




14.Select the line to measure distance.



15.Select the first section delimiter.




17. The new section is created equal to the main section, if the main section is changed, the new section will be readjusted, to ensure that the both sections have exactly the same length.



6.11 Operations - Stitch line

This tool allows automatic insertion of corners while stitching multiple lines to ensure smooth transitions.

- 1. To create a Stitch line, active the Stitch line option from the menu Operations.
- 2. Select the lines to stitch together. One click over each line successively.



3. Select finish from the contextual menu.

Finish	Enter
Cancel	Esc
Remove Last Pt	Backspace
Chamfer on next	с
Bezier on next	В
Arc on next	А

Finish - Allows to finish the stitch line.

Cancel - Allows to cancel the stitch line.

Remove Last Pt - Allows to remove the added last point.


Chamfer on next - Select this option to apply the type of corner Chamfer in the intersection between the selected line and the next selected line.

Select the first line and active the Chamfer on next option, from the contextual menu or

Insert the Radius(before). press Enter, then insert the Radius (after) and press Enter selected radius.

Select the other line and the corner will be created with the

pressing letter C in the keyboard. again.




Bezier on next - Select this option to apply the type of corner Bezier in the intersection between the selected line and the next selected line.

Select the first line and active the **Bezier on next** option, from press Enter, then insert the letter B in the keyboard.

Insert the Radius(before), the contextual menu or pressing Radius (after) and press Enter selected radius. again.

Select the other line and the corner will be created with the




Arc on next - Select this option to apply the type of corner Arc in the intersection between the selected line and the next selected line.

Select the first line and active Insert the Radius and press the Arc on next option, from the Enter.

contextual menu or pressing letter A in the keyboard.


Select the other line and the corner will be created with the selected radius.



6.12 Operations - Bisection

This option allows you to construct a lines that bisects two other lines.


1. Select the lines.




- 2. Select **Bisection** from the **Operations** menu.
- 3. Insert the number of lines and click OK.




4. The lines will be created




5. Select one line, do a right click and select Change




6. Now its possible to add new parameters to the line and change is position.



7. To add a new parameter press Shift, and do a left click over the desired place.




8. It's possible to change the parameter and is position by draging the red points over the lines (middle red point to change position, top red point to change parameter), or by change the values in the **Tool Options**.




6.13 Operations - Anchor

This option creates a link between lines of different geometry; it also holds them constant relative to each other when graded.


1. Select the anchor line.



- 2. Select Anchor from the Operations menu.
- 3. Select the master line



The anchor line turns yellow. Any edits done to the master line are reflected in the anchor line



4. The lines will remain a constant distance apart when graded (the length will grade).

6.14 Operations - Release

This option breaks the dependency to a master line.

1. Select dependent line(s).

2. Select **Release** from the **Operations** menu . Any dependency to a master line is broken.

6.15 Operations - Release All

This option breaks the dependency to a master line and lines dependent from the current line.


- 1. Select dependent line(s).
- 2. Select **Release All** from the **Operations** menu. Any dependency to a master line or slave lines are broken.



7 Parts Overview

286

This menu lets you create parts and add holes, punches and generally edit parts.




7.1 Parts - Create Part

This menu lets you to choose between create a part by contour or by on click.



Note:Enhanced part collection tool with information about last collected parts.



7.1.1 Parts - Create Part - By Contour

This is the same as clicking the **Create Part** button on the **Parts** toolbar or pressing **Ctrl+T**



- Parts can be created very quickly using hot keys and menu options.
- Treatments (for example, overlaps, folds and seams) can be added during part creation.
- If you work on a folded shell, centre notches can be added automatically.
- Inside indicators can be applied automatically.
- The software is designed to have some built in intelligence. So, if a treatment is applied to one side of a folded part that joins the other side of the part, the other side will have the same treatment applied to it.


The following examples show you how to create some of the common types of parts.

- Creating a part with no treatments or folds
- Creating an unfolded mirrored part
- Creating an unfolded non-mirrored part
- Creating parts with treatments
- Tips and Tricks


288

7.1.1.1 Creating a part with no treatments or folds


- 1. Select By contour from Create Part in the Parts menu.
- 2. Start to define the boundary of the part using the left mouse button.



3. Continue to select lines going in the same direction. The direction is not important as long as within each part you move in the same direction.








4. Click the right mouse button to display the following menu.


Finish	Enter
Finish (close with reflectio	n)
Remove Last	
Switch Side	
Auto insert corner on next	line
Side Indicator on Next	
None on next	
Overlap on next	
Fold on next	
Trim on next	
Seam on next	

5. Select **Finish** to complete the part. The part can also be finished by pressing the **Enter** key or clicking the middle mouse button.

The part will be highlighted.




- **Remove Last** If you make a mistake when selecting a line, use this option to undo the last selection. You can then pick another line.
- 6. The part will be added to the Parts/Library Bar.




Note: The part will always go to the first empty space in the parts toolbar.

7.1.1.2 Creating an unfolded mirrored part (1 axis)

- 1. Select By contour from Create Part in the Parts menu.
- 2. start to define the boundary of the part using the left mouse button. Select the first line next to the current axis that will be used to unfold the part.



3. continue to select lines going in the same direction.




292

4. click the right mouse button to display the following menu.

Finish	Enter
Finish (close with reflect	ion)
Remove Last	
Switch Side	
Auto insert corner on ne	ext line
Side Indicator on Next	
None on next	
Overlap on next	
Fold on next	
Trim on next	
Seam on next	

5. select Finish (close part with reflection) to complete the part. The part will be highlighted.




7.1.1.3 Creating an unfolded mirrored part (2 axis)


Example in how to create an unfolded mirrored part with two axis.

1. Select **By contour** from **Create Part** in the **Parts** menu.

2. Start to define the boundary of the part using the left mouse button. Select the first line next to the current axis that will be used to unfold the part.



3. Continue to select lines going in the same direction.




4. Click in the right mouse button to display the contextual menu. And select the option **Switch Side**.


		Parts Overview	295
Finish	Enter	L	
Finish (close with reflect	tion)		
Remove Last			
Switch Side			
Auto insert corner on n	ext line		
Side Indicator on Next			
None on next			
Overlap on next			
Fold on next			
Trim on next			

5. Continue to select lines going for the other side.


Seam on next




6. Place the cursor over second axis and press CTRL+E to active it.




7. Click the right mouse button to display the following menu.



8. Continue to select lines going for the other side.




9. Place the cursor over the other axis and press CTRL+E to active it.



10.Click the right mouse button to display the following menu.

Finish	Enter
Finish (close with reflection)	
Remove Last	
Switch Side	
Auto insert corner on next li	ne
Side Indicator on Next	
None on next	
Overlap on next	
Fold on next	
Trim on next	
Seam on next	


11.Continue to select lines going for the other side.



12. Click the right mouse button to display the contextual menu.


Finish	Enter
Finish (close with reflection)	
Remove Last	
Switch Side	
Auto insert corner on next li	ine
Side Indicator on Next	
None on next	
Overlap on next	
Fold on next	
Trim on next	
Seam on next	

13.Select **Finish** to complete the part. The part will be highlighted.




7.1.1.4 Creating an unfolded non-mirrored part

- 1. Select By contour from Create Part in the Parts menu.
- 2. Start to define the boundary of the part using the left mouse button. Select the first line next to the current axis which will be used to unfold the part.



3. Continue to select lines going in the same direction.




4. Use the right mouse button to display this context menu and select Switch Side

Finish	Enter
Finish (close with reflection	on)
Remove Last	
Switch Side	
Auto insert corner on nex	t line
Side Indicator on Next	
None on next	
Overlap on next	
Fold on next	
Trim on next	
Seam on next	


(Tip: If you press the ${\bf Ctrl}$ key when selecting the next point you do not need to select ${\bf Switch}$ Side from the menu.)

Now you can pick the other side of the part (in reverse order).

5. Continue picking the boundary








6. Click the right mouse button to display the following context menu.

Finish	Enter
Finish (close with reflecti	on)
Remove Last	
Switch Side	
Auto insert corner on ne	d line
Side Indicator on Next	
None on next	
Overlap on next	
Fold on next	
Trim on next	
Seam on next	

7. Click **Finish** to complete the part. The part can also be finished by pressing the **Enter** key or clicking the middle mouse button.

The part will be highlighted.




7.1.1.5 Creating parts with treatments

- 1. Select By contour from Create Part in the Parts menu.
- 2. click the right mouse button when in the graphics window and select Fold on next


Finish	Enter
Finish (close with reflection))
Remove Last	
Switch Side	
Auto insert corner on next li	ine
Side Indicator on Next	
None on next	
Overlap on next	
Fold on next	
Trim on next	
Seam on next	

This is the same as pressings the hot key ${\bf F}$


3. start to define the boundary of the part using the left mouse button.




4. before selecting the next line, click the right mouse button and select Overlap on next




This is the same as pressing the hot key ${\bf O}$




6. select the gross feather edge. If you don't select a treatment, no offset or corner will be applied (The default is zero offset and an ordinary corner).



7. before selecting the heel curve click the right mouse button and select Seam on next



This is the same as pressing hot key ${\boldsymbol{\mathsf{S}}}$




8. click the right mouse button to display the following menu.

Finish	Enter
Finish (close with reflection	n)
Remove Last	
Switch Side	
Auto insert corner on next	line
Side Indicator on Next	
None on next	
Overlap on next	
Fold on next	
Trim on next	
Seam on next	


9. click **Finish** to complete the part. The part can also be finished by pressing the **Enter** key or clicking the middle mouse button.

The part will be highlighted.




7.1.1.6 Creating parts with two axes (enabling one at a time)


1. Select and active the first axis. To do that you can go to **Operations - Mirror - Active Axis** or press **CTRL+E**, after Axis selection.



3. Press the right mouse button and select the option **Switch Side**.




4. Start to define the boundary of the part using the left mouse button. Select the lines based on the numbers order shown in the image below (1,2 and 3).





5. Press the right mouse button and select again the option Switch Side.

Finish ENT	TER
Finish (close with reflection)	
Remove Last	
	rrl
Auto insert corner on next line	С
None on next	
Overlap on next	0
Fold on next	F
Trim on next	Т
Seam on next	S


 Select the top line (marked on the below image with the number 1); next, select and active the seconde axis. To do so, you can select **Operations - Mirror - Active Axis** or press **CTRL+E**, after Axis selection.









8. Continue to select lines, based on the numbers order, as shown in the image below (1,2 and 3).



9. Press the right mouse button and select the option Switch Side.



10.Continue to select lines this time the bottom line (marked on the below image with the number 1).



11. Click the right mouse button to display the following menu.


Finish	ENTER
Finish (close with reflection	ר)
Remove Last	
Switch Side	CTRL
Auto insert corner on next	line C
None on next	
Overlap on next	0
Fold on next	F
Trim on next	Т
Seam on next	S

12. Select **Finish** to complete the part. The part can also be finished by pressing the **Enter** key or clicking the middle mouse button.




7.1.1.7 Creating parts with two axes (enabling the two axes at once)


1. Select the two axes. To select the both axes simultaneously select the first one and keep the **CTRL** press until select the second one.




2. Activate the axes. To activate the axes you can go to **Operations - Mirror - Active Axis** or press **CTRL+E**, after Axes selection.




- 3. Select By contour from Create Part in the Parts menu.
- 4. Press the right mouse button and select the option Switch Side.




5. Start to define the boundary of the part using the left mouse button. Select the lines based on the red numbers order shown in the image below (1,2 and 3).



6. Press the right mouse button and select again the option Switch Side.




7. Continue to select lines based on the red numbers order shown in the image below (1,2 and 3).




8. Click the right mouse button to display the following menu.

Finish ENT	ER
Finish (close with reflection)	
Remove Last	
Switch Side CT	RL
Auto insert corner on next line	С
None on next	
Overlap on next	0
Fold on next	F
Trim on next	Т
Seam on next	S

9. Select **Finish** to complete the part. The part can also be finished by pressing the **Enter** key or clicking the middle mouse button.



Note: The difference between this method and create a mirrored part is the fact that the lines can be different on each side. Take the below image for example.




7.1.1.8 Tips and tricks

Inside indicators


- Digitised shell For an inside indicator, use the Inside indicator on next option or press M.
- If you are trying to create unfolded or mirrored parts and the parts are not being displayed, always check that the correct axis is selected.
- Mirrored or unfolded parts will automatically update if you move the axis.
- Lines don't need to intersect a part to be created. The gap between the lines can be up to 25 mm.
- Avoid split lines after parts creation.

7.1.2 Parts - Create Part - By One Click


- 1. Select By One Click from Create Part in the Parts menu.
- 2. Position the mouse cursor in the middle of the lines that will compose the part.



3. When the cursor is in the right position, do a click with the left button, the parts contour will be selected.




4. Before ending the process you can select more parts; just position the cursor again in the middle of the desired lines.




7.1.3 Editing Parts

7.1.3.1 Editing Parts - Corners


1. Select one or more parts from the **Parts/Library** toolbar using the left mouse button.




The part will be displayed.




2. Using the left mouse button click inside the part, which will be highlighted.



3. As you move the cursor close to the corner positions (shown by green dots), the cursor will change to the corner cursor.




4. Using the left mouse button select the corner, which will be highlighted.



5. Select the type of corner from the **Tool Options** toolbar.


Comers
Comer
VLNLL
Radius
Begin: 3 A End: 3 A
Smooth factor: 0.5
No corner - Intersect the lines only
Arc - Insert an arc of given radius
Bezier - Similar to an arc, but with better results on sharp intersections.
Chamfer - Cut the corner off with a straight line. If Link button is OFF, you can enter a Begin
and End radius.
becomes active when there are treatments on both sides of the corner. If applied, the
net intersection of the two original lines is used to generate an internal cut out. This command is usually used when one of the treatments is a fold. Control of the radius value is also possible.




L Smooth - It's	s possible to	adjust tl	ne smooth factor, w	hen this corner t	type is selected the text
box is enable Smoot	th factor: ().99 🊔			

7.1.3.1.1 Editing Parts - Treatments


1. select one or more parts from the **Parts/Library** toolbar using the left mouse button.




The part will be displayed.




2. using the left mouse button click inside the part. It will highlight. Corners are represented by green dots.



As you move the cursor close to the edge the cursor will change to the treatments cursor.



3. click the left mouse button to select the outline of the part between the corners.



The section of the outline will highlight


4. select the required treatment from the **Tool Options** toolbar or press the appropriate hot key to change the treatment.

Tool Options					
Treatments					
Offset type None Quality Line Sawtooth					
Stencil Punch Comer Notches Stretch Offset					
Distance (mm):					


7.1.3.1.2 Editing Parts - Radius

This option allows to force smooth corners on treatments.







1. Using the left mouse button click inside the part. It will highlight.



2. As you move the cursor close to the edge the cursor will change to the treatments cursor.



3. Click the left mouse button to select the outline of the part. The section of the outline will highlight




4. In the Tool Options toolbar change the value of the Radius(mm).

Tool Options	
Treatments	
Offset type None Qua Line Sawtooth	lity
Stencil Punch Notches Stretch	Comer Offset
Distance (mm): Smooth sharp angles – Radius (mm):	


5. As you increase the value the sharp angle is smoothed.






7.1.3.2 Editing Parts - Notches


• select one or more parts from the **Parts/Library** toolbar using the left mouse button.




The part will be displayed.



• using the left mouse button click inside the part. It will highlight.




• with the **Shift** key pressed place the notch on the desired location clicking the left mouse button.




The section of the outline will highlight


• select the Notches tab of the Tool options toolbar



- Use the **Notches** options to set the notch type, size and side.
- 1. Line A line placed at the cursor position. You can also enter a Depth and Curvature value.
- The notches placement can be on mouse selection.




• Or **On Intersection** than can be **Oblique** or not. Oblique *OFF* Oblique *ON*




Oblique - A notch with the base of the triangle placed on the line it is created from. Oblique notches can only be applied using the intersection option.

- 2. **Triangle** A triangular notch, placed with its centre at the position or intersection selected.
- The notches placement can be done on mouse selection.




• Or **On Intersection** than can be **Oblique** or not. Oblique *OFF* Oblique *ON*




3. Arc - An arc shape - normally used as an inside indicator

• The notches placement can be done on mouse selection.




• Or On Intersection.




4. Rectangle - A rectangle of given size.

MindCAD 2D Design & Engineering


• The notches placement can be done on mouse selection.




• Or On Intersection.



 move the cursor towards the selected part of the outline. As you get close, the cursor will change to the notch cursor



position the notch and click the left mouse button.



The notch will be added.

- If the cursor is positioned inside the part, the notch will go inwards,
- If positioned outside the part, the notch will go outwards.
- If the intersection option is used when positioning a notch, the notch cursor will only be displayed at positions where lines intersect.

To edit notches,

328

- 1. Select them with the left mouse button
- 2. Use the **Tool** Options to make the required changes. You can use the **Delete** key to remove the notch
- To set a shortcut for commonly used notches, including type and value,
- 1. Click on a blank shortcut box at the top of the menu


Tool Options			
Notches			
Type name			
not 🔹			
OK Cancel			
On Intersection Margin (mm): 0			

2. Type in a name and select **OK**. This shortcut is now available for future use.


Notches			
Type Line Triangle Arc Rectangle	Width (mm): 7 Depth (mm): 1		
Change Side	O		
On Intersection			
Margin (mm):			

7.1.3.3 Editing Parts - Text

1. Select the part(s) from the **Parts/Library** toolbar using the left mouse button. The part will be displayed with its default text



2. Select the text using the left mouse button.



- 3. Change the text using one of the following methods
- To rotate the text,




- (a) Move the cursor to the yellow dot;
- (b) Click the left mouse button and drag the cursor to the required position;
- (c) Release the left mouse button.

To drag the text,




- (a) Move the cursor over the text;
- (b) Click the left mouse button and drag the cursor to the required position;
- (c) Release the left mouse button.

Note: If the text is dragged to one of the part edges, its orientation will adjust automatically.



To scale the text,



(a) Move the cursor over one of the white dots displayed;

- (b) Click the left mouse button and drag the cursor to the required position;
- (c) Release the left mouse button.

To add new text to parts,

(a) With the part is selected select the Text tab of the Tool Options toolbar

332	MindCAD 2D Design & Engineering
-----	---------------------------------

Text			
Labels	s on part –		
%Part %Num			C + -
Value:		%Part%	
Propert	ies:	Properties	-

(b) Press the button "+". Now select the required text from the list. Press **Ok** to apply it to the current part.

Add labels ×
Add fabels ↓
OK Cancel

7.1.3.4 Editing Parts - Configuring Treatments

Treatments are a quick way of applying offsets, corners and notches in one operation.

There are many options that can be set. You can also add a shortcut that allows them all to be applied in one operation.

1. Select a part

- 2. Select a part of the outline and go to the Treatments tab of the Tool Options toolbar.
- 3. Set the **Offset type** and use the **Treatment** options to set the treatments.

None - No offset;

Line - A normal offset line;

Sawtooth - An offset with a sawtooth edge.

To set a shortcut for commonly used treatments. Define treatments properties, including offset type, offset distance, stencil, punch, corner and notches,

1. Set the values on the Stencil tabulator

Treatments		
0	FT	S
	~~~~	
Offset type None Line	Quality	
Sawtooth	4	*
Notches	Stretch	Offset
Stencil	Punch	Comer
◯ Net ◉ Offset ◯ Inside	Out:	side
Width (mm):		1.6
Margin (mm): 8 💽 8 Max. Length (		<b>CO</b>
Gap (mm):		6
Distance (mm)	): Outsi	0 📮
Side indicator	0	0
Properties:	Properties	

3. Set the values on the Punch tabulator

Treatments		
0	FT	S
Offset type None Line Sawtooth	Quality	*
Notches Stencil	Stretch Punch	Offset Corner
Enable     Punches typ     By numbe     By distan	er	
Margin (mm): 8 -		C C C C C C C C C C C C C C C C C C C
Properties:	Properties	-

4. Set the values on the Corner tabulator


Treatments		
0	FT	S
	****	
Offset type None Line	Quality	~
◯ Sawtooth	4	•
Notches	Stretch	Offset
Stencil	Punch	Comer
Туре		
○ None		
O Bezier		
Arc		
Chamfer		
Smooth		
Radius (mm):		4
Smooth factor:		0.8

5. Set the values on the Notches tabulator

Treatments		
0	FT	S
	~~~~	
Offset type None Line	Quality	~
◯ Sawtooth	4	*
Stencil	Punch	Comer
Notches	Stretch	Offset
Type None Oblique Triangular		
Depth (mm):		2
Width (mm):		2
Curvature:		0
Offset (mm):		2

6. Set the values on the Stretch tabulator

336 MindCAD 2D Design & Engineering



7. Right click on a blank shortcut box at the top of the toolbar.

Tool Options	
Press right button to configure this	shortcut
Offset type None Quality Cline 4	
Stencil Punch Comer	
Notches Stretch Offset	
Stretch (%):	
Start decay distance (mm): 7	
End decay distance (mm): 24	

8. The contextual menu will appear, select configure.

Apply
Configure
Copy Paste Delete

9. Type in a name and select **OK**.

Tool Options		
Treatments		
OFTS		
Offset type ○ None Quality ● Line 4 ✓ Sawtooth		
Stencil Punch Comer		
Notches Stretch Offset		
Type name 🛛 🗙		
Overlap kids 🗸 🗸		
OK Cancel		


9. Type shortcut key and select **OK**.

Tool Options		
Treatments		
0	FT	S

Offset type	Quality	
Sawtooth	4	~
Stencil	Punch	Comer
Notches	Stretch	Offset
Type shortcut key		
К		~
	ОК	Cancel

10. This shortcut is now available for future use.

338 MindCAD 2D Design & Engineering



11. More space is available for more quick access buttons by pressing the 4 triangles button.

Parts Overview	339


Treatments			
	0	F	т
S	К		

7.1.3.5 Editing Parts - Stretch

This includes extreme wrinkle effects.

- 1. select a part
- 2. select an edge the part and go to the **Treatments** tab of the **Tool Options** toolbar.
- 3. set the values on the Stretch tabulator

340 MindCAD 2D Design & Engineering



Stretch (%)	Stretch percentage. This value controls the amount of added material along the selected edge that should exist to compensate the wrinkle effect
Start decay distance (mm)	Start value distance. This value controls the beginning of the blending region.
End decay distance (mm)	End value distance. This value controls the end of the blending region.

7.1.3.6 Treatments - Line Offset

These are the options for the most typical treatment, which is the Line type

Treatments		
0	FT	S

Offset type None Line Sawtooth	Quality 4	~
Notches	Stretch	Offset
Stencil	Punch	Comer
 ○ None ○ Net ● Offset ○ Inside) Out	side
Width (mm):		1.6
Margin (mm): 8 • 8 • 600 00 Max. Length (mm): 25 •		
Gap (mm):		6
Distance (mm)):	0
◯ Inside	Outsi	ide
Side indicator	(mm):	0 🛉
Properties:	Properties	-

Stencil

Stencils are the same as markers; the stencil menu can be scrolled by holding down the left mouse button.

None - no markers;

Net - Markers that are drawn over the original line;

If Net stencils are used, more information is required;

Width (mm) - the width of the stencil in millimeters;

Margin (mm) - the distance from the next portion of the part outline. This is used to undercut the markers so they do not break the edge of the part;

Max length (mm) - the maximum length of the marker in millimeters;


Gap (mm) - the gap between markers in millimeters;

Offset - markers which are offset from the original line. If Offset is used, the following values must be specified;

Inside - Offset is towards the inside of the part (away from the edge);

Outside - Offset is towards the outside of the part (towards the edge);

Distance (mm) - Distance of the offset in millimeters;



Side indicator - Enter value of the side indicator.

Corner

Corners will be applied at both ends of the treatment.

Notches

Notches will be applied at both ends of the treatment if selected

Offset

The offset from the original line in mm.

7.1.3.7 Treatments - Corners-Side


It is possible to control the corners of a treatment

Tool Options
Treatments Comers/Side
Side Indicator

Corners - please refer to Editing Parts - Corners for details. **Side Indicator** - Enables the side indicator. This option is only available in part creation.

7.1.3.8 Treatments - Sawtooth offset

These are the options for the **Sawtooth** type treatment



Triangular - Triangular shape

Rectangular - Rectangular shape

Elipse - Elipse shape

Arc - Arc shape

User defined - User defined shape. This must be selected from the **Punches** tab of the **Parts/** Library menu

The number of shapes on the part can be defined by

By Length - Length of each shape

By Number Waves - Number of shapes required

Depth (mm) - Depth of the shape in mm

Rounded - Corners of the shapes can be rounded

7.1.3.9 Editing Parts - Names, Cut Groups, Cost Groups and Colours

1. with a part selected, select to the Properties tab of the Tool Options toolbar

Properties	Notches Text Points
Name:	MO 🗸
Cut group:	• +
Cost group:	
Color:	
Quality:	1 -
Properties:	Properties -
Quantity (sy	mmetric): 0

2. Change or add the properties.

- Name - Select the part name from the drop down list

- **Group** - Select the part group from the drop down list. Using the + button will allow you to add names and groups using the properties options.

	Parts ×
Cut groups Group: Color:	leather V Create Delete
Names Name: Cut group: Color:	toecap v AUTO v Create Delete
	×
Type the new Part_X	material name Cancel


- Color Define the part color;
- Quality Part quality used to calculate its cost;
- Properties It is recommended that this option is unchanged;
- Symmetric If ON, the part needs to be cut twice (once mirrored);
- Quantity Number of parts in the project
- Quantity (symmetric) Number of parts symmetric in the project.

7.1.3.10 Editing Parts - Points

Entry Point - To define the cutting start position.

Orientation - To define the orientation of the part when cutting. This orientation is used by the automatic or interactive nesting algorithms.


1. When you select the part the entry point it's already placed. To move the point just click over it and drag.



2. To set the orientation point do right click and select the option **Show orientation**. The orientation will also be visible in the parts bar.


	Finish	Enter
	Properties	
	Notches	•
	Alignment point	+
	Reset points	
	Select	•
L	Show orientation	
	Delete	Delete
	None	
	Overlap	
	Fold	
	Trim	
	Seam	

Note: If you move the part the points will be dragged with it.



7.1.3.11 Editing Parts - Breaking the part boundary.


- The boundary of a part can be broken or cut where a line intersects it.
- 1. select the section of the part boundary you wish to break. This may be for a change in offset within that section.



2. Press **Shift** and move the cursor towards the line that defines the cut position. The cut cursor will

be displayed 🗾


- 3. click the left mouse button to cut the boundary.
- 4. apply different treatment to one section.




7.1.3.12 Editing Parts - Edit lines

Sometimes it is useful to be able to display only the lines that are used in the current part. This is particularly useful when a shell has many lines.

- 1. Select the part(s) in the parts library.
- 2. Right mouse click over the part in the Parts toolbar.
- 3. Select Edit Lines option, from the contextual menu.



The part and its lines will be displayed for editing




7.1.3.13 Editing Parts - Copy and paste

To make a copy of a part,


- 1. Select the part.
- 2. Right mouse click over the part in the Parts toolbar.
- 3. Select **Copy** from the contextual menu.

	Cut
	Сору
	Paste V
	Delete
	Replace contour
	Place
	Select Axis
	Edit Lines
	Return to Shell
court	Variants +
Parts/Lib	Simulate Cut
Parts	Costing
Υ.	Properties
El court1	

4. Select a blank space in the Parts toolbar



- 5. Click the right mouse button while the cursor is over the blank space.
- 6. Select Paste All from the contextual menu.




The copy of the part will be displayed in the parts toolbar.


7.1.3.14 Editing Parts - Return to Shell

Use this option to show all the lines on a part. The display is scaled so that the whole part is shown on the screen.


With the part selected,



- 1. Right mouse click over the part in the Parts toolbar.
- 2. Select Return to Shell option.



The part and all lines will be scaled to fit the screen and displayed




352

7.1.3.15 Editing Parts - Simulate Cut


This option simulate cut the parts.

- 1. Select the part(s).
- 2. Right mouse click over the part in the $\ensuremath{\textbf{Parts}}$ toolbar.
- 3. Select Simulate Cut from the contextual menu.



- 4. Select exporter machine to simulate.
- 5. The Cut simulation window will appear.





7.1.3.16 Editing Parts - Costing

This option does the costing evaluation of the target parts.

- 1. Select the part(s).
- 2. Right mouse click over the part in the **Parts** toolbar.
- 3. Select **Costing** from the context menu.

354 MindCAD 2D Design & Engineering

	Cut
	Сору
	Paste 🕨 🕨
	Delete
	Replace contour
	Place
	Select Axis
< \	Edit Lines
court	Return to Shell
Parts/Library	Variants 🕨
Parts Pu	Simulate Cut
T ,	Costing
<u></u>	Properties
court1	M ² M ²

4. The dialog part assessment will appear. More information on the options available could be found on the Parts - Costing section.

Part assessm	ent										
Material:	<all></all>		•	Technique:	In	verse parall	elogram 🔻				7
Size:	<all></all>		•	Group com	mon sizes						
Part:	<all></all>		•							rt-T-	
Group by:	None		•	Options]	Report	t PDF	CSV			
Component	Part	Size	Area	Perimeter	Efficiency	Total/Part	Total/Pair	Punches	Markers	Lines	
1260D	meP_sita - 0	Inv.	0.080 m²	1117.5 mm	99.4 %	0.080 m²	0.161 m²	0	0.0 mm	0.0 mm	
Average:			0.080 m ²	1117.5 mm	99.4 %	0.080 m²	0.161 m²				
Total:			0.080 m ²	1117.5 mm	99.4 %	0.080 m ²	0.161 m ²	0	0.0 mm	0.0 mm	
Total:			0.080 m²	1117.5 mm	99.4 %	0.080 m²	0.161 m²	0	0.0 mm	0.0 mm	
Total:			0.080 m²	1117.5 mm	99.4 %	0.080 m²	0.161 m²	0	0.0 mm	0.0 mm	
Total:			0.080 m²	1117.5 mm	99.4 %	0.080 m²	0.161 m²	0	0.0 mm	0.0 mm	
Total:			0.080 m²	1117.5 mm	99.4 %	0.080 m ²	0.161 m²	0	0.0 mm	0.0 mm	
Total:			0.080 m²	1117.5 mm	99.4 %	0.080 m²	0.161 m²	0	0.0 mm	0.0 mm	
Total:			0.080 m²	1117.5 mm	99.4 %	0.080 m²	0.161 m²	0	0.0 mm	0.0 mm	
Total:			0.080 m²	1117.5 mm	99.4 %	0.080 m ²	0.161 m²	0	0.0 mm	0.0 mm	l
Total:			0.080 m²	1117.5 mm	99.4 %	0.080 m²	0.161 m²	0	0.0 mm	0.0 mm	
Total:			0.080 m²	1117.5 mm	99.4 %	0.080 m²	0.161 m²	0	0.0 mm	0.0 mm	
Total:			0.080 m²	1117.5 mm	99.4 %	0.080 m²	0.161 m²	0	0.0 mm	0.0 mm	
Total:			0.080 m²	1117.5 mm	99.4 %	0.080 m ²	0.161 m²	0	0.0 mm	0.0 mm	

7.1.3.17 Editing Parts - Properties

How to access parts properties.

- 1. Select the part(s). Several parts could be selected by using the **CTRL** button while clicking. This enables to set common properties to the selection.
- 2. Press the right mouse button while the cursor is over the part(s) in the **Parts** library.
- 3. Select **Properties** option.

Cut
Сору
Paste +
Delete
Replace contour
Place
Select Axis
Edit Lines
Return to Shell
Simulate Cut
Costing
Properties

4. Change or add new properties.

Properties Properties	Assessment					
Name: Group: Quantity: Quantity (symmetric):	M%S	* *	Angle:	0.0 v	Angle: Range:	0
Color:	AUTO V				+ •	

7.1.3.17.1 Parts Properties - Properties

Use this option to edit the part properties.

Properties Properties	Assessment					
Name: Group: Quantity: Quantity (symmetric):	M%S	× +	ngle: Rotation angles fo	0.0	Angle: Range:	0
Color:	AUTO -				+ -	

Name - Select the part name from the drop down list.

Group - Select group from the drop down list.

Quantity - Number of parts in the project.

Quantity (symmetric) - Number of parts symmetric in the project.

Color - Select the part color.

Angle - Insert the start position angle of a part.

Rotation angles for auto nesting - After inserting the Angle and Range, click "+" button, to add the new angle range.

To delete an angle range, select it and press "-" button.

Properties Properties Assessment	
Post processing	Part contents
✓ Filter outside border	Remove lines outside border
✓ Filter holes	Remove lines inside holes
✓ Filter internal lines	Trim line groups
	Remove holes outside border

Post processing - Allow to filter (remove excessive points) from the **outside border**, **holes** or **internal lines**.

Part Contents - Select or deselect the content parts options.

Remove lines outside border - When the part is generated (to send for cut or PDM) all the lines outside the border will be excluded.

Remove lines inside holes - When the part is generated (to send for cut or PDM) all the lines inside the holes will be excluded.

Trim line groups - For line groups (ex. markers), this option controls if the markers is cut or deleted when is intersecting the border.

Remove holes outside border - The holes contained outside the part border will not be exported.

7.1.3.17.2 Parts Properties - Assessment

The parts assessment allows to have real time consumptions.

Properties Properties	Assessment	
Method	Bounding box	
Parts margin	0 mm	
Parts area	0.032 m ²	
Parts	1	
Result	0.070 m ²	
Efficiency	46.19 %	

• Method: Several interlock costing techniques can be used;

There are several methods:


~	Convex Hull
	Parallelogram
	Inverse parallelogram
	Bounding box
	Linear
	Circle
	Grid
	Synthetic

- Parts Margin: Adds a margin in mm between parts;
- Parts Area: The parts area;
- **Parts**: The number of parts;
- **Result:** Consumption area for the specified pattern.
- Parts Margin: Adds a margin in mm between parts;
- **Result:** Consumption area for the specified pattern.
- Efficiency: Measure of efficiency, defined as material area being cut versus raw material area;

7.1.3.17.2.1 Method - Convex Hull

This is a nesting interlock technique called Convex Hull.

It uses the tightest bounding convex polygon (Convex Hull) of the part or part group and evaluates the resulting area.




The result will be as displayed in the Part assessment panel tab, with the following result metrics:

7.1.3.17.2.2 Method - Parallelogram

This is a nesting interlock technique called Parallelogram.

It uses the central point of the part group and packs, without any rotation, the group based on a parallelogram that is the minimum parallelogram with the shortest height (distance in Y).

The result will be as displayed in the Part assessment panel tab, with the following result metrics:



7.1.3.17.2.3 Method - Inverse Parallelogram

This is a nesting interlock technique called Inverse Parallelogram.

It uses the central point of the part group and packs, without any rotation, the group based on a parallelogram that is the minimum parallelogram with the shortest height (distance in Y).

Method	Inverse parallelogram	
Parts margin	0 mm	
Parts area	0.032 m ²	
Parts	1	
Result	0.036 m ²	
Efficiency	88.52 %	
		RH

7.1.3.17.2.4 Method - Bounding box

This is a nesting interlock technique called Bounding Box.

It uses the tightest bounding box of the part group and evaluates the resulting area.



operties Properties	Assessment	
Method	Bounding box	
Parts margin	0 mm	
Parts area	0.032 m ²	
Parts	1	
Result	0.070 m ²	
Efficiency	46.19 %	

7.1.3.17.2.5 Method - Linear

This is a nesting interlock technique called Linear. This is used for linear raw materials automatically fed from a roll.

It uses the minimum vertical linear strip that fully contains part group and evaluates the resulting area.

1ethod	Linear		
Parts margin	0 mm		
arts area	0.032 m ²		
arts	1		
fficiency	46.19 %		
Vidth	0.301 m		
Height	0.231 m		


7.1.3.17.2.6 Method - Circle

This is a nesting interlock technique called Circle.

It uses a calculated edge of the part group and evaluates, using a circle with a specific radius traveling over that edge, the boolean union of all those circles.

After choosing the this technique enter the radius

Circle radius 5




7.1.3.17.2.7 Method - Grid

This is a nesting interlock technique called Grid. The system activate the grid over parts.

The operator add the grid value.

Grid size		10
-----------	--	----



7.1.3.17.2.8 Method - Synthetic

This is a nesting interlock technique called Synthetic. This is used for synthetic materials available in rectangular formats.

First the measures of the material should be defined.

 Material width
 2000

 Material height
 1000


Properties Properties	; Assessment	
Method	Synthetic	
Parts margin	0 mm	
Material width	2000	
Material height	1000	
Parts area	0.032 m²	
Parts	45	
Result	0.044 m ²	
Efficiency	72.35 %	
		SSSSSS

7.1.3.18 Editing Parts - Parts Bar

MindCAD 2D Design & Engineering

366

For a better user experience, a parts bar is available on the lower end of MindCAD 2D Design & Engineering interface layout. This bar has thumbnails of the parts.



Besides the graphical representation of the part, containing outer boundary and all the elements that could be included on a part (markers, notches to name a few), there are auxiliary symbols appearing on the top right corner of the thumbnail.

This symbol means this part is not symmetrical (could be defined in properties).



This symbol means this part has more than one part per foot (could be defined in properties).



This symbol means this part has an associated group grading (could be defined in properties).




This symbol means this part has variants (could be defined in properties)



This symbol shows the part orientation.



When we hover the cursor on the part, a quick properties window appears.



This button allows filtering parts by material.

7

This button allows sorting part by alphabetic order.



This button allows hiding empty part thumbnails.



7.2 Parts - Create Hole

This menu lets you to choose between create a hole by contour or by on click.



7.2.1 Parts - Create Hole - By Contour


This option lets you apply holes to parts. This is the same as clicking the **Create Hole** button in the **Parts** toolbar.




Treatments can be applied to holes.

To create a hole,

- 1. Select the part.
- 2. Select Create Hole from the Parts toolbar
- 3. Start defining the boundary of the hole.



4. Define the rest of the boundary of the hole going in one direction.




5. Click the right mouse button to display the following menu.

Finish	ENT	ER
Finish (close with reflection))	
Finish (add on reflection)		
Finish (add on both sides)		
Remove Last		
Switch Side	CT	RL
Auto insert corner on next l	ine	С
Side Indicator on Next		М
None on next		
Overlap on next		0
Fold on next		F
Trim on next		Т
Seam on next		S
overlap Kids on next		К

6. Select **Finish** to complete the part. The part can also be finished by pressing the **Enter** key or clicking the middle mouse button.

The part will be drawn with the hole.



• Use the Finish (and insert reflection) option to put the hole in the reflected part of a folded part.

To delete a hole,

1. Move the cursor over the hole to be deleted. A circular cursor will be displayed




MindCAD 2D Design & Engineering


- 2. Press the left mouse button to select the hole.
- 3. Press the **Delete** key to delete the hole.

7.2.2 Parts - Create Hole - By One Click

- 1. Select By One Click from Create Hole in the Parts menu.
- 2. Position the mouse cursor in the middle of the lines that will compose the hole.



3. When the cursor is the right position do a click with the **left button**, the hole will be created.



7.3 Parts - Create Quality Area

This option lets you create quality areas within parts to aid in the costing process.


- 1. Select the part to have a quality area applied
- 2. Select Create Quality Area from the Parts menu
- 3. Create an area, using the method used to create a hole.

370

- 4. When the circular cursor is displayed, select the quality area.
- 5. Use the Tool Options toolbar to set the quality value.

To	ool Options
Properties N	otches Text
Name:	M%S ♥
Group:	× +
Color:	AUTO -
Quality:	1 ~
Properties:	1
Symmetric	
Quantity:	51 /1
Quantity (symn	netric): 0 / 1
Side:	Left 🗸

The quality areas color depends in the quality value.



7.4 Parts - Add Lines

This option lets you add lines to completed parts.



372


7.4.1 Parts - Add Lines - Add Lines

This is the option to add lines to completed parts, if you use this option on unfolded parts, lines will be added to both sides of the part. Lines added to parts will be drawn on the finished (cut) part.


This is the same as clicking the Add Lines 🧰 button in the Parts toolbar




1. Select the Part to have lines added.



2. Select Add Lines from the Add Lines options of the Parts menu, select Add Lines from the parts tool bar or press F4.



3. After selecting the required lines, do a right click and select **finish** from the contextual menu or press **Enter**.




7.4.2 Parts - Add Lines - Add Lines to One Side


This option adds lines, in their original position, to completed mirrored parts.

To add lines to one side of the part,


1. Select the Part to add the Line.



2. Select the Line to be added.



- 3. Select Add Line to one side from the Add Lines options of the Parts menu.
- 4. The line will be added to the part.




7.4.3 Parts - Add Lines - Add Lines only to Reflection


This option adds lines in their mirrored position, to completed mirrored parts.

To add lines only to the reflection,


1. Select the **Part** to add the Line.



2. Select the Line/Stencil to be added.



- 3. Select Add Lines only to reflection from the Add Lines options of the Parts menu.
- 4. The line will be added to the part.




7.4.4 Parts - Add Lines - Add Lines on both Sides

This option adds lines to both sides of completed mirrored parts.


To add lines to both sides,

1. Select the **Part** to add the Line.




376 MindCAD 2D Design & Engineering

2. Select the Line to be added.



- 3. Select Add Lines on both sides from the Add Lines options of the Parts menu.
- 4. The lines will be added to the part.



7.5 Parts - Add Cut


This option lets you add lines to completed parts. The lines that are added will be cut when sent to the cutting table.




7.5.1 Parts - Add Cut - Add Cut

This option allows choosing where to add the cut.


1. Select the line to be added to the part.




2. Select Add Cut from the Add Cut options of the Parts menu.




3. Select the lines to add the cuts by doing a left mouse click over the shown lines.



4. To finish the process press the middle mouse button or CTRL key.




5. To edit the selected cut, do the same process and deselect the lines.




7.5.2 Parts - Add Cut - Add Cut to One Side

This option adds cuts in their original position, to completed mirrored parts.


1. Select one or more parts to have cuts added.



3. Select Add Cut to One Side from the Add Cut options of the Parts menu.




The part will have the cut added




7.5.3 Parts - Add Cut - Add Cut only to Reflection


This option adds cuts in their mirrored position, to completed mirrored parts. 1. Select one or more parts to have cuts added.




2. Select one or more lines to be added



3. Select Add Cut only to Reflection from the Add Cut options of the Parts menu.



The part will have the cuts added




382


7.5.4 Parts - Add Cut - Add Cut on both Sides

This option adds cuts to both sides of completed mirrored parts.


1. Select one or more parts to have cuts added.



3. Select Add Cut on both Sides from the Add Cut options of the Parts menu.



The part will have the cuts added



7.6 Parts - Add Stencil

This option allows to add lines, text and images to parts. The added elements keep is characteristics (color, thickness, style, etc) when exported to Cut, using the Printer exporter.

Allowing these elements to be sent directly to the laser machine and designed within the part to cut.

Add Stencil
Add Stencil to One Side
Add Stencil only to Reflection
Add Stencil on both Sides

This tool was made for Laser engraving, allowing to print images, text and lines with different color intensity.

- 1. Select the Part to add the Stencils.
- 2. Select Add Stencil from the Add Stencil options of the Parts menu, or press F4.
- 3. With the left mouse button click over the lines, images or text to add.



384 MindCAD 2D Design & Engineering

- 4. When items will be highlighted when selected.
- 5. To finish do a right click and select **Finish** from the contextual menu, or press **Enter**.

For images, the machine driver will automatically apply color intensity, lighter colors will by applied less intensity, darker colors will by applied more intensity.

For Lines and Text, its possible to configure the intensity and machine velocity for each color. The intensity can also be configured by material type.

Option Pe	en	Advance	Paper	Language	Raster		
Pen No.	Color	Speed	Powe	r PPI	Raster	Vector	
1 2		86.0 60.0	36 31	300 300	YES YES	YES YES	^
3 4		89.0 25.0	15 88	300 300	YES YES	YES YES	_
5 6 7 8 9 10		86.0 50.0 50.0 50.0 50.0 50.0 50.0	25 50 50 50 50 50	300 300 300 300 300 300	YES YES YES YES YES YES	YES YES YES YES YES YES	
11		50.0	50	300	YES	YES	V .
Speed: Power:	•				•	86.0 25	✓ Raster✓ Vector
PPI:	•				•	300	
							OK Cancel

Simulating the Cut in MindCAD2D its possible to check the elements properties that are kept for each exporter.


Using the printer exporter:

385

	Cut simulation	- 🗆	x
Exporter:	New Printer exporter		*
Part:	1 ~	< 1	>
	nind Technolog	y	


7.6.1 Parts - Add Stencil - Add Stencil

This option allows to add or remove lines/stencils through an interactive tool.



2. Select Add Stencil from the Add Stencil options of the Parts menu.

386




3. After selecting the required lines/stencils, do a right click and select finish from the contextual menu.

	Finish	Enter
	Cancel	
~	On both sides	
	Only to reflection	
	Only to non reflected sid	e


7.6.2 Parts - Add Stencil - To One Side

This option allows to add lines/stencils to one side.




1. Select the **Part** to add the Stencil/Line.

- 3. Select Add Stencil to one side from the Add Stencil options of the Parts menu.
- 4. The stencil/line will be added to the part.




7.6.3 Parts - Add Stencil - Only to Reflection

This option allows to add lines/stencils only on reflection.



1. Select the Part to add the Stencil/Line.


- 3. Select Add Stencil only to reflection from the Add Stencil options of the Parts menu.
- 4. The stencil/line will be added to the part.




7.6.4 Parts - Add Stencil - On both Sides

This option allows to add lines/stencils on both sides.

1. Select the Part to add the Stencil/Line.



- 3. Select Add Stencil on both sides from the Add Stencil options of the Parts menu.
- 4. The stencil/line will be added to the part.



7.7 Parts - Add Modifier

This option lets you add modifier to completed parts.

This tool covers the guided deformation of a part through a master line and parameters. On a real modelling scenario, this will avoid the need to make manual cutting of the original part, to emulate the stretching imposed by the wrinkling effect. This provided an integrated solution where this kind of deformation is modelled before the piece being cut, not after.


Several options are available to add this kind of effect (**One side**, **Reflection** and **Both sides**). Please refer to the following sections.

- Add modifier to one side
- Add modifier only reflection
- Add modifier on both sides


7.7.1 Parts - Add Modifier - To one side

This option add modifiers to one side.


1. Select one part to add the modifier.



2. Select one or more lines to be added



3. Select Add on one Side from the Add Modifier options of the Parts menu.



4. Set the modifier values.

Properties Part modifier		
Mode: Rotate V		
Amount (mm): 1 📮 1 📮 📾		
Smooth: 1		
Central markers:		
Margin markers:		
Stretch		
O Percentage (%):		
Absolute (mm): 3		
Start decay (mm): 3		
End decay (mm): 20		
Decay function: Smooth V		
Direction: Forward V		
Middle point (%):		
Markers:		
Invert direction		

Crease

- Mode Select the mode between Rotate or Offset.
- Amount This value controls the amount of added material for the crease mode. (mm):
- Smooth This value controls the smoothness of the change.
- **Central** Add central markers automatically using the modifier line. **markers**
- Margin Add margin markers automatically using the modifier line. markers


Stretch

- Percentage Select how to input the values between Percentage or Absolute.
- (%) This values control the amount of added material along the selected edge, that
- Absolute should exist to compensate the wrinkle effect. (mm)
- Start decay This value controls the beginning of the blending region. (mm)
- End decay This value controls the end of the blending region. (mm)
- **Decay** Select the decay function between Linear, Sharp or Smooth. function
- Direction Select the stretch direction between Forward, Back or Both.
- Middle point Define in which point of the line the modifier should be applied. Ex: applied from the (%) line beginning (middle point = 0%), from the line middle (middle point = 50%) or the line ending (middle point = 100%).
- Markers Add markers automatically using the modifier line.
 Invert Enable/disable the invert direction option. If active inverts the line direction, so the
 - direction modifier is applied backwards.


7.7.2 Parts - Add Modifier - Only to reflection

This option add modifiers only to reflection.

1. Select one part to add the modifier.



2. Select one or more lines to be added.



3. Select Add only to reflection from the Add Stretch options of the Parts menu.



4. Set the modifier values.

Parts Overview	393
----------------	-----

Properties Part	t modifier	
Crease		
Mode:	Rotate	*
Amount (mm):	1	1 📮 📾
Smooth:	1]
Central markers		
Margin markers	c .	
Stretch		
O Percentage	(%):	0
Absolute (mr	m):	3 🔺
Start decay (mn	n):	3 🔺
End decay (mm) :	20 🛓
Decay function	:	Smooth 🗸 🗸
Direction:		Forward 🗸 🗸
Middle point (%)):	1
Markers:		
	ion	

Crease

- Mode Select the mode between Rotate or Offset.
- Amount This value controls the amount of added material for the crease mode. (mm):
- **Smooth** This value controls the smoothness of the change.
- Central Add central markers automatically using the modifier line. markers
- Margin Add margin markers automatically using the modifier line.
 markers

Stretch


- Percentage Select how to input the values between Percentage or Absolute.
 (%) This values control the amount of added material along the selecter
- (%) This values control the amount of added material along the selected edge, that
 Absolute should exist to compensate the wrinkle effect.
 (mm)
- Start decay This value controls the beginning of the blending region. (mm)
- End decay This value controls the end of the blending region. (mm)
- Decay Select the decay function between Linear, Sharp or Smooth. function
- Direction Select the stretch direction between Forward, Back or Both.
- Middle point Define in which point of the line the modifier should be applied. Ex: applied from the


394 MindCAD 2D Design & Engineering

- (%) line beginning (middle point = 0%), from the line middle (middle point = 50%) or the line ending (middle point = 100%).
- Markers Add markers automatically using the modifier line.
 Invert Enable/disable the invert direction option.


Applying a Crease modifier:

Mode: Rotation





Applying a Stretch modifier:




7.7.3 Parts - Add Modifier - On both Sides


This option add modifiers to both sides.

1. Select one part to add the modifier.


Parts Overview	395
----------------	-----



2. Select one or more lines to be added.



3. Select Add on both Sides from the Add Stretch options of the Parts menu.



4. Set the modifier values.

396 MindCAD 2D Design & Engineering

Properties P	art modifier
Crease	
Mode:	Rotate 🗸 🗸
Amount (mm)	1 📮 1 📮 😋
Smooth:	1
Central marke	ers:
Margin marke	ers:
Stretch	
O Percentag	ge (%):
Absolute	(mm): 3 🛓
Start decay (r	mm): 3 🔺
End decay (n	nm): 20 🔺
Decay function	on: Smooth V
Direction:	Forward 🗸 🗸
Middle point ((%): 1
Markers:	
Invert dire	ction

Crease

- Mode Select the mode between Rotate or Offset.
- Amount This value controls the amount of added material for the crease mode. (mm):
- **Smooth** This value controls the smoothness of the change.
- **Central** Add central markers automatically using the modifier line. **markers**
- Margin Add margin markers automatically using the modifier line. markers

Stretch


- Percentage Select how to input the values between Percentage or Absolute. (%) This values control the amount of added material along the selected edge, that
- Absolute should exist to compensate the wrinkle effect. (mm)
- Start decay This value controls the beginning of the blending region. (mm)
- End decay This value controls the end of the blending region. (mm)
- Decay Select the decay function between Linear, Sharp or Smooth. function

- Direction Select the stretch direction between Forward, Back or Both.
- Middle point Define in which point of the line the modifier should be applied. Ex: applied from the (%) line beginning (middle point = 0%), from the line middle (middle point = 50%) or the line ending (middle point = 100%).
- Markers Add markers automatically using the modifier line.
 - **Invert** Enable/disable the invert direction option.


direction

Applying a Crease modifier:

Mode: Offset



Applying a Stretch modifier:



7.8 Parts - Remove - Lines


398

This option removes lines that have been added to parts. This is the same as clicking the **Remove**


lines button in the Parts toolbar



1. Select the one or more parts to have the line removed from




2. Select one or more lines to be removed



3. Select Lines from the Remove options of the Parts menu.




The lines will be removed from the part




7.9 Parts - Insert Lines on Border

This option lets you insert lines into an already finished part.


- 1. Select the part to be edited.
- 2. Select Insert Lines on Border from the Parts menu.




3. Select the line that comes before the line(s) to be inserted



4. Select one or more lines to be inserted



5. Select the line that comes after the line(s) to be inserted




6. Click the right mouse button to display the popup menu.

Finish	Enter
Remove La	st
Switch Side	e
None on n	ext
Overlap on	next
Fold on ne	xt
Trim on ne	xt
Seam on n	ext


7. Select **Finish** to complete the part. The part can also be finished by pressing the **Enter** key or clicking the middle mouse button.

The part will be highlighted.



7.10 Parts - Replace Lines


Use this to replace lines in your parts. It allows you to change one line for another on all selected parts.



7.10.1 Parts - Replace Lines - Replace Lines

This option lets you replace one line with another on completed parts.


1. Select the line to be replaced (the original line).




2. Select Replace Lines from the Replace Lines options of the Parts menu.



3. Select the replacement line (the new line).



The part will be drawn with the new line as part of the boundary.




7.10.2 Parts - Replace Lines - Replace Lines on Reflection


This option lets you replace one line with another, on the reflected side of parts that have been mirrored/reflected.

1. Select the line to be replaced (the original line).

2. Select Replace Lines on Reflection from the Replace Lines options of the Parts menu.




3. Select the replacement line (the new line).




7.10.3 Parts - Replace Lines - Replace Lines/Reflection

This option lets you replace one line with another, on both sides of the parts that have been mirrored/ reflected


1. Select the line to be replaced (the original line).




2. Select Replace Lines/Reflection from the Replace Lines options of the Parts menu.



3. Select the replacement line (the new line).



The part will be drawn with the new line as part of the boundary.



7.11 Parts - Delete Part

This option deletes the current part(s). This is the same as selecting the part from the Parts/Library Bar, do a right click over it and select **Delete**.

7.12 Parts - Delete All Parts


This option deletes all parts.

7.13 Parts - Auto Add Lines on Creation

This option adds lines on creation of the parts.

•	Off
	on normal side
	on reflected side
	on both sides
Off	
On r	ormal side
On r	eflected side
On b	ooth sides

1. Active the option on normal side;



Now if you create punches, notches, markers or corners they will be added to the select part automatically (if they are located in the area of the part)

7.14 Parts - Costing

This option makes shape consumption assessment part by part.

Several display options could be configured to better evaluate the consumption like material, part, size, grouping and other like technique will control the evaluation costing algorithms.

Material - select which material already assigned to parts will be displayed.


<all></all>	•
<all></all>	
leather	
nubuck	
camurça	

Size - select which sizes of parts will be displayed.





Group by - select how to group the results



Technique - select the costing technique.

408 MindCAD 2D Design & Engineering

Circle	-
Convex hull	
Parallelogram	1 IIII
Inverse para	
Bounding bo:	<
Circle	

Group Common Sizes - Select this option to group common sizes.

Options - Select this option to configure the costing options.

Report - print a report

Model:	court		Base size:	5			
Costing technique:	Circle (4.0 mm)						
M4							
Component	Part	Size	Area	Perimeter	Efficiency	Total/Part	Total/Pair
camurça	M4	6	0.005 m²	283.7 mm	99.1 %	0.005 m²	0.010 m²
			0.005 m²	283.7 mm	99.1 %	0.005 m²	0.010 m²
M5							
Component	Part	Size	Area	Perimeter	Efficiency	Total/Part	Total/Pair
	M5	6	0.001 m²	106.4 mm	99.0 %	0.001 m²	0.001 m²
			0.001 m²	106.4 mm	99.0 %	0.001 m²	0.001 m²

PDF - Save a report in PDF format.

CVS - Save a report in CVS format.

7.14.1 Parts - Costing - Options

This option allows to adding costing options.

1. Create new Pricing settings

Co	sting options				×
	Pricing settings				
	Name:				
	Currency:		Margin (%):		
	Area cost:		Length cost:		
		Default	#1	#2	
	Punches cost:				
	Lines cost:		Markers cost:		
	Area unit		Length unit		
	Name:	m² 🔻	Name:		mm 👻
	Conversion:	1	Conversion:		1
	Punches				
	#1 property:				
	#2 property:				
	Report template				
	Without images			•	
			ОК		Cancel

2. Insert the name and the other costing properties.

410 MindCAD 2D Design & Engineering

osting options	-			×
Pricing settings				
Costing-1				▼ + -
Name:	Costing-1			
Currency:	EUR	Margin (%):		٥
Area cost:	0	Length cost:		0
	Default	#1	#2	_
Punches cost:	0	0	0	
Lines cost:	0	Markers cos	t:	0
Area unit		-Length uni	t	
Name:	m² ▼	Name:		mm 🝷
Conversion:	1	Conversion	:	1
Punches				_
#1 property:				
#2 property:				
Report template				_
Without images				•
		0	ĸ	Cancel

- 3. In the **Punches Cost** it's possible to assign them to specific properties.
- 4. To create a new property go to Preferences, Default Properties tab.
- 5. To assign the punch to the property, select the punches distribution and go to the preferences in the tool options box.
- 6. In the costing option, the name that is inserted in the **Punches #1 property** must match with the name given to the property assigned to the punches distribution.

The punch cost 1# represents the cost of the punches that have that property assigned.

7. Press **Ok** to finish the Costing Option.




8 Window Overview

This lets you control the position and the way your windows are arranged on the screen.

	Cascade
	Side by Side
	1 MindBags1
•	2 Novo-641-07334-02.b2d


8.1 Window - Cascade

This option lets you display your windows in a cascade.



8.2 Window - Side by Side

This option lets you display your windows side by side.



8.3 Window - List

Select the name of a current window to make it active.



9 Help Overview

416

This lets you launch the help system, open the Mind web site and display the version number of the current software.

?	Help Topics
•	Mind on the Web
	About MindCAD Bag Design & Engineering

9.1 Help - Help Topics


This option lets you launch the help system.

9.2 Help - Mind on the Web

This option lets you open the Mind website.

9.3 Help - About MindCAD 2D Modelling for Luggage

This option displays a dialogue box containing the version number.



419

Index

- A -

about 417 about axis 248, 261 Adding a new text string 92

- B -

Before you begin 12

- C -

cascade 412 Changing the values of the offset 236 161, 162 circle close 25 constrain bar 129 constrain edit 117, 121, 122, 123 nearest end 118 120 nearest grid 118 nearest intersection nearest line 117 nearest point 119 continue line 186 copy 115 368 create holes 286 create part Creating a closed curve. 153 151 Creating a curved line Creating a curved line with corner 152 288 Creating a part with no treatments or folds Creating an offset to a line 234 Creating an unfolded mirrored part 291, 293 Creating an unfolded non-mirrored part 300 Creating New Punch Shapes 261 Creating parts with treatments 305 115 cut

- D -

delete 116

design helper lines 141 drawing 148 161, 162 circle continue line 186 151 line rectangle 166, 170, 178, 179, 180, 181, 182 sawtooth line 174 Edit 114, 115, 116, 117, 118, 119, 121, 122, 123 overview 114 paste 116 select all 116 Edit - Constrain Edit constrain edit 117 Edit - Constrain Edit - Grid 120 Edit - Constrain Edit - Nearest End nearest end 118 Edit - Constrain Edit - Nearest Intersection nearest intersection 118 Edit - Constrain Edit - Nearest Line nearest line 117 Edit - Constrain Edit - Nearest Point nearest point 119 Edit - Copy copy 115 Edit - Cut 115 cut Edit - Delete delete 116 Edit - Digitize constrain edit 122 Edit - Drag Constrain constrain edit 121 Edit - Fixed Paste 116 Edit - Freezings 117 Edit - Group group 116 Edit - Paste paste 115 Edit - Precopy 122 Edit - Properties constrain edit 123 Edit - Redo undo 115 Edit - Reverse Selection 116

Edit - Select All 116 Edit - Undo undo 114 Edit - Ungroup ungroup 116 Edit Overview 114 Editing Parts 319 Editing Parts - Breaking the part boundary. 347 Editing Parts - Configuring Treatments 332. 339 Editing Parts - Copy and paste 349 Editing Parts - Corners 319 Editing Parts - Edit lines. 348 Editing Parts - Names Materials and Colours 344 Editing Parts - Notches 325 Editing Parts - Return to Shell. 350 Editing Parts - Text 330 Editing Parts - Treatments 321 exit 111 export 26 extend 248 File 20, 21, 25, 26, 28, 34, 59, 65, 72, 77, 84, 86, 87, 89, 90, 91, 92, 98, 99, 100, 101, 110, 111 overview 20 File - Close

close 25 File - Cut import 34

420

File - Digitize import 59

File - Digitize - Options import to MindCAD2D 77

File - Digitize - Parts import to MindCAD2D 65

File - Digitize - Select Source import to MindCAD2D 72

File - Digitize - Shell import to MindCAD2D 59 File - Exit

26

exit 111

File - Export export 26 File - Export - DGT

File - Export - DXF 27

File - Export - Image 26 File - Export - PDF 27 File - Import export 28 File - Import - DGT 30 File - Import - DXF 30 File - Import - HPGL 30 File - Import - MDB 32 File - Import - PDF 32 File - New new 20 File - Open open 21 File - Preferences preferences 84 File - Preferences - Customize customise 100, 101 File - Preferences - Default Labels customise 91 File - Preferences - Default Properties customise 99 File - Preferences - Digitizer customise 89 File - Preferences - Language customise 90 File - Preferences - Locations editing 86 File - Preferences - Options customise 87 File - Preferences - Parts directories 92 File - Preferences - Parts - Materials 93 File - Preferences - Parts - Names 94 File - Preferences - Printer misc 98 File - Print editing 110 File - Print Parts editing 110 print preview 110 File - Print Preview print preview 111 File - Printer Setup print setup 111 File - Save save 25

File - Save As

421

File - Save As save as 25 File Overview 20 Free measurements 225

- G -

Getting Help with MindCAD2D 16 Getting Started 12 group 116

- H ·

Help 416, 417 overview 416 Help - About MindCAD2D about 417 Help - Help Topics help topics 416 Help - Mind on the Web Delcam 416 Help Overview 416 416 help topics How do I manipulate the graphics? 16 How do I start MindCAD2D? 12 How do I use the menus? 12

- | -

import 34, 59 import to MindCAD2D 59, 65, 72, 77

- L -

layers 141 lines 141 141, 372, 373, 374, 375, 379, 380, 382, parts 389, 391, 394, 403, 404 punches 142 129 layers bar line 151 Line editing 154 Line editing - Add/Delete point 156 Line editing - Changing a Corner/Curve point 157 Line editing - Dragging/Scaling/Rotating lines 157 Line editing - Move point 155

lines 141 links on/off 232 list 413

main bar 129 Measurement along lines 226 menu constrain edit 117 create holes 368 drawing 148 114 edit edit-group 116 26.28 export 20 file help 416 import 34, 59 layers 141 141 lines mirror 247 operations 232 parts 286 146 selection show all 143 toolbars 117, 129 tools 146 view 126 window 412 Mind 416 mirror 247 about axis 248, 261 Moving (Panning) 16

- N -

new 20

- 0 -

offset 233 open 21 Operations 232, 233, 241, 247, 248, 251 overview 232 Operations - Advanced - Anchor 283 Operations - Advanced - Bisection 281 Operations - Links On/Off

Operations - Links On/Off links on/off 232 **Operations - Markers** extend 248 **Operations - Mirror** mirror 247 Operations - Mirror - About axis 248 Operations - Mirror - Activate Axis 247 **Operations - Offset** offset 233 **Operations - Perpendicular** perpendicular 241 **Operations - Perpendicular - Axis** 244 Operations - Perpendicular - Line 241 **Operations - Punches** split line 251 **Operations Overview** 232 overview 126, 146, 286, 412

- P -

141, 286, 372, 373, 374, 375, 379, 380, 382, parts 389, 391, 394, 403, 404 Parts - Add Cut 376 Parts - Add Cut - Add Cut on both Sides 382, 394 Parts - Add Cut - Add Cut only to Reflection 380, 391 Parts - Add Cut - Add Cut to One Side 379.389 Parts - Add Lines 371 Parts - Add Lines - Add Lines 372 Parts - Add Lines - Add Lines on both Sides 375 Parts - Add Lines - Add Lines only to Reflection 374 Parts - Add Lines - Add Lines to One Side 373 Parts - Create Hole 368 Parts - Create Part 286 Parts - Create Quality Area 370 Parts - Delete All Parts 406, 407 Parts - Delete Part 406 Parts - Insert Lines on Border 399 Parts - Remove - Lines 398 Parts - Replace Lines 401 Parts - Replace Lines - Replace Lines 402 Parts - Replace Lines - Replace Lines on Reflection 403 Parts - Replace Lines - Replace Lines/Reflection 404 130 parts bar

Parts Overview 286 paste 115, 116 perpendicular 241 preferences 84 customise 87, 89, 90, 91, 99, 100, 101 directories 92 editing 86 misc 98 print 110 print preview 110, 111 print setup 111 project info 144 punches 142

- R -

rectangle 166, 170, 178, 179, 180, 181, 182 Re-open 24

- S -

save 25 save as 25 sawtooth line 174 Scaling 16 select all 116 selection 146 show all 143 side by side 413 split line 251 Standard online Help 17 Status Bar Help 17

- T

Tips and tricks 316 Tool tips 16 toolbars 117, 129 tools 146 Tools - Change 187 Tools - Change - Bounding Box 206 Tools - Change - Convert 224 Tools - Change - Convert - to Axis 224 Tools - Change - Convert - to Curve 225 Tools - Change - Convert - to Sawtooth 224 Tools - Change - Cut Line 192

Index

Tools - Change - Explode 201 Tools - Change - Extend Line 199 Tools - Change - Hide Part of a Line 197 Tools - Change - Join Lines 203 Tools - Change - Reverse 199 Tools - Change - Rotate 187 189 Tools - Change - Scale Tools - Change - Smooth 202 Tools - Change - Swap Lines 205 Tools - Change - Wrap Lines 207 Tools - Drawing 148 Tools - Drawing - Arc 170 Tools - Drawing - Axis 178 Tools - Drawing - Circle 161 Tools - Drawing - Circle - By radius 162 Tools - Drawing - Circle - Free 161 Tools - Drawing - Continue line 186 Tools - Drawing - Line 151 Tools - Drawing - Marks 179 Tools - Drawing - Punches 180, 181, 182 Tools - Drawing - Rectangle 166 Tools - Drawing - Sawtooth 174 Tools - Drawing - Text 170 **Tools - Measurements** 225 Tools - Selection 146 146 Tools - Selection - Point selection **Tools Overview** 146 Treatments - Line Offset 341 Treatments - Sawtooth offset 343

- U -

undo 114, 115 ungroup 116 Using markers when measuring 227

view 126 View - Filters 143 View - Full Screen 144 View - Grid 143 143 View - Grid - Lines View - Grid - None 144 View - Grid - Points 144 View - Grid - Spacing 144 View - Layers 141 View - Layers - Lines 141 View - Layers - Markers 142 View - Layers - Parts 141 View - Layers - Punches 142 View - Toolbars 129 View - Toolbars - Constrain Bar 129 View - Toolbars - Layers Bar 129 View - Toolbars - Main Bar 129 View - Toolbars - Object Browser bar 130 View - Toolbars - Parts Bar 130 View - Toolbars - Parts/Library Bar 131 View - Toolbars - Tools Bar 130 View - Zoom to Fit 126 View Overview 126 130, 131 views bar

- W -

window 412 Window - Cascade 412 Window - List 413 Window - Side by Side 413 Window Overview 412

zoom to fit 126